

Remington Arms Co., Inc.
Product Service
Legal Case #:4296

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
187268	1/25/2010	1/26/2010	1/26/2010				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter		Paul	Bramble	3845 Berkley Dr.	Bensalem	PA	19020		H 215-245-8940 C 215-852-1417

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4015	Improper Maintenance		
S	Concern:1007	Fired on Safe Release	Unknown	
C	Fired on Safe release			

Customer reported in a letter - When gun is loaded & Safe is pushed forward the gun will fire. dmf

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/7MM REM MA	26039	E6398601	ER	10/22/1997
Date Purchased	Where Purchased	Accessories	Original Owner			
	DICK'S CLOTHING & SPORTING GOODS	TWO PIECE SCOPE BASE,BOTTOM HALF OF RINGS	U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per factory - repair @ n/c - goodwill gesture	Repair/Replacement Cost \$47.23	Repair/Replacement Date 2/1/2010				

2/1/10: Per Fred S. - Trigger & trigger pin are rusted. Trigger will not return properly. Will follow down, replace trigger assembly, check over, clean at n/c. Goodwill gesture. dmf

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/26/2010
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY

Cause	4015	Improper Maintenance	
Barrel	Description		24" 7MM REM MAG
	Date Code		ER
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.012
	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test	False		
Trigger	Condition	Slightly Worn; Functioning	TRIG AND PIN RUSTED WILL FOLLOW DOWN
	Pull	---Select---	6#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington	Description		TWO PIECE SCOPE BASE,BOTTOM HALF

Components		OF RINGS
------------	--	----------

4/29/96

2411
E210/97
6#
1012

when weapon is loaded and you push
safety forward the gun will fire. This
happened on two different occasions and almost
killed my partner the second time. I've
had confidence in Remington weapons but this
has is the second weapon I've sent back
and my confidence has really diminished.

Sincerely,

Paul Bramble
3845 Berkley dr.
Bensalem, Pa 19020

P.S I paid alot of money in
insurance and the weapon
I'd like to be compensated for
this

Home Phone 215-245-8940
Cell Phone 215-852-1417

Serial:
Number:

E6398601

Model: 700



RE00187268

TRIG. & TRIG. PIN RUSTED.

TRIG. will not return properly.

will FOLLOW DOWN. replace TPA,

check over, clean AT N/C.

GOOD-will GESTURE

230145