email@tacproshootingcenter.com

Remington Arms Co., Inc. Product Service Legal Case #:4319

Case Information

RE# **Date Opened Date Closed** Obsolete Pre Lit Lit Date Opened(PS) **Incident Date** 187732 1/28/2010 1/29/2010 1/29/2010

Customer Information

**First** Type **Business** Last Name Street City State Zip Age Contact Name

H 254-968-3112 35100 N St Hwy Tac Pro Shooting Tac Pro Reporter Mingus TX 76463 E Center Shootin 108

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PΙ

PD Cause:4038 Could Not Duplicate Concern Unknown  $\mathbf{S}$ 

fired when safety disengaged Concern: 1007 Fired on Safe Release

C

2/4/10 Per note with rifle, on 11/22/09, a round was chambered and the safety was engaged. Once the safety was disengaged the weapon fired without touching the trigger.cm

Firearm Information

Mfg. Model/Ga. SKU Serial Bbl. DOM Type 700/2506 REM 26031 E6360537 AR 3/25/1997 Remington CF/BA

Date Purchased Where Purchased Accessories **Original Owner** 

**GRICE WHOLESALE** SCOPE, RINGS, BASE, SLING, HARD CASE U

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Cash Cash Reim. Release of Claims Release Date Settlement Reimbursement Settlement Date APV Date APV

Per Ilion, replace TPA, clean at 1/2 normal charges as goodwill

> Repair/Replacement Repair/Replacement Cost

2/4/10 Per Ilion, could not duplicate concern. Trig set screws altered. Replace TPA, check over, clean at 1/2 normal charges.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date	]	1/29/2010
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4006	Altered Adjustments or Components	
Barrel	Description		24" 2506 REM
	Date Code		AR
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

1	<del>  </del>		1
		Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
D .	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		STANDARD M/700 SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.014
Sear	Notch	Like new; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Functioning	DIRTY
•	Pull	Select	3#
Trigger	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		SCOPE,RINGS,BASE,SLING,HARD CASE

Arms Ser Vices Repair & Estimate System  Add Repair Sestimate Repair Expedite Repair Trouiny Rep	spair Tools CSR Tools Reports Table Maintenance System Maintenance Help
Repair Inquiry	
Pepair Number   RE00187732	ter Fire: Cailber: Repairment Bruce Travis  7 Status: Approval-Hold 1/29/2010 8:27:57 AM
ddress Information Customer: Name: TAC PRO SHOOTING CENTER  Address I: 35100 N. ST. HWY 108  ddress 2  City MINGUS	Return To: C Received From  TAC PRO SHOOTING CENTER  85100 N. ST. HWY 108  PO Boxd  MINGUS
	ate: [TX Zip Code: ]76463 Country/US
Contact / Condition Problems Estimate	le History / Status Shipping / Billing  Durrent Status
Date	Deec2   Shipping Holds   Approval Hold
1/29/2010 8:37:C Expedite pencerl From Repair Bench	To: ApproveD  Theturn As Received Current Docation That been Approved Transfer Number  Transfer Number
Repair Search	Refresh Close

DECERVE L FEB 0 1 2010 D BY:

>	13/9		
Deira	47		
Print Reset			
Model Number: 700	E6360537	Serial Number: E6360537	
Are you the original owner?: ☐ YES	⊠ NO		
Name: Tac Pro Shooting Center	Date of Purchase	Date of Purchase:	
Address (no PO Boxes): 35100 N. St. HWY 108			
City: Mingus	State: TX	<b>Zip:</b> 76463	
Phone (Daytime): 254-968-3112	<b>Fax:</b> 254-968-5857		
E-mail Address:(if e-mail address is provided be sent) email@tacproshootingcenter.com		eceipt and shipment will	
E-mail Address:  Use I would like to receive future e-mail upon			
Please describe your problem and date	of occurrence:		
11-22-09			
-A round was chambered and the safety the safety was disengaged the weapon			
the trigger. could not dup		=	
Trig. set screw	syltered lept	rece	
TOA checken	inclean at 1/2	-	
populat cha	ryes.	i	
358 characters left	Quote		
Ammunition Information:			
Manufacturer:	Type:		
Other (i.e. bullet weight/type, shot size, po	owder):		
Handload Information:			
Powder Used:	Powder Weight:		
Case/Hull Used:	Primer Used:		
Bullet Type/Shot Size:	Reloader Used:	Reloader Used:	

Firearms Care (Cleaning and Lubrication):
Brand of cleaning solution used: Remington
How often do you clean the bore? (Months or Number of rounds)  Every month
How often do you clean the action? (Months or Number of rounds)  Every month
How often do you clean the trigger assembly? (Months or Number of rounds)
Brand of lubricant used: Remington
How often do you lubricate the bore? (Months or Number of rounds)  Every Month
How often do you lubricate the action? (Months or Number of rounds)  Every Month
How often do you lubricate the trigger assembly? (Months or Number of rounds)
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? > ☐ YES ☐ NO
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?) Never
What were the services performed?)
r Parcel Post to:

E6360537

Model:



ENT SHELLS IN YOUR FIREARM OR IN

THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.

:: Record the serial number of your firearm before sending it.

- :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably,
  - ship in a firearm box. (Note: Original boxes may not be returned.)
- :: Remove all accessories from your firearm to prevent loss or damage.
- :: Provide a return address on both the outside and inside the box. Shipments without a proper

return address will be refused.

- :: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for
- damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

- :: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)
- :: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.