Remington Arms Co., Inc. **Product Service** Legal Case #:2084

Case Information

RE# Obsolete **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit

139942 1/30/2008 1/31/2008 1/31/2008

**Customer Information** 

Type **Business** Contact First Name Last Name Street City State Zip Age H 573-564-8153 Reporter Rick Gotchger 24 Riley Lane Wellsville MO 63384 E gotseg@yahoo.com

Incident Information

Claims Codes **Medical Treatment Medical Status** Repair Est.

PΙ

PD Cause:4038 Could Not Duplicate Concern

Unknown

S fires on safe release

Concern:1007 Fired on Safe Release

 $\mathbf{C}$ 

2/1/08-correspondence from repair-cust inherited this rifle. It sometimes fires when the safety is released.lw

Firearm Information

Mfg.

Type

Model/Ga.

TWO PIECE SCOPE BASE

SKU

Serial Bbl. **DOM** 

6/1/1952

270734 PYY

721/270 WIN Remington CF/BA **Date Purchased** Where Purchased Accessories

**Original Owner** 

U

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/721/CF/BA

Settlement Release of Claims

Release Date

Reimbursement

Cash Settlement Reim. Date Cash Date APV APV

Replace TA under **SMP** 

Repair/Replacement Cost

Repair/Replacement Date


2/1/08-quote sent to replace TA under SMP.lw

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/31/2008
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4038	Could Not Duplicate Concern	]
Barrel	Description		24" 270 WIN
	Date Code		PYY
	Bore Plugged	False	
	Bulged	False	]
	Fired	False	]
	Fired while Obstructed		

	Muzzle/Crown Condition	Worn; Functioning	٦
	Firing Pin	Slightly Worn; Functioning	1
	Shroud	Slightly Worn; Functioning	<u>]</u>
Bolt	Face	Worn; Functioning	1
Boil	Handle	Slightly Worn; Functioning	<u>]</u>
	Stop	Slightly Worn; Functioning	STICKY/SLUGGISH
	Condition	Slightly Worn; Functioning	STICK 1/SLUGGISH
Extractor		<u> </u>	1
Extractor	Cut Condition	Slightly Worn; Functioning	<u> </u> 
	Ext/Eject Test	False	]
L	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Worn; Functioning	]
Overall	Stock Condition	Worn; Functioning	
	Fore End Condition	Select	]
Receiver	Condition	Worn; Functioning	
Receiver	Bulged	False	
C - for-	Description		STANDARD M/721 BOLT LOCK SAFETY
Safety	Function	Slightly Worn; Functioning	
	Lift	Select	.014
	Notch	Slightly Worn; Functioning	O/S DOUBLE SEAR
	<b>x</b>	Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Functioning	TRIG ASSM VERY DIRTY
Trican	Pull	Select	3#
Trigger	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	Other Remington	
Non-Remington Components	Description		TWO PIECE SCOPE BASE

Arms Services Repair & Estimate System	
File Add Répair Estimate Repair Expedite Répair Inquiry Répair Tools CSR Tools Reports Table Maintenance versem Maintenance Help  Repair Inquiry	
Repair Number RE00139942 Sérial: 270734 Model 72): Center Fire: Caliber Repairman: Chuck Dekanek  Verify Repair  Address Information Customer: Received From Return Lo: Received From Re	Hippone
Name: RICK GOTCHER RICK GOTCHER	
Address 1: 24 RILEY LANE         24 RILEY LANE           Address 2: P0 Box:         P0 Box:           City: WELLSVILLE         WELLSVILLE	
State: MO Zip Code: 63384 Country: US State: MO Zip Code: 63384 Country: US	
Contact / Condition Problems E stimate History / Status Shipping / Billing  Date Code UserID Desc1 Shipping Hold ApprovalHold ApprovalH	The second secon
Repair <u>Search</u> <u>C</u> lose	A Salabana
	The second of the second
supple   1/31/2008   8.01 AM   CAPS   NUM   INS   SCRE   STAIN   NORMON   GRAIN Services   Williams Care   December   Parks and No.   Parks	worsen (Jeole Casomi



2017

Rick Gotchen
24 Roley Lawe
Wellsville, Mo 63384
573-564-8153
gots860 yphoo.Co.

P14 0/52

My wife and I inheretal than
My wife and I june inheretal than
Remine ton Model 721, sexial #270734

Remine ton Model 721, sexial #270734

upon her Sathers cheath. The problem

with this fixenew is that he fimes
it will discharge when the saftey
is rekensed. Thanks you your help.

is rekensed. Thanks you your help.
It understand that there is a saftey
recall ow this Model firenam.

Sincenely Solito

270734

Model:

**72**1



RE00139942

raig. Set schews Altered raig. /Act. very dirty. replace TPA, eleckovery lear under BOCT LOCK PROGRAM for \$ 20.00 + SX+H

## Remington. Factory Repair Instructions

(NOTE: Please print and complete this fo	rm, and then include it with your firearm.)					
Model Number: 721	Serial Number: 276734					
Are you the original owner?: YES NO						
Name: Rick Gotcher	Date of Purchase: + A live 1+64					
Address (no PO Boxes):	,					
21 Rilay / 1112						
City: /, ) & // & ( , // &	State: 1116   Zip: 63304					
Phone (Daytime): 573-564-8153	Fax:					
E-mail Address: 4 PAOC CODI  I would like to receive ruture e-mail upuate from Remington.						
Please describe your problem:						
dischange when the saftey is Released.						
Ammunition Information: Mul /4 p/-						
Manufacturer:	Type:					
Other (i.e. bullet weight/type, shot size, powder):						
Handload Information: Done						
Powder Used:	Powder Weight:					
Case/Hull Used:	Primer Used:					
Bullet Type/Shot Size:	Reloader Used:					
Firearms Care (Cleaning and Lubrication):						
Brand of cleaning solution used: $\phi_{\mathcal{L}_1} \leftarrow \omega_{\mathcal{L}_2}$						
How often do you clean the bore? (Months or Number of rounds)						
How often do you clean the action? (Months or Number of rounds) A LYCK PACK USC						
How often do you clean the action? (Months or Number of						
How often do you clean the action? (Months or Number of How often do you clean the trigger assembly? (Months o	of rounds) A LYCK ARCH 48C					
	of rounds) A LYCK ARCH 48C					

How often do you lubricate the bore? (Months or Number of rounds)

How often do you lubricate the action? (Months or Number of rounds)

How often do you lubricate the trigger assembly? (Months or Number of rounds)

Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual?

YES NO

Comments: Bleen bleen in the control of the control o

Ship your INSURED firearm by either UPS or Parcel Post to:

## REMINGTON ARMS CO., INC

ATTN: Arms Service Divison 14 Hoefler Ave Ilion, NY 13357

WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.

- :: Record the serial number of your firearm before sending it.
- :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.)
- :: Remove all accessories from your firearm to prevent loss or damage.
- :: Provide a return address on both the outside and inside the box. Shipments without a proper return address will be refused.
- :: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

- :: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)
- :: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card.