Remington Arms Co., Inc. Product Service Legal Case #:5440

000	Inforn	antion
	пиол	ашоп

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete 217819 1/6/2011 12/15/2010 1/7/2011

Customer Information

Business First Name Last Name Street City Type State Zip Contact Age 2130 Montmorenci Rd Incident Leroy Benson Ridgeway PA 15853 H 814-772-3041

Incident Information

Claims Codes Repair Est. **Medical Treatment Medical Status**

ΡI

PD Cause: 4038 Could Not Duplicate Concern

Unknown Concern:1007 Fired on Safe Release Fired on safety release

12/15/10 Per call from Benson, he has had this rifle for a long time but it just recently started firing when the safety was released.cm

Firearm Information

Model/Ga. SKU Mfg. Serial Bbl. DOM Type Remington CF/BA 700/243 WIN B6484919 DD 9/1/1983 n/a

Date Purchased Where Purchased **Original Owner** Accessories U

GRICE WHLSE CLEARFIELD PA TWO PIECE BASE

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Cash Reim. Date Cash Date Settlement Release of Claims Release Date Reimbursement Settlement APV APV

Per Ilion, replace TPA, clean, test fire at 1/2 normal cost

> Repair/Replacement Repair/Replacement

12/15/10 Mailing ARS.cm 1/17/11 Per Ilion, could not duplicate concern. Trigger assm set screws altered. Replace TPA, clean and test fire at 1/2 normal cost.cm 1/20 Tried to pall Bence, no answer, no machine ma

Examination[Remington/CF/BA]

Part Sub-Part Code Comment Examiner **B.TRAVIS** Exam Date 1/7/2011 Examination Product Type RF Action Type Assigned To T.NAGLE 4038 Could Not Duplicate Concern Cause Description 22" 243 WIN Date Code DD Bore Plugged False False Barrel Bulged Fired False Fired while Obstructed Muzzle/Crown Condition Slightly Worn; Functioning Firing Pin Slightly Worn; Functioning

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=5440&Type=Case

1/17/2011

124 Tried to call him no answer

l .	l market		
-	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		M/700 SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.009
Sear	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	Select	5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

22''

December 15, 2010

Leroy P. Benson 2130 Montmorenci Rd Ridgeway, PA 15853

Subject: #5440, Model 700


Dear Mr. Benson,

Thank you for your patience. Enclosed is a UPS ground prepaid shipping label to cover shipment of the firearm for inspection at our factory. Please include a copy of this letter with the firearm. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Please mark the ends of the box with "Product Service".

I apologize for the inconvenience that this incident has caused and I hope that these actions will keep you a loyal Remington customer.

Sincerely,

Christy Mitchell Consumer Affairs Administrator Phone: 800-243-9700, ext 8684 christy.mitchell@remington.com





tould not duplicate concern to A. SetSCIUWS Altered Replace TPA, cleand Testfire At 1/2 Normal cost. Quote

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025

Phone 800-243-9700 • www.remington.com

247

NOTE: Please complete and print this form, and then include it with your firearm.

Model Number: 700 Classic	Serial Number: B6484919
Are you the original owner?: YES NO	
Name: Leroy Benson & P	Date of Purchase: BACK IN 80°
Address (no PO Boxes): A130 MonTr	MOMERCI RD
city: Ridguay	State: PA. Zip: 15853
Phone (Daytime): 814-77-83041	Fax: NONE
E-mail Address:(if e-mail address is provided, notification sent)	of receipt and shipment will be
E-mail Address:	
I would like to receive future e-mail updates from Rei	mington.
Please describe your problem and date of occurrence	:
When you TAKE OFF IT did it twice To	<u> </u>
It did it Once To	My Boy
500 characters left	
Ammunition Information:	
Manufacturer: Relonds only	Type:
Other (i.e. bullet weight/type, shot size, powder):	
Handload Information:	
Powder Used: 4350	Powder Weight: 40-5
Case/Hull Used: RemingTon	Primer Used: Rem 95
Bullet Type/Shot Size: 100 gR Spitzer	Reloader Used:

Firearms Care (Cleaning and Lubrication):
Brand of cleaning solution used: Otters
How often do you clean the bore? (Months or Number of rounds) RFTer Every Use
How often do you clean the action? (Months or Number of rounds)
How aften do you clean the trigger assembly? (Months or Number of rounds)
Brand of lubricant used: Hoppe,5
How often do you lubricate the bore? (Months or Number of rounds) AFTEN EVENY USE
How often do you lubricate the action? (Months or Number of rounds)
How often do you lubricate the trigger assembly? (Months or Number of rounds) 12 NONThs
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual?
YES (NO) No Computer
When was the last time that your firearm was serviced by a Remington authorized
repairmen/gunsmith?) Never 5:Nce New
What were the services performed?)
Remington Arms Co., Inc.
Attn: Arms Service Division
14 Hoefler Avenue
Ilion, NY 13357
@WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.
:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably.
ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage.
:: Provide a return address on both the outside and inside the box. Shipments without a proper return address will be refused.

*****Internal Use Only****

700 Log Sheet – 2010 CNBC Story

Date: 12/15/10 CSR: M
Is the customer calling as a result of the broadcast? YES NO
Initial tone/Attitude of the caller:
Angry at Remington Supportive of Remington
Angry at CNBC for airing Supportive of CNBC
Nature/Purpose of Call:
Calling to offer support (pro-Remington)
Inquisitive about Remington position
Calling to provide broadcast feedback
Customer Owns a Model 700:
General concern of safety with personal model 700
seeking company feedback regarding direction/use of personal Model 700
claims they experienced a "safety" related issue with their personal Model 700
has not experienced a problem but wants firearm inspected (fill out address) send to an RARC
If the customer references any concerns or problems experienced in relation to the operation of the safety of the firearm, they should be advised to return it to (Product Service, Ilion NY).
Did they agree to return it to the factory? (YES) NO had it long time Consumer Name: Lerry P. Benson 760 (243) just started
Consumer Name: Lerry P. Benson 700 (243) just started
Address: 2130 Montmorenci Rd Couple yes ago
Ridgeway PA 15853
Phone: 814-772-3641
Serial #:
Send an ARS label
Comments:

Confidential

Remington

10/19/10

5440



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE: 1	12/15/2010 REQUESTED BY:	christy
QUANTITY:	1 WEIGHT PER PACKAGE:	10
Brievae Check One		
MEDIA		xx
COORDINATOR		
TO MAIL	I WILL MAIL	
DESCRIPTION:		
	700	
		·

LABEL INFORMATION

MAIL LABEL TO:	Leroy P. Benson 2130 Montmorenci Rd Ridgeway, PA 15853	tmorenci Rd	
	·	,	
RETURN ITEM TO:	Rem Prod Service		

PLEASE COMPLETE ALL PARTIS OF THIS FORM AND SEND TO THE MEDIA COORDINATION

```
AXX596 DEC 15, 2010 ALL CURR USD 1 OF 1
SVC GNDCOM ACT UT 10.0 LBS
TRACKING# 124XX5969066911609
REF 1:LEROY BENSON/CD/CM
REF 2:700

HANDLING CHARGE 0.00
SINGLE-PIECE PUB RATE CHRGS: SVC T/P USD
DV 0.00 COD 0.00 RS 0.50
DC 0.00 DGD 0.00 SD 0.00
AH 0.00 PR 0.00 SP 0.00
TOT PUB CHG 7.42 PUB+HANDLING 7.42
```



