Remington Arms Co., Inc. **Product Service** Legal Case #:5346

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete

12/8/2010 1/20/2011 218490 1/11/2011

Customer Information

Street **Business** First Name Last Name City Zip Type State Age Contact

Gary 1 Jones Park #3 Incident Jones Kirby AR 71950 H 870-398-4868

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

ΡI

PD shot window of truck

Cause:4012 Improper Headspace

Fired when bolt

Concern:1008 Fired on Bolt Closing

Unknown

closed

C

12/8/10 Per call from Jones, he has a 700 that was passed to him from his grandfather. It has fired when closing the bolt on 2 occassions. The first time he shot out the window of his truck. He was not asking for us to reimburse for that. He said it happened again last year, fired on bolt closing, no damages. He has not used it since. He just wants it safe. It has sentimental value.cm

Firearm Information

Mfg.

Type

Model/Ga.

SKU

Serial

Bbl. DOM

Remington **Date Purchased** 

CF/BA Where Purchased 700/3006 SPR Accessories

n/a **Original Owner**  231032 BM 1/1/1965

SCOPE, RINGS, BASE

N

CONCERN:FBC

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date

Reim bursement

Reim. Cash Date Settlement

Cash Date

APV

Repair rifle no charge as gesture of

goodwill

Repair/Replacement

Repair/Replacement Cost

65.90

Date 1/24/2011

12/8/10 Mailing ARS.cm 12/13/10 Needs a box, ord #1167771.cm 1/20/11 Repair rifle no charge as a gesture of goodwill. Mailing 700 owner's manual with the cleaning bolt, action and trigger pages flagged and highlighted due to the condition of his rifle.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Соттепт
	Examiner		B.TRAVIS
	Exam Date		1/12/2011

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=5346&Type=Case

1/24/2011

,	<b> </b>	4	1 450 2 01
	Product Type		RF
Examination	Action Type		A
	Assigned To		T.NAGLE
Cause	4012	Improper Headspace	]
	Description	]	22" 3006 SPR
	Date Code	]	ВМ
	Bore Plugged	False	
	Bulged	False	
Barrel	Fired	False	<u> </u>
	Fired while Obstructed		
	Muzzle/Crown Condition	Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	DIRTY,SLUGGISH
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	DIRTY,SLUGGISH
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	<u></u>
	Block Condition	Select	<u> </u> =
Locking	Lug Condition	Slightly Worn; Functioning	=
	Notch Condition	Select	
Overall	Exterior Condition	Worn; Not Functioning	ACTION VERY DIRTY, HAS A LOT OF FOREIGN BEBRIS
o voium	Stock Condition	Worn; Functioning	<u> </u>
·-·	Fore End Condition	ļ	
Receiver	Condition	Worn; Functioning	
	Bulged	False	
	Description	] 	M/700 BOLT LOCK SAFETY
Safety	Function	Slightly Worn; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	N/A
Sear	Notch	Select	O/S DOUBLE,SLUGGISH
- · · · ·	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	VERY DIRTY,STICKY,PARTS WORK SLUGGISH.WILL FOLLOW DOWN
	Pull	Select	4#

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=5346&Type=Case

1/24/2011

PrintDisplay				Page 3 of 3
1	Altered	False		
	Sub-Assembly	M/700 Bolt Lock		!
Non-Remington	Description		SCOPE DINGS BASE	

Components

## Remington.



3myt

5396

December 8, 2010

Gary Jones 1 Jones Park #3 Kirby, AR 71950

Subject: #5346, Model 700

Dear Mr. Jones,

Enclosed is the UPS ground prepaid shipping label for shipment of the firearm for inspection at our factory. Please include a copy of this letter with the firearm. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Please mark the ends of the box with "Product Service".

I apologize for the inconvenience that this incident has caused and I hope that these actions will keep you a loyal Remington customer.

Sincerely,

Christy Mitchell Consumer Affairs Administrator Phone: 800-243-9700, ext 8684 christy.mitchell@remington.com

enclosure

231032 Model: 700



27 17.50 1.-26.40 M JAN 1 3 2011

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com NOTE: Please complete and print this form, and then include it with your firearm.

	Model Number: TOO	Serial Number: 23/03 A	
	Are you the original owner?: TYES NO (	orandfather owned it gave it to me	2,
	Name: Gary Joves -	Date of Purchase: T I do not Know	
		Park #3	
·	City: KIV by	State: Ar Zip: 71950	
	Phone (Daytime): <b>87</b> 0) 398-4868	Fax:	
!	E-mail Address:(if e-mail address is provided, notification	of receipt and shipment will be	
	sent)		
	I would like to receive future e-mail updates from Rem	nington.	
	Please describe your problem and date of occurrence:		
pprox.	Check if bullet was	in chambers and it	
IN Deci		9	
£ 2008 /	truck, and done it	the next year	
	but was checking it	before going to it this year. My the internet that they	
	Stand alunt use i	up internet that they	
	had problems with certa	in trigger in 700 models.	
	11		<b>L</b>
	Ammunition Information:	fix call + tell me how much	rost
	Manufacturer: Remin aton	Type: Express Core-LOKT	me.k
		O.Gl.	
	7		
	Handload Information:		
	Powder Used:	Powder Weight:	
	Case/Hull Used:	Primer Used:	
	Bullet Type/Shot Size:	Reloader Used:	

Firearms Care (Cleaning and Lubrication):	
Brand of cleaning solution used: Remin glon	
How often do you clean the bore? (Months or Number of rounds) Fvery year I used it.	
How often do you clean the action? (Months or Number of rounds) Every 3 months and several three	o inDoer Ceasi
How often do you clean the trigger assembly? (Months or Number of rounds) Once Ayear while Using	•
Brand of lubricant used: Remington	
How often do you lubricate the bore? (Months or Number of rounds) DNCe Ayear while I used,	
How often do you lubricate the action? (Months or Number of rounds) French 3 months, Every week	luning Deer seas
How often do you lubricate the trigger assembly? (Months or Number of rounds) SICP A YEAR.	
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual?	
YES TO NO DON'T have owners manual	
When was the last time that your firearm was serviced by a Remington authorized	
repairman/gunsmith?)	
What were the services performed?)	
Remington Arms Co., Inc.	
Attn: Arms Service Division 14 Hoefler Avenue	
Ilion, NY 13357	
r' ·	
♠WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.	
:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.)	
:: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper return address will be refused.	



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

## ARS LABEL REQUEST FORM

DATE:	12/8/2010 REQUESTED BY:	christy	
QUANTITY:	1 WEIGHT PER PACKAG	GE:	10
RLEASE GHEOKONES MEDIA			
COORDINATOR		xx	
TO MAIL	I WILL MAIL		
DESCRIPTION:			
	700		

## LABEL INFORMATION

MAIL LABEL TO:	Gary Jones I Jones Park #3 Kirby, AR 71950
RETURN ITEM TO:	Rem Prod Service

## PLEASE COMPLETE ALLEPARTIS OF THIS FORM AND SEND TO THE MEDIA COORDINATOR

```
4XX596 DEC 9, 2010 ALL CURR USD 1 OF 1
SVC GNDCOM ACT WT 10.0 LBS
TRACKING# 124XX5969067557509
REF 1:GARY JONES/CD/CN
REF 2:700

HANDLING CHARGE 0.00
SINGLE-PIECE PUB RATE CHRGS: SVC T/P USD
DV 0.00 COD 0.00 RS 0.50
DV 0.00 DGD 0.00 SD 0.00
AH 0.00 PR 0.00 SP 0.00
TOT PUB CHG 9.45 PUB+HANDLING 9.45
```







