Remington Arms Co., Inc. Product Service Legal Case #:4850

Case 1	Intorn	nation

Date Opened Date Opened(PS) **Date Closed Incident Date** RE# Pre Lit Obsolete Lit 10/26/2010 11/19/2010 210788 11/18/2010

Customer Information

Last Name **Business** First Name Street City Type State Zip Age Contact 51 Highline Rd Incident Lou Kern NM C 575-447-2969 Maxwell 87728

Incident Information

Repair Est. Claims Codes Medical Treatment Medical Status

ΡI

FSR

PD Could Not Duplicate Concern Cause:4038

Unknown

S C

10/26/10 Per email from Eric Aliff sent on 10/25 at 5:10pm, Kern called and stated his 700 fired on safety release.cm

Firearm Information

Mfg. Model/Ga. SKU Serial Bbl. DOM Type CF/BA 700/264 WIN MA 29715 S6407152 KV 5/29/2001 8:16:31 AM Remington

Where Purchased **Date Purchased** Accessories

Concern:1007 Fired on Safe Release

Original Owner

ACUSPORT (OH) CORPORATION TWO PIECE SCOPE BASE 10/1/2010 U

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Cash Cash Reim. Release of Claims Settlement Release Date Reimbursement Date Settlement Date APV APV

Per Ilion, replace TPA, clean at 1/2 normal charges

Repair/Replacement Cost Repair/Replacement Date

10/26/10 Left voice message that I would mail a prepaid shipping label to him.cm 11/22/10 Per Ilion, could not duplicate concern. Trigger set screws altered. Trigger has min trigger return. Replace TPA, clean and test fire at 1/2 normal charges. Emailed inspect and quote info. Awaiting reply cm 12/9/10 Rec'd email from Kern that she approves and is mailing a check for the repair.cm


Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		11/19/2010
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		26" 264 WIN MAG
	Date Code		KV
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=4850&Type=Case

12/9/2010

	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Dogoiyon	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description	<u> </u>	STANDARD M/700 SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	ISS	
	Lift	Select	.016
Sear No	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	1 6212	False	
	Condition	Slightly Worn; Functioning	MIN TRIGGER RETURN
Frigger	Pull	Select	2#
1118801	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		TWO PIECE SCOPE BASE



quote \$ 79.28

PECELVE Nov 2 2 2010 By: 4850

26" 24 KV50 1016

October 26, 2010

Lou Kern 51 Highline Rd. Maxwell, NM 87728

Subject: #4850, Model 700

Dear Mr. Kern.

Regarding your contacting with Remington and the incident you incurred, enclosed is a prepaid UPS ground shipping label for shipment of the firearm to our factory. Please include a copy of the attached letter with the firearm. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Please mark the ends of the box with "Supry".

I apologize for the inconvenience that this incident has caused and I hope that these actions will keep you as a loyal Remington customer.

Sincerely,

Christy Mitchell Consumer Affairs Administrator Phone: 800-243-9700, ext 8684 christy.mitchell@remington.com

S6407152 Model: 700 RE00210788 could not duplicate concern.
Thig. Set screws ALTERED. Thig.
HAS MIN trip, HETHER HIPHER
TPA, clean & rest Rize AT
1/2 Noismal changes,
Quale

Remington Arms Company, Inc. ● 870 Remington Drive ● P.O. Box 700 ● Madison, NC 27025

Phone 800-243-9700 ● www.remington.com

NOTE: Please complete and print this form, and then include it with your firearm.

Model Number: 700	Serial Number: 56 407/52	
Are you the original owner?: YES NO	,	
Name: MARY LOU KEIZN &	Date of Purchase: Dct 2010	
Address (no PO Boxes): 51 HIGHUNE RD		
City: WAY WELL	State: NM Zip: 87728	
Phone (Daytime): 575-447-2969	Fax: 1-575-375-2969	
E-mail Address: (if e-mail address is provided, notification of receipt and shipment will be sent) Lkeev Chacavalley, Lom		
E-mail Address: I would like to receive future e-mail updates from Remington.		
Please describe your problem and date of occurrence		
THE RIFIE BISS FIRES when -	taken of Safety.	
500 characters left		
Ammunition Information:		
Manufacturer: Wincits STER	Туре:	
Other (i.e. bullet weight/type, shot size, powder): 115. Gr. /120		
Handload Information:		
Powder Used:	Powder Weight:	
Case/Hull Used:	Primer Used:	
Bullet Type/Shot Size:	Reloader Used:	

Firearms Care (Cleaning and Lubrication):
Brand of cleaning solution used: Hoppes
How often do you clean the bore? (Months or Number of rounds) 20 Rounds or less
How often do you clean the action? (Months or Number of rounds)
How often do you clean the trigger assembly? (Months or Number of rounds)
Brand of lubricant used: ReminGToH
How often do you lubricate the bore? (Months or Number of rounds) Zo Rounds or less
How often do you lubricate the action? (Months or Number of rounds) As needed
How often do you lubricate the trigger assembly? (Months or Number of rounds)
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? YES NO
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?) Never les Been
What were the services performed?)
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357
●WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.
:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper return address will be refused.

Mitchell, Christy

From:

Aliff, William

Sent: To: Monday, October 25, 2010 5:10 PM Mitchell, Christy; Fulcher, Dell Marie

Subject:

700

Model 700 firing with safety release.

Says it is a new gun (new purchase). Was built in 2001.

SN: S6407152

Lou Kern 51 Highline Road Maxwell, NM 87728

575-447-2969



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:	10/26/201	REQUESTED BY:	christy
QUANTITY:		WEIGHT PER PACKAGE:	10
PTEASE CHECKIONES MEDIA COORDINATOR TO MAIL		I WILL MAIL	xxxx
· ·	Model 700 S6407152		•

LABEL INFORMATION

MAIL LABEL TO:	Lou Kern 51 Highline Rd. Maxwell, NM 87728
RETURN ITEM TO	: Rem Product Service

REMANSE COMPRESE ALLEPARTIS OF THIS FORM AND SEND TO THE MEDIA COORDINATION



