А ,

			I	Remington Arms Co.,	Inc.				
				Product Service		•			
				Legal Case #:5434					
Case Informati				_					
RE# 216687	Date Op 12/29/2		Date Opened(PS) 12/15/2010	Date Closed 1/17/2011	i Inci	dent Date	Pre	Lit Lit	Obsolete
Customer Info	rmation								
Туре В	Business	First Name	Last Name	Street	City	State	Zip Ag		Contact
Incident		Kenneth	Richardson	3131 Hwy 100	Centerville	TN	37033	C 6	31-670-6490 15-294-4019 zzle1@att.net
Incident Inform	nation						-		Ŭ
Clai	ims		Code	s	Repair E	st. Mee	dical Treat	ment l	Medical Status
PI									
PD Shot hol	le in ceiling	g Cause	:4038 Could No	t Duplicate Concern			Unknown		
S		Conce	ern:1008 Fired on E	Bolt Closing			Charlown		
C FBC									
Customer calle	ed in. He st	ated that about	t 2 weeks ago he ha	d a FBC with a used g	un he bought	& shot a h	iole in his c	aling. No	injury. df
Firearm Inform	nation								
Mfg.			Туре	Model/Ga.		SKU	Sei	ial Bb	I. DOM
Remingt	on		CF/BA	700/3006 SPI	RG	n/a	249	299 RN	11/1/1966
Date Purch	nased	When	re Purchased	Accessories	s Ori	ginal Own	ег		
3/19/200	09	PROUDFI	T OGDEN UTAH			N			
CONCERN:FE	BC		·						
Ammunition Ir	oformation	- None Define	ed						
Other Products									
Settlement									
				Remington/700/CF/B	BA				
Settleme	nt	Release of C	Claims	Release Date	Reimburse	ment	Cash Settlement	Reim. AP	
Repair @ n goodwill ges									
	R	epair/Replace \$97.40	-	r/Replacement Date 1/17/2011					
trigger is dirty	& sticky. I	will offer to r	emove bolt lock, re	4. df 1/13/11: Per Ilion place TA, clean & test called back & apprvd	t fire at n/c - g	esture of g	goodwill. df		
Examination[R	Remington/	CF/BA]							

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/4/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 3006 SPR
	Date Code		RN
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	1		

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=5434&Type=Case

1/17/2011

1

	Muzzle/Crown Condition	Slightly Worn; Functioning]
	Firing Pin	Slightly Worn; Functioning	
Bolt	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Like new; Functioning	BINDS, SLUGGISH
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Ketter	Bulged	False	
	Description		M/700 BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.009
Sear	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY,STICKY
	Pull	Select	3.5#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	

1/17/2011



COPY

December 15, 2010

Kenneth Richardson 3131 Hwy 100 Centerville, TN 37033 Ph: 931-670-6490

Ref: # 5434

Dear Mr. Richardson,

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination.

Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results.

I hope that this action will keep you a loyal Remington customer.

Sincerely, D. Fulcher Consumer Affairs Administrator Remington, H&R, Marlin Phone: 1-800-243-9700 Fax: 336-548-7872

5 2011 BY:

enclosure



Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

-**7**0°'4

ň.

.

•

CS 12-2910	1 ago 1			
Print	Reset			
Model SPRINGFIELD Number: 700 REMINGTON	Serial Number: 249299			
Are you the original ov	vner?: 🗆 YES 🛛 NO			
Name: KENNETH E.Richardson	Date of Purchase: 3-19-09			
Address (no PO Boxes): 3131 Hwy, 100				
City: CENTERVILLE	State: TN Zip: 37033			
Phone (Daytime): 931-670-6490	CELL] Fax: 615-294-4019			
E-mail Address:(if e-mail address is provi be sent)	ded, notification of receipt and shipment will			
E-mail /	Address: e-mail updates from Remington.			
Please describe your problem and date of occurrence: I LOADED THREE ROUNDS IN THE RIFLE TO INSULE THOT IT WORKED CORRECTLY. I NOTICED TO UNLOAD IT-I HAD TO LEAVE THE SOFETY OFF- THE RIFLE FIRED WHEN I PUSHED THE BOLT FORWARD. TO MY EMBERRESMEN IT PUT D HOLE INICEILING & ROOF. MY WIFE IS STILL AFROID OF THE RIFLE				
Ammunition	Information:			
Manufacturer: REMINGTON	Туре: 30-06			
Other (i.e. bullet we powder): 150 Grai	eight/type, shot size,			
Handload I	nformation:			
Powder Used:	Powder Weight:			
Case/Hull Used:	Primer Used:			
Bullet Type/Shot Size:	Reloader Used:			
Firearms Care (Clear	ning and Lubrication):			

http://www.remington.com/asp/factory_repair_form.asp

12/13/2010

i

1	PPES
How often do you clean the bore rounds) <i>み</i> 上てを介	? (Months or Number of
How often do you clean the action rounds) <u>のれい</u> ティアを	1? (Months or Number of DONE ROUND SENCE OWNED.
How often do you clean the trigger ass rounds) <u>う</u> そく	embly? (Months or Number of Jborc
Brand of lubricant used: Hoffes	
How often do you lubricate the bo rounds) aFTER	
How often do you lubricate the acti rounds)	
How often do you lubricate the trigger as rounds)	sembly? (Months or Number of
Have you reviewed the cleaning and maintenan in our owners manual? >	
When was the last time that your firearm was repairman/gunsmith?) しゃく	serviced by a Remington authorized
What were the s performed?)	ervices
Ship your INSURED firearm by eith	per IPS or Parcel Post to:
Remington Art Attn: Arms Sen 14 Hoefler Ilion, NY	ns Co., Inc. vice Division Avenue
Attn: Arms Sen 14 Hoefler	ns Co., Inc. vice Division Avenue 13357 I SHELLS IN YOUR FIREARM OR IN A VIOLATION OF FEDERAL LAW. IF ELLS PLEASE SEND THEM IN A ME, ADDRESS (WITH ZIP CODE),

12/13/2010

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for

damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.



www.remington.com

a si s

\$

Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:		12/15/2010	REQUESTED BY:	Dell
QUANTITY:	1	· · · · · · · · · · · · · · · · · · ·	WEIGHT PER PKG:	10 lbs
REASECHECKIONE MEDIA COORDINATOR TO MAIL			I WILL MAIL	XXXXXX
DESCRIPTION:	Ref # 5434 rifle			

LABEL INFORMATION

MAIL LABEL TO: Kenneth Richardson 3131 Hwy 100 Centerville, TN 37033 Ph: 931-670-6490

RETURN ITEM TC Remington Arms Attn: Product Service Ilion, NY

PLEASE COMPLETE ALL PARTS OF THIS FORM AND SEND TO THE MEDIA COORDINATION

 4XX595
 DEC 15, 2010
 ALL CURR USD
 1 OF 1

 SVC GNDCOM
 ACT WT 10.0 LBS
 1 OF 1

 TRACKING# 1Z4XX5969067739554
 REF 1:KENNETH RICHARDSON/CD/DMF

 REF 1:KENNETH RICHARDSON/CD/DMF

 REF 2:5434/RIFLE

 HANDLING CHARGE 0.00

 SINCLE-PIECE PUB RATE CHRGS:
 SVC T/P USD

 DV 0.00
 COD 0.00
 RS 0.50

 DV 0.00
 DGD 0.00
 SD 0.00

 AH 0.00
 PR 0.00
 SD 0.00

 TOT PUB CHG 8.74
 PUB+HANDLING 8.74







