DOM

Remington Arms Co., Inc. **Product Service** Legal Case #:5256

$\sim$		. •
( 'ace	Intor	mation
Case	LIMOL	manon

Pre Lit Date Opened(PS) **Date Closed** Incident Date Obsolete RE# **Date Opened** Lit 215764 12/21/2010 12/1/2010 1/5/2011

Customer Information

Business First Name Last Name Street City State Zip Age Contact Type C 205-617-3189 656 County Rd 28 Double Spring Incident Dannon Wright 35553 E dannonwright@yahoo.com

Incident Information

**Medical Status** Codes Repair Est. Medical Treatment Claims

PΙ

S

Cause:4038 Could Not Duplicate Concern PD

Concern:1008 Fired on Bolt Closing

Unknown

C FBC

12/1/10: Customer called in. He stated that he had a FBC a few months ago with the rifle. No damage, No injury. He stated that the bolt is really hard to close on a shell. Bought it new from Dicks Sptg Gds. df

Firearm Information

Model/Ga. SKU Type Serial Bbl. Mfg. 700/22-250 REM 85434 CF/BA G6874601 OD 7/6/2009 10:54:54 AM Remington **Date Purchased** Where Purchased Accessories Original Owner

DICK S SPORTING GOODS/ATL TWO PIECE BASE Y

CONCERN:FBC

Ammunition Information - None Defined Other Products Information - None Defined Settlement

#### Remington/700/CF/BA

Cash Cash Reim. Settlement Release of Claims Release Date Reimbursement Date Settlement Date APV APV

Per Ilion - Check over, clean, test fire @ n/c - warranty

Repair/Replacement Repair/Replacement Date Cost 1/17/2011 \$42

12/1/10: Sending ARS, ltr, form. df 12/28/10: Cust. called for status but factory is closed for holidays. df 1/17/11: Per Ilion - Could not duplicate concern. TA functions as designed. Assem. is dirty. Check over completely, clean & test fire @ n/c - warranty. df

### Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/5/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		26" 22-250 REM HB
	Date Code		OD
	Bore Plugged	False	
	Bulged	False	
	Fired	False	

	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
Bolt	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		XMP SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	Select	.010
	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Like new; Functioning	DIRTY
	Pull	Select	3.5#
	Altered	False	
	Sub-Assembly	X-Mark Pro	
Non-Remington Components	Description		TWO PIECE BASE

3,5

5256

December 1, 2010

Dannon Wright 656 County Rd 28 Double Springs, AL 35553 Ph: 205-617-3189

Ref: # 5256

Dear Mr. Wright,

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination.

Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results.

I hope that this action will keep you a loyal Remington customer.

Sincerely,
D. Fulcher
Consumer Affairs Administrator
Remington, H&R, Marlin
Phone: 1-800-243-9700

Fax: 336-548-7872

AN 0 0 2011

BY: .....

enclosure

G6874601 Model: 700 RE00215764 could not duplicate concern. T.A. Punctions as Designed. Assm. is Dirty. Check over computely, clean thest fine at N/c unraamly



Print

Reset

Model	Serial	
Number: 100 + 2 Vasmint	Number: 6687460	
Are you the original ow	ner?: ☒ YES º NO	
Name: Name:	Date of Purchase:	
Address (no	PO Boxes):	
656 County Bog	128	
City: DoubleSprings	State: \( \( \) \( \) \( \) Zip: \( \] \( \] 35333	
Phone	Fax:	
(Daytime): 305-617-3185	190.	
E-mail Address:(if e-mail address is provid	ed, notification of receipt and shipment will	
be sent) Canonwris	4-60 114400-60m	
E-mail A		
I would like to receive future e	e-mail updates from Remington.	
Please describe your proble		
I was boltinsa shell and +	he gun fired and	
bolt dos Not Pixi down to the	The state of the s	
bolt does not Pushdown when	14 Shell 15 Chambercel, 17	
COSMIT Seel Smark all all	;	
the sin has not Cincil a co	be to so checked	
, , , , , ,	The that Since	
This gun risonly had 65000 76ha	racters left round's put in 1+	
' Ammunition I	nformation:	
Manufacturer: Harnay 55 grain Type: Varmint Express		
Other (i.e. bullet weight/type, shot size,		
powder):		
Handload Information:		
Powder Used:	Powder Weight:	
Case/Hull Used:	Primer Used:	
Bullet Type/Shot Size: Reloader Used:		
Firearms Care (Cleaning and Lubrication):		

Brand of cleaning solution used:
How often do you clean the bore? (Months or Number of
rounds) On camonth
How often do you clean the action? (Months or Number of
rounds) I rear 4p rounds
How often do you clean the trigger assembly? (Months or Number of
rounds) haven't yet
Brand of lubricant used: Harmons Oler 135 Gun 011
How often do you lubricate the bore? (Months or Number of
rounds) Montaly
How often do you lubricate the action? (Months or Number of
rounds) Fresy Lio mounds
How often do you lubricate the trigger assembly? (Months or Number of
rounds) Haven't 1/27
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? > YES INO
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?) T+13 a 0 5 1 3 6 13 8
What were the services
performed?)
Ship your INSURED firearm by either UPS or Parcel Post to:
Remington Arms Co., Inc.
Attn: Arms Service Division
14 Hoefler Avenue
Ilion, NY 13357
WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF
YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A
SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE),
TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.
:: Record the serial number of your firearm before sending it.
:: Pack your firearm for safety and to prevent further damage in shipping and handling.
Preferably,
ship in a firearm box. (Note: Original boxes may not be returned.)

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for

damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

- :: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)
- :: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

# ARS LABEL REQUEST FORM

DATE:		12/1/2010	REQUESTED BY:	Dell
QUANTITY:		1	WEIGHT PER PKG:	10 lbs
PLEASE CHECKONE MEDIA COORDINATOR TO MAIL			I WILL MAIL	XXXXX
DESCRIPTION:	Ref # 5256 rifle			

## LABEL INFORMATION

MAIL LABEL TO: Dannon Wright
656 County Rd 28
Double Springs, AL 35553
Ph: 205-617-3189

RETURN ITEM TC Remington Arms
Attn: Product Service
Ilion, NY

## APLEASE COMPLETE ALLEPARTIS OF THIS FORM: AND SEND TO THE MEDIA COORDINATION:

4XX596 DEC 1, 2010 ALL CURR USD 1 OF 1 SVC GNDCOM ACT WT 10.0 LBS
TRACKING# 1Z4XX5969066815375
REF 1:DANNON WRIGHT/CD/DMF
REF 2:5256/RIFLE

HANDLING CHARGE 0.00
SINGLE-PIECE PUB RATE CHRGS: SVC T/P USD DV 0.00 COD 0.00 RS 0.50
DC 0.00 DGD 0.00 SD 0.00

0.00

PUB+HANDLING

SP 0.00

PR

AH 0.00

TOT PUB CHG 8.74