Remington Arms Co., Inc. Product Service Legal Case #:5413

Case Information

Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete 12 8 H Date Opened 217413 1/4/2011 12/13/2010 1/6/2011

Customer Information

Business First Name Last Name Street Contact City State Zip Age Type H 724-962-4637 1500 Sandy Lane Hermitage PA 16148 Matchak Reporter Larry E Imatchak@verizon.net

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

21

C FSR

PD Cause:4038 Could Not Duplicate Concern Unknown 5 Concern: 1007 Fired on Safe Release

Customer sent in an email. He stated that his son was currently using the Model 700 that was his father's. His father bought the rifle around 1972. He stated that his father & his son have had a FSR. No damage, No injury. He would like to have trigger replaced, df

Firearm Information

Mfg. Type Model/Ga. SKU Serial ¥3433. DOM 311943 CF/BA 700/3006 SPRG EP 10/1/1967 Remington n/a Date Furchased Where Purchased Accessories Original Owner

TWP PIECE BASE N

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Reim. Cash Cash Settlement Release of Claims Release Date Reimbursement Date Date Settlement APV APV

Per Ilion - Quote to repair under BLM program

> Repair/Replacement Repair/Replacement Cost Date \$45,40 1/17/2011

12/13/10: I will email Itr & form, I will ask media coord, to email ARS, df 1/17/11: Per Ilion - Could not duplicate concern, TA very dirty & sticky, parts work sluggish. Replace TA, clean & test fire under BLM program - quote. Customer approd repair & paid by credit card, df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
***************************************	Examiner		B.TRAVIS
Examination	Exam Date		1/6/2011
	Product Type		RF

http://cps03ap13/200/psaapp/PrintDisplay.aspx7ID=\$413&Type=Case

1/17/2011

	Action Type		A.
	Assigned To		TNAGLE
Cause	403.8	Could Not Duplicate Concern	
	Description	21	22" 3006 SPR
	Date Code		EP
	Bore Plugged	False	
Barrei	Bulged	False	
	Fired	False	
	Fired while Obstructed		•
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Wom; Functioning	
	Shroud	Slightly Worn; Functioning	
Bok	Tace	Slightly Wom; Functioning	
	Handle	Slightly Wom; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Wom; Functioning	
Extractor	Cut Condition	Slightly Wom; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Wom; Functioning	
, and the second	Notch Condition	Select	
Overali	Exterior Condition	Slightly Wom; Functioning	
	Stock Condition	Slightly Worn; Functioning	Average of the state of the sta
	Fore End Condition	HSelect	
	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		M/700 BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lit	llSelect	.009
Sear	Notch	Slightly Worn; Functioning	SLUGGISH
	Tests	Test Fired	False
Feeding Test	11 (642542)	False	
	Condition	Slightly Worn; Functioning	DIRTY,STICKY
Trigger	Pull	Select	6#
A.A. ASSOCIATION OF THE PROPERTY OF THE PROPER	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description	sir	TWP PIECE BASE

Remingion

5413

December 13, 2010

Larry Matchak 1500 Sandy Lane Hermitage, PA 16148 Ph: 724-962-4637 Email: lmatchak@verizon.nst

Ref: #5413

Dear Mr. Matchak,

You will receive a pre-paid shipping label in a separate email within 24-48 hours. Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results.

I hope that this action will keep you a loyal Remington customer.

Sincerely, D. Fulcher Consumer Affairs Administrator Remington, H&R, Marlin Phone: 1-800-243-9700

Fax: 336-548-7872

NECESVI N JAN (2011

enclosure

311943 Model: 700



RE00217413

could not dupli cote concern T.A. very duzty a sticky, PADTS WORK sluggish, Rephace TPA, cleant test Pine under BLP for 8-20.00 + ship.

Quote

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025

Phone 800-243-9700 • www.remington.com

3000

L.Print. J	Reset 1					
Model	Serial					
Number: 700	Number: 3// 943					
Are you the original owner?: YES NO						
Name: LARRY MATCHAIC	Date of Purchase: スー3ー/タフン					
Address (no PO Boxes): /SOO SANDY 스ANE						
City: //ÆAMITAGE	State: PA Zip: 141-15					
Phone (Daytime): <u>フュケータレューガムスク</u>	Fax:					
* * * * * * * * * * * * * * * * * * *	ded, notification of receipt and shipment will					
be sent) LMATCHAK 6 V 5	RIZGN. NET					
	Address:					
💢 I would like to receive future	e-mail updates from Remington.					
****	lem and date of occurrence:					
ACCIDENTAL FI	RING WHEN					
SAFETY IS TAK	EN OFF.					
THIS MASPEN	to on 2 Oktassions					
ANCE APPROX. 2	OYEARS AGO, T					
ONE APPROX, 20 YEARS, AGO, TO						
* SEE ATTIC	TEO LETTER &					
500 characters left						
Ammunition	Information:					
Manufacturer: REMINGTON	Type: CONE-LOKT					
Other (i.e. bullet w	eight/type, shot size,					
powder):	O GRAIN					
*						
Handload I	nformation:					
Powder Used:	Powder Weight:					
Case/Hull Used:	Primer Used:					
Bullet Type/Shot Size.	Reloader Used:					
Firearms Care (Cleaning and Lubrication):						

http://www.remingtou.com/asp/factory_repair_form.asp

12/13/2010

LARRY MATCHAK 1500 SANDY LANE HERMITAGE, PA. 16148 PH# 724-962-4637 REF#5413 COPY OF ORIGINAL E-MAIL SENT

MY SON IS PRESENTLY USING HIS GRANDFATHERS REMINGTON MODEL 700 30-06 BOLT ACTION RIFLE. THIS GUN WAS PURCHASE BY MY FATHER IN 1972, BETWEEN MY SON AND MY FATHER THERE HAS BEEN 2 ACCIDENTAL FIRINGS OVER THE YEARS WHEN THE SAFETY IS TAKEN OFF. I UNDERSTAND THAT THERE HAS BEEN THIS TYPE OF PROBLEM WITH THIS RIFLE DATING WAY BACK. I AM NOT INTERESTED IN ANY LAW SUITS BUT WOULD FEEL MUCH BETTER KNOWNING THE GUN IS SAFE. I UNDERSTAND THAT THERE IS A REPLACEMENT TRIGGER THAT WILL SOLVE THE PROBLEM. I BELIEVE THAT IT IS THE X-MARK PRO TRIGGER ASSEMBLY. SO FAR I HAVE BEEN TOLD BY SEVERAL GUN DEALERS THAT I HAVE TO SEND THE RIFLE TO THE FACTORY TO GET THIS DONE. IF THIS IS TRUE WHERE DO I SEND IT AND HOW MUCH WILL IT COST? I WOULD APPRECIATE ANY HELP YOU CAN GIVE ME. SERIAL NUMBER ON THIS RIFLE IS #311943. THANK YOU

Brand of cleaning solution used: OUTERS + Hopge's				
How often do you clean the bore? (Months or Number of rounds) タデアルス ひゃくら しょうしゃ しょうしてしゃ				
How often do you clean the action? (Months or Number of rounds)				
How often do you clean the trigger assembly? (Months or Number of rounds) ンピルパレソ				
rounds) YEARLY Brand of lubricant used: OUTERS + Hoppe's				
How often do you lubricate the bore? (Months or Number of rounds) マルドストリー ひとたったけ ぶんし メルカソ				
How often do you lubricate the action? (Months or Number of rounds) レンター・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・				
How often do you lubricate the trigger assembly? (Months or Number of rounds) リタチュスムタ				
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? > 回 YES				
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?)				
What were the services performed?)				
Ship your INSURED firearm by either UPS or Parcel Post to:				
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Illion, NY 13357				
☐ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.				
:: Record the serial number of your firearm before sending it: :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably,				

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for

damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.

12/13/2818 00:56 AM

Reference # 101209-000045

Status Updated

Assigned To Administrators

Dell -

Product Fireams

SLA

Not specified

Queue CSR

Date Created 12/09/2010 12:12 PM

Initial Response 12/13/2010 08:51 AM

Last Updated 12/13/2010 09:56 AM

Customer SmartSense 0 (on -3 to +3 scale)

Staff SmartSense +1 (on -3 to +3 scale)

REMINGTON MODEL 700 BDL

Discussion Thread

Customer (Larry Matchak)

HERE IS THE INFORMATION YOU REQUESTED:

RIFLE SERIAL #311943

CAL. 30-06

MAILING ADDRESS: LARRY MATCHAK

1500 SANDY LANE

HERMITAGE, PA. 16148

PHONE # 724-962-4637

---- Original Message ----

From: Remington Information To: Imatchak@verizon.net

Sent: Monday, December 13, 2010 8:51 AM

Subject: REMINGTON MODEL 700 BDL [Incident: 101209-000045]

Response (Dell -)

12/13/2010 08:51 AM

Dear Mr. Matchak,
We would like to have the firearm come into our Product Services Department at our factory for examination.
Please reply back to me with the serial number of the firearm, caliber, your mailing address and phone number. We would like to send you a pre-paid shipping label for UPS to have the firearm come in. I will also include a form that you can fill out to let the examiner know exactly what happened, when this occurred, and what you are expecting.

Sincerefy, Dell

Customer (Larry Matchak)

12/09/2010 12:12 PM

MY SON IS PRESENTLY USING HIS GRANDFATHERS REMINGTON MODEL 700 BDL 30-06 BOLT ACTION RIFLE. THIS GUN WAS PURCHASE BY MY FATHER IN 1972. BETWEEN MY SON AND MY FATHER THERE HAS BEEN 2 ACCIDENTAL FIRINGS OVER THE YEARS WHEN THE SAFETY IS TAKEN OFF. I UNDERSTAND THAT THERE HAS BEEN THIS TYPE OF PROBLEM WITH THIS RIFLE DATING WAY BACK. I AM NOT INTERESTED IN ANY LAW SUITS BUT WOULD WOULD FEEL MUCH BETTER KNOWNING THE GUN IS SAFE. I UNDER STAND THAT THERE IS A REPLACEMENT TRIGGER THAT WILL SOLVE THE PROBLEM. I BELIEVE THAT IT IS THE X-MARK PRO TRIGGER ASSEMBLY. SO FAR I HAVE BEEN TOLD BY SEVERAL GUN DEALERS THAT I HAVE TO SEND THE RIFLE TO THE FACTORY TO GET THIS DONE. IF THIS IS TURE WHERE DO I SEND IT AND HOW MUCH WILL IT COST? I WOULD APPRECIATE ANY HELP YOU CAN GIVE ME. SERIAL NUMBER ON THIS RIFLE IS #311943. THANK YOU

Primary Contact

First Name: Larry Last Name: Matchak

Organization:

Login: Imatchak@verizon.net

Title: Contact Type:

Email: imatchak@verizon.net

Email - Alternate #1:

Email - Alternate #2:

Office Phone:

Mobile Phone:

Fax:

Assistant Phone: Home Phone:

Street

City

State/Province

Postal Code

Country

Additional Information

Model_Number: 700

5413

http://remington.custhelp.com/cgi-bin/remington.cfg/php/admin/display/inc print.php7p ... 12/13/2010



December 13, 2010

Larry Matchak 1500 Sandy Lane Hermitage, PA 16148 Ph: 724-962-4637 Email: Imatchak@verizon.net

Ref: #5413

Dear Mr. Matchak,

You will receive a pre-paid shipping label in a separate email within 24-48 hours. Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results.

I hope that this action will keep you a loyal Remington customer.

Sincerely, D. Fulcher Consumer Affairs Administrator Remington, H&R, Marlin Phone: 1-800-243-9700

Fax: 336-548-7872

enclosure

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com



December 13, 2010

Larry Matchak 1500 Sandy Lane Hermitage, PA 16148 Ph: 724-962-4637

Email: lmatchak@verizon.net

Ref: #5413

Dear Mr. Matchak,

You will receive a pre-paid shipping label in a separate email within 24-48 hours. Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results.

Fax: 336-548-7872

I hope that this action will keep you a loyal Remington customer.

Sincerely, D. Fulcher Consumer Affairs Administrator Remington, H&R, Marlin Phone: 1-800-243-9700

enclosure

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

Print	Resat					
Model Number:	Serial Number:					
Are you the original ow	ner?: 🛮 YES 🖾 NO					
Name:	Date of Purchase:					
Address (no PO Boxes):						
City:	State: Zip:					
Phone (Daytime):	Fax:					
E-mail Address:(if e-mail address is provided be sent)	led, notification of receipt and shipment will					
E-mail A						
Please describe your proble						
500 cha Ammunition l	racters left					
Manufacturer:	Type:					
Other (i.e. bullet we powder):	***************************************					
Handload ir						
Powder Used:	Powder Weight:					
Case/Hull Used:	Primer Used:					
Bullet Type/Shot Size:	Reloader Used:					
Firearms Care (Cleani	ng and Lubrication):					

Brand of cleaning solution used:
How often do you clean the bore? (Months or Number of rounds)
How often do you clean the action? (Months or Number of rounds)
How often do you clean the trigger assembly? (Months or Number of rounds)
Brand of lubricant used:
How often do you lubricate the bore? (Months or Number of rounds)
How often do you lubricate the action? (Months or Number of rounds)
How often do you lubricate the trigger assembly? (Months or Number of rounds)
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? > YES INO
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?)
What were the services performed?)
Ship your INSURED firearm by either UPS or Parcel Post to:
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357
☐ WARNING : DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM, THIS IS A VIOLATION OF FEDERAL LAW . IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.
:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for

damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

- :: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)
- :: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.

Fulcher, Dell Marie

From:

Verizon Online Postmaster [postmaster@verizon.net]

To:

Sent: Subject: imatchak@verizon.net Monday, December 13, 2010 5:13 PM Delivered: Larry Matchak - Ref# 5413

Your message has been delivered to the following recipients:

Imatchak@verizon.net

Subject: Larry Matchak - Ref# 5413





Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

ros a since	andamentium			······································	······		**********		
DATE:	12/13/2010		QUESTED BY:	Dell	***********		335433345555		
QUANTITY:	1	WE	IGHT PER PKG:	~~~~~~		10 lbs	*******		
eľeasejcheckione Media							***************************************		
COORDINATOR	XXXXXX	4 J						,	
TO MAIL	40 00 000000000000000000000000000000000	3							
DESCRIPTION:	Ref # 5413		***************************************	•••••		vannananananananavv	********	***************************************	
	rifle		4XX598 DEC SVC GNBCOM TRACKING: 114XX8 REF 1:LPRRY MATC REF 2:5413/91FLE	:HAK/CI	701014	ALL CUR T 10.0 LBS 13	R USD	31 .	OF 1
	LABEL II	NF(HANDLING CHARCE SINGLE-PIECE PUB DV 0.00 DC 0.00 AH 0.00 TOT PUB CHG 7.92	RATE C C P	CD (3.80 3.60 3.00	88 80 88	T/P USD 1.80 0.80 8.80	
MAIL LABEL TO:	Larry Matchak	*********	TO: PUB CHG 7.52		b	NB+HANDLI	พย	7.92	
	1500 Sandy Lane								
	Hermitage, PA 16148							1	
	Ph: 724-962-4637								
	Email: Imatchak@verizon.o	n k		200		stomer.			
	Linui. Highligh w yvikhili	Ç.Ş.		&	110000	(B) (S) (1 (1 (1 (1 (1 (1 (1 (1 (1 (1 (1 (1 (1			
RETURNITEM TO	Remington Arms	**********		***********	***************************************	***************************************	VVVVVVVVVVVVVVVVVVVVVVVVVVVVVVVVVVVVVV	***************************************	
	Attn: Product Service								
	Ilion, NY							}	
	expected that t								
		3							
Suitanaus functions expansional action and process	ing any pagagaga ang ang ang ang ang ang ang ang	×							

RELEASE CONFLETE ALL PARTS OF THIS FOR

(_lmatchak@verizon.net * L″







