

## Remington Arms Co., Inc.

Product Service

Legal Case #:4212

## Case Information

| RE#    | Date Opened | Date Opened(PS) | Date Closed | Incident Date | Pre Lit | Lit | Obsolete |
|--------|-------------|-----------------|-------------|---------------|---------|-----|----------|
| 184628 | 1/8/2010    | 1/11/2010       | 1/11/2010   |               |         |     |          |

## Customer Information

| Type     | Business              | First Name | Last Name       | Street       | City   | State | Zip   | Age | Contact        |
|----------|-----------------------|------------|-----------------|--------------|--------|-------|-------|-----|----------------|
| Reporter | B-Z Gun & Repair Shop |            | B-Z Gun & Repai | 5225 39th St | Groves | TX    | 77619 |     | W 409-963-3407 |

## Incident Information

| Claims | Codes                    | Repair Est.                 | Medical Treatment             | Medical Status |
|--------|--------------------------|-----------------------------|-------------------------------|----------------|
| PI     |                          |                             |                               |                |
| PD     | Cause:4038               | Could Not Duplicate Concern |                               |                |
| S      | fired when safety was on | Concern:1005                | Unexplained Discharge Safe ON | Unknown        |
| C      |                          |                             |                               |                |

1/15/10 Per note with rifle, the dealer shipped this for his customer who stated the rifle fired when safety was on.cm

## Firearm Information

| Mfg.           | Type                   | Model/Ga.            | SKU            | Serial  | Bbl. | DOM      |
|----------------|------------------------|----------------------|----------------|---------|------|----------|
| Remington      | CF/BA                  | 700/243 WIN          | 20000          | 6737249 | CY   | 4/1/1974 |
| Date Purchased | Where Purchased        | Accessories          | Original Owner |         |      |          |
|                | S S KRESGE FT WAYNE IN | TWO PIECE SCOPE BASE | U              |         |      |          |

CONCERN:FIRED WITH SAFETY ON

Ammunition Information - None Defined

Other Products Information - None Defined

## Settlement

Remington/700/CF/BA

| Settlement                                                              | Release of Claims | Release Date | Reimbursement | Cash Settlement | Reim. Date APV | Cash Date APV |
|-------------------------------------------------------------------------|-------------------|--------------|---------------|-----------------|----------------|---------------|
| Per Ilion inspect/decision, replace TPA, clean at BLSM price \$20 + S&H |                   |              |               |                 |                |               |

| Repair/Replacement Cost | Repair/Replacement Date |
|-------------------------|-------------------------|
| 82.34                   | 1/15/2010               |

1/15/10 Per Ilion, could not duplicate concern. Trig set screws altered. Replace TPA, check over, clean under bolt lock program for \$20 + S&H.cm

## Examination[Remington/CF/BA]

| Part        | Sub-Part     | Code | Comment   |
|-------------|--------------|------|-----------|
| Examination | Examiner     |      | B.TRAVIS  |
|             | Exam Date    |      | 1/11/2010 |
|             | Product Type |      | RF        |
|             | Action Type  |      | A         |

|                          |                        |                                   |                                 |
|--------------------------|------------------------|-----------------------------------|---------------------------------|
|                          | Assigned To            |                                   | F.SUPRY                         |
| Cause                    | 4006                   | Altered Adjustments or Components |                                 |
| Barrel                   | Description            |                                   | 22" 243 WIN                     |
|                          | Date Code              |                                   | CY                              |
|                          | Bore Plugged           | False                             |                                 |
|                          | Bulged                 | False                             |                                 |
|                          | Fired                  | False                             |                                 |
|                          | Fired while Obstructed |                                   |                                 |
|                          | Muzzle/Crown Condition | Slightly Worn; Functioning        |                                 |
| Bolt                     | Firing Pin             | Slightly Worn; Functioning        |                                 |
|                          | Shroud                 | Slightly Worn; Functioning        |                                 |
|                          | Face                   | Slightly Worn; Functioning        |                                 |
|                          | Handle                 | Slightly Worn; Functioning        |                                 |
|                          | Stop                   | Slightly Worn; Functioning        |                                 |
| Extractor                | Condition              | Slightly Worn; Functioning        |                                 |
|                          | Cut Condition          | Slightly Worn; Functioning        |                                 |
|                          | Ext/Eject Test         | False                             |                                 |
| Locking                  | Block Condition        | ---Select---                      |                                 |
|                          | Lug Condition          | Slightly Worn; Functioning        |                                 |
|                          | Notch Condition        | ---Select---                      |                                 |
| Overall                  | Exterior Condition     | Slightly Worn; Functioning        |                                 |
|                          | Stock Condition        | Slightly Worn; Functioning        |                                 |
|                          | Fore End Condition     | ---Select---                      |                                 |
| Receiver                 | Condition              | Slightly Worn; Functioning        |                                 |
|                          | Bulged                 | False                             |                                 |
| Safety                   | Description            |                                   | STANDARD M/700 BOLT LOCK SAFETY |
|                          | Function               | Like new; Functioning             |                                 |
| Sear                     | Lift                   | ---Select---                      | .010                            |
|                          | Notch                  | Like new; Functioning             |                                 |
|                          | Tests                  | Test Fired                        | False                           |
| Feeding Test             |                        | False                             |                                 |
| Trigger                  | Condition              | Like new; Functioning             |                                 |
|                          | Pull                   | ---Select---                      | 3#                              |
|                          | Altered                | True                              | SET SCREWS ALTERED              |
|                          | Sub-Assembly           | M/700 Bolt Lock                   |                                 |
| Non-Remington Components | Description            |                                   | TWO PIECE SCOPE BASE            |






























$$\begin{array}{r} 27 \\ 20.74 \\ 35. \\ \hline 82.74 \end{array}$$

RECEIVED  
JAN 13 2010

BY:.....

UB  
4212  
B-Z Gun & Repair Shop  
5225 39<sup>th</sup> St.  
Groves, Texas 77619  
(409)963-3407

4/4/74  
22"  
3#  
.010

12/21/2009

To: Remington

I am sending the rifle listed below for a customer to be repaired or replaced. The rifle fired when safety was on.

1) Remington 700 ser.# 6737249 243 win.

If you have any questions, please call the number listed above.


Thank You,

*Sonia Boden*

Sonia Boden  
(Mgr.)

6737249

Model: 700



RE00184628

could not duplicate concern.  
Trig. set screws altered.  
Replace TPA, check over, clean  
under bolt lock program Rec.  
\$20.00 + \$4.00

Quote