

Remington Arms Co., Inc.  
Product Service  
Legal Case #:4845

## Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
		10/26/2010	10/26/2010				

## Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Carl	Canerossi			NY			C 631-418-5174

## Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4079 Other - Unexamined		Unknown	
S FSR	Concern:1007 Fired on Safe Release			
C				

10/26/10 Per call from Canerossi, he bought his Model 700 new in the mid-90's and installed a trigger shoe and replaced the barrel. 2nd year owning it he went to Alaska and had a FSR. He thought it was his mistake but has had it happen twice since, a PA and NY hunt. He cannot duplicate it when he tries.cm

## Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/	n/a			
Date Purchased	Where Purchased	Accessories	Original Owner			
			Y			

bought in mid-90's, altered

Ammunition Information - None Defined

Other Products Information - None Defined

## Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
	Repair/Replacement Cost	Repair/Replacement Date				

10/26/10 His rifle has been altered with an aftermarket barrel and a trigger shoe. I told him that he might want to contact a RARC for inspection as the factory does not repair altered rifles without quoting to for parts to put it back to factory specs.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
------	----------	------	---------