

Remington Arms Co., Inc.
Product Service
Legal Case #:5982

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
227584	4/1/2011	3/9/2011	4/4/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Michael	Mayhew	161 Delaware Rd.	Statesville	NC	28625		W 704-775-6706 C 704-419-4092 E mayhewmichael55@yahoo.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern	Unknown	
S	Concern:1007	Fired on Safe Release		
C	FSR			

3/9/11: Customer called in. He stated that he had FSR about 5 years ago. No damage, No injury. He stated that he adjusted the trigger & he is having problems with the trigger locking up. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/22-250 REM	85352	G6680467	BF	8/14/2007 7:26:20 AM
Date Purchased	Where Purchased	Accessories	Original Owner			
	DICK S SPORTING GOODS	TWO PIECE BASE	Y			

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair						

Repair/Replacement Cost Repair/Replacement Date

3/9/11: Sending ARS, letter, form, box. Box order# 1199604. df 4/8/11: Per Ilion - Could not duplicate concern. TA set screws altered, safety snap clip mis-assembled. Replace TA, clean & test fire @ 1/2 normal cost - quote. I emailed quote to customer for appr & payment. df 4/15/11: Left msg for customer to call about quote. df 4/19/11: Customer called. He is mailing a check for quote. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		4/4/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		24" 22-250 REM HB
	Date Code		BF
	Bore Plugged	False	
	Bulged	False	
	Fired	False	

	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.011
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	HAS AN EXCESSIVE AMOUNT OF SEAR ENGAGEMENT SAFETY SNAP CLIP MISASSM
	Pull	---Select---	4#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

QUOTATION**Remington Arms Company, Inc.****ESTIMATING
REPORT**Parts/Repairs
Fax800-243-9700
336-548-7801870 Remington Dr. P.O. Box 700
Madison, NC 27025-0700www.remington.com info@remington.com**ALL PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS.**

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (4) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 15 DAYS, WE SHALL RETURN THE ITEM(S) AS RECEIVED POSTAGE DUE.

Repair Order Number RE00227584 Account # - R-	Description/Serial Number B6680467	Date Received - 4/1/2011 Estimate Date - 4/4/2011 Current Date - 4/8/2011
Customer MICHAEL MAYHEW 161 DELAWARE ROAD STATESVILLE, NC 28625 US		Return To MICHAEL MAYHEW 161 DELAWARE ROAD STATESVILLE, NC 28625 US
Phone (H) (704)-419-4092 Phone (W) (704)-775-6706	Fax Email mayhewmichael55@yahoo.com	

Please Circle One
 VISA MC AMEX DISCOVER Card No. _____ Exp. Date _____
 PO Number _____
 Daytime Phone (____) _____ Time To Call _____ Open Acct. R _____
 Approval: Customer Signature _____ Date _____
☐ If You Desire Any Change Please Use The Reverse Side For Your Comments And Mark This Box
Notice: We process checks electronically through Check 21

Reported		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTIO	M123	FORWARD TO PRODUCT SERVICE F

Technician's Comments

ProblemNotes could not duplicate concern.trigger assm set screws altered.safety snap clip misassm.replace trigger plate assm, clean and test fire at 1/2 normal cost.

Estimate **C.O.D. /Shipping and Handling Charges are NOT Included in this Quote

Material #	Material Description	Qty	Warranty Y/N	Price/ Unit	Discount Percent	Extended Amt
Part						
F305570B	X-MARK PRO 700 TRIG ASSB RH BLACK (O	1	N	\$94.00	50%	\$47.00
Service						
4000114	GR-SHIPING & HANDLING (GUN REPAIR)	1	N	\$17.00	0%	\$17.00
4000119	GR-TEST	1	N	\$23.00	50%	\$11.50
Sub Total:						\$75.50
Est. Sales Tax:						\$2.82
Grand Total:						\$78.32

5982

[COPY]

24"
BF 1/85
4#
10/11

March 9, 2011

Michael Mayhew
161 Delaware Rd.
Statesville, NC 28625
Ph: 704-419-4092

Ref: # 5982, M/700

Dear Mr. Mayhew,

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination.

Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results.

I hope that this action will keep you a loyal Remington customer.

Sincerely,
D. Fulcher
Consumer Affairs Administrator
Remington, H&R, Marlin
Phone: 1-800-243-9700
Fax: 336-548-7872

RECEIVED
APR 07 2011

enclosure

RECEIVED
APR 07 2011

B6680467

Model: 700



RE00227584

BY:.....

could not duplicate concern.
T.A. set screws altered, Safety
swap clip misassembly replace TPA,
clean & test fire at 1/2 normal
cost.

Quote

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025
Phone 800-243-9700 • www.remington.com

PS 21263

Print

Reset

Model Number: <u>700</u>		Serial Number: <u>B 6680 467</u>	
Are you the original owner?: <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO			
Name: <u>MICHAEL LEE MAYHEW</u>		Date of Purchase: <u>P in the 70s or 80s</u>	
Address (no PO Boxes): <u>161 Delaware Road</u>			
City: <u>STATESVILLE</u>	State: <u>NC</u>	Zip: <u>28625</u>	
Phone (Daytime): <u>704 775 6706</u>		Fax: <u></u>	
E-mail Address: (if e-mail address is provided, notification of receipt and shipment will be sent) <u>MAYHEW MICHAEL55@YAHOO.COM</u>			
E-mail Address: <input checked="" type="checkbox"/> I would like to receive future e-mail updates from Remington.			
Please describe your problem and date of occurrence: <u>FIRST TIME TRIGGER LOCKED UP, THE GUN WENT OFF BY ITS SELF, THEN 4 YEARS LATTER SAME THING, THEN RECENTLY SAME THING HAPPENED AGAIN.</u>			
500 characters left			
Ammunition Information:			
Manufacturer: <u>Remington</u>		Type: <u>22-250</u>	
Other (i.e. bullet weight/type, shot size, powder): <u>55GR. PSP R22501</u>			
Handload Information:			
Powder Used: <u></u>		Powder Weight: <u></u>	
Case/Hull Used: <u></u>		Primer Used: <u></u>	
Bullet Type/Shot Size: <u></u>		Reloader Used: <u></u>	
Firearms Care (Cleaning and Lubrication):			

Brand of cleaning solution used:	
How often do you clean the bore? (Months or Number of rounds)	10 To 15 Rounds
How often do you clean the action? (Months or Number of rounds)	Same
How often do you clean the trigger assembly? (Months or Number of rounds)	Same
Brand of lubricant used:	HOPPE'S & WD 40
How often do you lubricate the bore? (Months or Number of rounds)	10 To 15 Rounds
How often do you lubricate the action? (Months or Number of rounds)	Same
How often do you lubricate the trigger assembly? (Months or Number of rounds)	Same
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual?	> <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?	NEVER
What were the services performed?	
Ship your INSURED firearm by either UPS or Parcel Post to: Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357	
<input type="checkbox"/> WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM. :: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper	

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.



www.remington.com

Remington Arms Company, Inc.
870 Remington Drive
P. O. Box 700
Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:	3/9/2011	REQUESTED BY:	Dell
QUANTITY:	1	WEIGHT PER PKG:	10 lbs
PLEASE CHECK ONE			
MEDIA COORDINATOR TO MAIL		I WILL MAIL	XXXXXX
DESCRIPTION: Ref# 5982 rifle			

LABEL INFORMATION

MAIL LABEL TO: Michael Mayhew 161 Delaware Rd. Statesville, NC 28625 Ph: 704-419-4092
RETURN ITEM TO Remington Arms Attn: Product Service Ilion, NY

PLEASE COMPLETE ALL PARTS OF THIS FORM AND SEND TO THE MEDIA COORDINATOR

4XX596 MAR 10, 2011 ALL CURR USD 1 OF 1
SVC GND COM ACT WT 10.0 LBS
TRACKING# 1Z4XX5969067980533
REF 1:MICHAEL MAYHEW/CD/DMF
REF 2:5982/RIFLE

HANDLING CHARGE 0.00
SINGLE-PIECE PUB RATE CHRG:
DV 0.00 COD 0.00 SVC T/P USD
DC 0.00 DGD 0.00 RS 0.50
AH 0.00 PR 0.00 SD 0.00
TOT PUB CHG 8.84 PUB+HANDLING 8.84







