Remington Arms Co., Inc. Product Service Legal Case #:5260

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete 228839 4/14/2011 12/1/2010 4/15/2011

Customer Information

Type Business First Name Last Name Street City State Zip Age Contact W 800-262-2012- x 123 150 Wades Mill Rd. Winchester F 859-744-3623 Jonathan Morphew 40391 Reporter E jmorphew@deltagas.com

Incident Information

Claims Codes Repair Est. **Medical Treatment Medical Status**

ΡI PD

Cause: 4006 Altered Adjustments or Components

Unknown

S

Concern: 1007 Fired on Safe Release

C FSR

12/1/10: Customer called in. He stated that his father was shooting rifle about a week ago & had a FSR. No damage, No injury. He bought it used at a gun store. df

Firearm Information

Mfg. Remington

Type CF/BA

Model/Ga. 700/270 WIN

SKU 26033 Serial

Bbl.

DOM

Date Purchased

Where Purchased **ELLETT BROTHERS** Accessories

Original Owner N

E6368254 CR

4/28/1997

CONCERN: FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement

Release of Claims

Release Date

Reimbursement

Cash Settlement Reim. Date Cash Date

APV APV

Per Ilion - Quote to repair

Repair/Replacement Cost Repair/Replacement Date

12/1/10: Sending ARS, ltr, form. df 4/26/11: Per Ilion - Could not duplicate concern. Trigger not returning properly. TA dirty & set screws altered. Can offer to replace TA, clean & test fire @ 1/2 normal cost - quote. Customer included CC# with repair form. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date]	4/15/2011
	Product Type		RF
	Action Type]	A
	Assigned To]	T.NAGLE
Cause	4006	Altered Adjustments or Components	
Barrel	Description]	22" 270 WIN
	Date Code]	CR
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed]	
	Muzzle/Crown Condition	Slightly Worn; Functioning]

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=5260&Type=Case

4/26/2011

Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
Extractor	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
Locking	Ext/Eject Test	False	
	Block Condition	Select	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Dagairea	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		M/700 SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.014
Sear	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	16212	False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY AND TRIG NOT RETURNING PROPERLY
	Puli	Select	2#
	Altered	Тпие	SET SCREWS ALTERED
	Sub-Assembly	M/700 Non-Bolt Lock	

CON 24/9

5260

December 1, 2010

Jonathan Morphew 150 Wades Mill Rd ——— Winchester, KY 40391 Ph: 800-262-2012 x 123

Ref: #5260

Dear Mr. Morphew,

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination.

Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results.

I hope that this action will keep you a loyal Remington customer.

Sincerely,
D. Fulcher
Consumer Affairs Administrator
Remington, H&R, Marlin
Phone: 1-800-243-9700

Fax: 336-548-7872

APR 20 2011

BY:----

enclosure

E6368254

Model: 700

could not duplicate concern.

TRIG. NOT INTURNING PROPERTY

T.A. disty + set screws Altered.

CAN offer to hyplace TPA, chan

+ TEST RIRE At 1/2 HORIMAL LOST.



Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com Jonathan Morphew Delta Natural Gas Co., Inc. 3617 Lexington Rd Winchester, KY 40391

D. Fulcher
Consumer Affairs Administrator
Remington, H&R, Marlin
.870 Remington Drive, P.O.-Box-700 —
Madison, NC 27025

RE: Remington Model 400 S/N E6368254

Attn: D. Fulcher,

Pursuant to our telephone conversation several weeks ago, I am finally taking care of this issue. I have answered the enclosed questionnaire to the best of my ability.

At the risk of being redundant, I will briefly explain my situation. I bought this rifle used in 2003 (I think) and it was in like new condition. Not long after buying it, I gave it to my dad as a gift. He is now 74 years old. Several weeks ago, he was hunting with it in Arkansas. He was preparing to shoot when he moved the safety switch forward. Upon moving it, the gun discharged. Thank the Lord no one or anything, was damaged as a result of this discharge. He tried to repeat the process over and over and one other time (gun unloaded of course) the gun did drop the firing pin again upon moving the safety.

Like everyone else, we have seen the negative reports regarding the trigger mechanisms in the Model 700's. We are not trying to seek any damages, money or any such thing. I just want Remington to inspect the rifle and make it operationally safe for my dad. Of course, I would prefer this procedure to be done as reasonable (\$) as possible. We have been loyal Remington customers for many years. I look forward to a positive experience with you and your company.

Respectfully

Jónáthán Morphew (859) 749-3757 c

(859)744-6171 x123 w

Print

Reset

Model Number: 700	Serial Number: <i>E636</i> 8254							
Are you the original owner?: ☐ YES 🂢 NO								
Name: JONATHAN MORPHEN	Date of Purchase:							
Address (no PO Boxes):								
DELTA NATURAL GAS Co., 3617 LEXINGTON RO								
City: WINCHESTER State: KY Zip: 40391								
Phone (Daytime): (800) 262 -2012 x 123	Fax: (859) 744-3623							
E-mail Address:(if e-mail address is provid	The state of the s							
be sent) SMORPHEW @ DELTAG	AS, Com							
E-mail Address: X I would like to receive future e-mail updates from Remington.								
Please describe your problem and date of occurrence:								
OCCASIONALLY GUN WILL FIRE BY SIMPLY MOUNG								
THE SAFETY FORWARD. THIS HAS HASPENED TWEET								
ONCE WHEN THE GUN WAS	· 1							
ACCIDENTAL DISCHARGE.								
500 characters left								
Ammunition I								
Manufacturer: Reministration CONE-LOKT								
Other (i.e. bullet weight/type, shot size, powder):								
Handload Information:								
Powder Used: Powder Weight:								
Case/Hull Used:	Primer Used:							
Bullet Type/Shot Size:	Reloader Used:							
Firearms Care (Cleaning and Lubrication):								

Brand of cleaning solution used: Rem Oic						
How often do you clean the bore? (Months or Number of rounds) Twite Avyracy						
How often do you clean the action? (Months or Number of rounds)						
How often do you clean the trigger assembly? (Months or Number of						
rounds) NONE Brand of lubricant used: Rem On						
How often do you lubricate the bore? (Months or Number of rounds) Twice Advised						
How often do you lubricate the action? (Months or Number of rounds)						
How often do you lubricate the trigger assembly? (Months or Number of rounds) Twice Assumed						
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? >□ YES 🂢 NO						
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?)						
What were the services performed?)						
Ship your INSURED firearm by either UPS or Parcel Post to:						
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357						
☐ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.						
:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper						

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for

damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.

MASTER CARO

REDACTED

JONATHAN W. MORPHEN



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:		12/1/2010	REQUESTED BY:	Dell	
QUANTITY:		1	WEIGHT PER PKG:		10 lbs
PLEASE CHECK ONE MEDIA COORDINATOR TO MAIL			I WILL MAIL	XXXXXX	
DESCRIPTION:	Ref # 5260 rifle				

LABEL INFORMATION

MAIL LABEL TO: Jonathan Morphew
150 Wades Mill Rd
Winchester, KY 40391
Ph: 800-262-2012 x 123

RETURN ITEM TC Remington Arms
Attn: Product Service
Ilion, NY

PLEASE COMPLETE ALL PARTS OF THIS FORM AND SEND TO THE MEDIA COORDINATOR

4XX596 SVC GNDCOM DEC 1, 2010 ALL CURR USD ACT WT 10.0 LBS 1 OF 1 TRACKING# 124XX5969066739814 REF 1: JONATHAN MORPHEW/CD/DMF REF 2:5260/RIFLE HANDLING CHARGE 0.00 SINGLE-PIECE PUB RATE CHRGS: SVC T/P USD COD" 0.00 0.00 0.00 DV 0.00 RS 0.50 SD 0.00 DGD DC 0.00 AH 0.00 PR SP 0.00 TOT PUB CHG 8.20 PUB+HANDLING







