Remington Arms Co., Inc. Product Service Legal Case #:6936

Case Information

RE# **Date Opened** Date Opened(PS) Date Closed Incident Date Pre Lit Obsolete 1/25/2012 11/29/2011 2/3/2012 11/26/2011 255898 Customer Information

Contact Type **Business** First Name Last Name Street City State Zip Age C 504-416-4088 837 Ave G F 504-826-1176 70094 Incident Nickey Chaisson Westwego E snapper.head@cox.net

Incident Information

Medical Treatment Medical Status Repair Est. Claims Codes

PΙ

PD Shot a hole in truck door Cause:4038 Could Not Duplicate Concern

Concern: 1007 Fired on Safe Release S

Unknown

C FSR

11/29/11: Cusotmer called in. He stated that he was using rifle on 11/26/11 & it had a FSR & shot a hole in his truck door. He did not ask refund on truck damage. He bought gun used from a friend & has never had a problem for years. df

Firearm Information

Model/Ga. SKU DOM Mfg. Type Serial Bbl. 700/3006 SPRG Remington CF/BA n/a 6448782 PU 6/1/1971 **Original Owner** Where Purchased Accessories

Date Purchased

M W DIST CHARLESTON W VA

N

CONCERN: FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Reim. Date Cash Date Cash Settlement Release of Claims Release Date Reimbursement Settlement APV APV

Replace TA, clean & test fire @ n/c - goodwill gesture

Repair/Replacement Repair/Replacement Date Cost

\$66

11/29/11: Mailing ARS & forms. Box order# 1276400. df 2/3/12: Spoke to customer. We agreed to replace TA, clean & test fire @ n/c goodwill gesture. df


Examination[Remington/CF/BA]

Sub-Part	Code	Comment
Examiner		B.TRAVIS
Exam Date		1/26/2012
Product Type		RF
Action Type		A
Assigned To		T.NAGLE
4038	Could Not Duplicate Concern	
Description		22" 3006 SPRG
Date Code		PU
Bore Plugged	False	
Bulged	False	
Fired	False	
	Examiner Exam Date Product Type Action Type Assigned To 4038 Description Date Code Bore Plugged Bulged	Examiner Exam Date Product Type Action Type Assigned To 4038 Could Not Duplicate Concern Description Date Code Bore Plugged Bulged False

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=6936&Type=Case

2/3/2012

	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		M/700 BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.010
Sear	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Functioning	
Trigger	Pull	Select	5#
Trigger	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	



6936

November 29, 2011

Mickey Chaisson 837 Ave G Westwego, LA 70094 Phone: 504-416-4088

Ref: #6936, Model 700, Serial #6448782

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination and service request. A box will arrive separately.

Please include a copy of this <u>letter and service request</u> to put inside the shipping container. The letter and service request inside are important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results. I will contact you once I get the report.

I hope this action will keep you a loyal Remington customer.

Sincerely,
Dell Fulcher
Consumer Affairs Administrator
Remington Arms Co., LLC
Phone: 1-800-243-9700 press 0 and ask for ext 8686

Fax: 336-548-7872

enclosure



DEGETTED JAN 3 0 2012 BY:

Remington Arms Company, LLC • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

Service Request

Remington Service

Madison, NC 27025-0700

ATTN: Product Service

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. **ENCLOSE THIS DOCUMENT WITH YOUR RETURN**.

Service Request Number SR00005129	Serial Number / Description 6448782		Date of Date	Request: Printed:	11/29/20 11/29/20	
	Model 700 Center Fire Caliber: 3006					
Customer: MICKEY CHAISSON		Destination: Arms Services				
837 AVE G		14 Hoefler Ave				
WESTWEGO, LA 700)94 US	Ilion, NY 13357	US	4.0 000		
Email:		Email:				
	e item(s) will be evaluated by our repairman to dontacted with an estimate before work is perform		icy. If it is	your firearm	will be rep	aired and
Reason For Return M123 - FORWARD TO F	PRODUCT SERVICE FOR INSPECTION					
Service Request Section Product Service # 6936 - F	SSR		Grand Control of the			
Parts And Service Details Material Type	Description	Qty Warranty Needed		Price	Disc A	\mount
			•			
	·					
		•				
THIS IS NOT AN INVOICE. Theing sent based on the converse	This is a pre-estimate to repair, recondition, or restation with our representative.	place the item(s)		b Total: Sales Tax:		. 00 . 00

Print

Reset

Model Number: 700	Serial Number: 6448782		
Are you the original ow			
Name: NICKey Chaisson	Date of Purchase: 8/200/ (APPRox.)		
837 AVE G	PO Boxes):		
city: westwego	State: LA Zip: 70094		
Phone (Daytime): 504-416-4089	Fax: 504-826-1176		
E-mail Address: (if e-mail address is provided be sent) SNAPPER . HEAD			
E-mail A I would like to receive future e			
Please describe your problem and date of occurrence:			
11-26-11			
RIFLE FIRED WHEN SAFTY			
WAS dISENGAGE	rd To unload		
RIFIE 500 cha	racters left		
Ammunition I			
Manufacturer: Remington	Type: PSPcoke LOKT		
Other (i.e. bullet wei powder): 150 gR	ght/type, shot size,		
}			
Handload Information:			
Powder Used:	Powder Weight:		
Case/Hull Used:	Primer Used:		
Bullet Type/Shot Size:	Reloader Used:		
Firearms Care (Cleani	ng and Lubrication):		

http://www.remington.com/asp/factory_repair_form.asp

8/25/2011

Brand of cleaning solution used:
How often do you clean the bore? (Months or Number of rounds)
How often do you clean the action? (Months or Number of rounds) 3.70 6 months
How often do you clean the trigger assembly? (Months or Number of rounds) 3 70 6 m out s
Brand of lubricant used: Hoppe S
How often do you lubricate the bore? (Months or Number of rounds) 3 70 6 mculs
How often do you lubricate the action? (Months or Number of rounds) 3 To 6 months
How often do you lubricate the trigger assembly? (Months or Number of rounds)
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? >□ YES 💥 NO
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?)
What were the services performed?)
Ship your INSURED firearm by either UPS or Parcel Post to:
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357
☐ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.
:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper

http://www.remington.com/asp/factory_repair_form.asp

8/25/2011

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for

damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.

ARS LABEL REQUEST FORM

11/29/2011	Service Request #	SR00005129
1	WEIGHT PER PACKAGE:	10 LBS
fulcherdm	email address:	I WILL MAIL LABEL
	1	1 WEIGHT PER PACKAGE:

Business:

Remington Service PO Box 700 Madison, NC 27025-0700 www.Remington.com

LABEL INFORMATION

MAIL LABEL TO:

MICKEY CHAISSON 837 AVE G

WESTWEGO, LA 70094 US

SR00005129

Email:

RETURN ITEM TO:

ILN

Arms Services



