Remington Arms Co., Inc. Product Service Legal Case #:6915

Case Information

 RE#
 Date Opened
 Date Opened(PS)
 Date Closed
 Incident Date
 Pre Lit
 Lit
 Obsolete

 251291
 12/20/2011
 11/28/2011
 12/21/2011

231271 12/20/201

Customer Information

Type Business First Name Last Name Street City State Zip Age Contact C 541-979-8167

Incident Dennis Fryman 2963 SE 17th Ave Albany OR 97322 F 541-928-8373

E dewm@comcast.net

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PΙ

S

PD Cause:4038 Could Not Duplicate Concern

Concern: 1020 Fired on Bolt Opening

Unknown

C FBO

11/28/11: Customer called in. He stated that a long time ago - no incident date - he had a FBO with the rifle. No damage, No injury. He put the gun away after that & just recently saw some blogs on the internet about the Model 700 & wants to send it in. df

Firearm Information

 Mfg.
 Type
 Model/Ga.
 SKU
 Serial
 Bbl.
 DOM

 Remington
 CF/BA
 700/3006 SPRG
 n/a
 A6625184 PQ 6/1/1978

Date Purchased Where Purchased Accessories Original Owner

Date Purchased Where Purchased Accessories Original Owner

PACIFIC SCHWABACHER SEATTLE WA

N

CONCERN: FBC

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Reim.
Settlement Date APV

Cash
Date APV

Per Ilion - Quote to repair under BLM

Repair/Replacement Cost Repair/Replacement Date

\$29 1/16/2012

11/28/11: Mailing ARS & forms. Box order# 1275480. df 12/22/11: Per Ilion - Could not duplicate concern. TA dirty & rusty. Replace TA, clean & test fire under BLM - quote. df

Examination[Remington/CF/BA]

| Part | Sub-Part | Code | Comment |
|-------------|--------------|------|------------|
| Examination | Examiner | | B.TRAVIS |
| | Exam Date | | 12/21/2011 |
| | Product Type | | RF |
| | Action Type | | A |

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=6915&Type=Case

1/16/2012

| | Assigned To | | T.NAGLE |
|--------------|------------------------|-----------------------------|------------------------|
| Cause | 4038 | Could Not Duplicate Concern | |
| Barrel | Description | | 22" 3006 SPRG |
| | Date Code | | PQ |
| | Bore Plugged | False | |
| | Bulged | False | |
| | Fired | False | |
| | Fired while Obstructed | | |
| | Muzzle/Crown Condition | Slightly Worn; Functioning | |
| | Firing Pin | Slightly Worn; Functioning | |
| | Shroud | Slightly Worn; Functioning | |
| Bolt | Face | Slightly Worn; Functioning | == |
| | Handle | Slightly Worn; Functioning | |
| | Stop | Slightly Worn; Functioning | SLUGGISH |
| | Condition | Slightly Worn; Functioning | |
| Extractor | Cut Condition | Slightly Worn; Functioning | _ |
| | Ext/Eject Test | False | |
| | Block Condition | Select | |
| Locking | Lug Condition | Slightly Worn; Functioning | |
| | Notch Condition | Select | |
| | Exterior Condition | Slightly Worn; Functioning | |
| Overall | Stock Condition | Slightly Worn; Functioning | |
| | Fore End Condition | Select | |
| | Condition | Slightly Worn; Functioning | |
| Receiver | Bulged | False | |
| Safety | Description | | M/700 BOLT LOCK SAFETY |
| | Function | Like new; Functioning | |
| | Sub-Assembly | Non-ISS | |
| | Lift | Select | .007 |
| Sear | Notch | Slightly Worn; Functioning | |
| | | Test Fired | False |
| Feeding Test | Tests | False | |
| | Condition | Slightly Worn; Functioning | DIRTY,RUSTY |
| Tuis | Pull | Select | 5# |
| Trigger | Altered | False | |
| | Sub-Assembly | M/700 Bolt Lock | |



6915

November 28, 2011

Dennis Fryman 2963 SE 17th Ave. Albany, OR 97322 Phone: 541-979-8167

Ref: #6915, Model 700, Serial # A6625184

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination and service request. A box will arrive separately.

Please include a copy of this <u>letter and service request</u> to put inside the shipping container. The letter and service request inside are important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results. I will contact you once I get the report.

I hope this action will keep you a loyal Remington customer.

DECEIVED DEC 2 2 2011

BY:----

Sincerely, Dell Fulcher

Consumer Affairs Administrator

Remington Arms Co., LLC

Phone: 1-800-243-9700 press 0 and ask for ext 8686

Fax: 336-548-7872

enclosure

Could not duplicate CONCERN T.A. dinty + musty, replace TPA, Elepno rest fine under BCP For \$ 20. + sup

Quote

Remington Arms Company, LLC • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

Service Request

Parts and Repairs: P:800-243-9700/F:336-548-7801

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s)

being sent based on the conversation with our representative.

Remington Service PO Box 700



Sub Total:

Est Sales Tax:

Madison, NC 27025-0700

ATTN: Product Service www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

| Service Request Number | Serial Number / Description | | Date of | Request: | 11/28/2011 |
|--|---|--|------------------------|-----------------|---|
| SR00004917 | A6625184 | | Date | Printed: | 11/28/2011 |
| | Model 700 Center Fire Caliber: 3006 | | | | |
| Customer: DENNIS FRYMAN | | Destination: Anns Services | | | |
| 2963 SE 17TH AVE | | 14 Hoefler Ave | | | |
| —-ALBANY, OR-97322 | -HS | Ilion, NY 13357 | US | | |
| ADDITIVE, OR SEDE | | 111011, 111 10001 | 00 | | |
| Email: | | Email: | | | |
| | e item(s) will be evaluated by our repairman to determine ontacted with an estimate before work is performed. | if it is covered under our warranty po | olicy. If it is | your firearm | will be repaired and |
| | | | | | |
| The second of th | 1. 15. Let 1 a let 1 J. 20. When the second limit combination | e op voor op op oppose op | A * 'or 'orres T | · SOME OF LIGHT | - Little the company of the second |
| Reason For Return M123 - FORWARD TO | PRODUCT SERVICE FOR INSPECTION | | un islamad | Mexicon work | |
| Service Request Section | | | FE 75 | 14. 78. | |
| Product Service # 6915 | the company payor is the first state of the company of the payor to the state of the company of | Township to appropriate the second of the second se | | and the second | Acceptable to the same of the |
| | | | | | |
| | | | | | |
| | | | | | |
| Danta And Carries Dateil | | Company of the Compan | 5 1 A.4 | | to the second second second |
| Material Type | Description | Qty Warranty Needed | الله . يعاضل سكا والده | Price | Disc Amount |
| J F - | | Needed | | | |
| | | | | • | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | _ | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| • | | | | | |
| | • | | | | |
| | | | | | |
| • | | • | | | |
| | | | | | |
| | | | | | |

.00

Print

Reset

| Model Number: 700 | Serial Number: <i>AGG</i> 25184 | | | | |
|--|---------------------------------------|-----|--|--|--|
| Are you the original owner?: ☐ YES ☒ NO | | | | | |
| Name: Dinny FRYMan | Date of Purchase: 20 years ago apaox. | | | | |
| Address (no PO Boxes): 2963 SE 175 Ave. | | | | | |
| City: Albany | State: 0 Zip: 97322 | | | | |
| Phone (Daytime): 541-979-8167 | Fax: 54/-928-8373 | | | | |
| E-mail Address: (if e-mail address is provided, notification of receipt and shipment will be sent) DCWMD comcast, rut | | | | | |
| E-mail Address: I would like to receive future e-mail updates from Remington. | | | | | |
| Please describe your problem and date of occurrence: | | | | | |
| appox, 20 genes ago, Hunting with beother walking down text to get into our boat. Pointed muster, into It the air to un lood shell out of chamber, Pulled bott love up and gun dicharged into air. Have not used gun sence. My boy is growing up tweeter getting into huntin I'm afrid to juse gun until I know its safe. I have | | | | | |
| taken it apart of the han territory colland (forms back, | | | | | |
| 500 characters left Hopen, you ean find | | | | | |
| Ammunition Information: problem, Love the gas | | | | | |
| Manufacturer: | Type: PHURY Cheistings | !!! | | | |
| Other (i.e. bullet weight/type, shot size, | | | | | |
| powder): | | | | | |
| Handload Information: | | | | | |
| Powder Used: Powder Weight: | | | | | |
| Case/Hull Used: | Primer Used: | * | | | |
| Bullet Type/Shot Size: | Bullet Type/Shot Size: Reloader Used: | | | | |
| Firearms Care (Cleaning and Lubrication): | | | | | |

http://www.remington.com/asp/factory_repair_form.asp

8/25/2011

| Brand of cleaning solution used: | | | | |
|---|--|--|--|--|
| How often do you clean the bore? (Months or Number of rounds) | | | | |
| How often do you clean the action? (Months or Number of rounds) Have not | | | | |
| How often do you clean the trigger assembly? (Months or Number of rounds). Have not | | | | |
| Brand of lubricant used: | | | | |
| How often do you lubricate the bore? (Months or Number of rounds) | | | | |
| How often do you lubricate the action? (Months or Number of rounds) | | | | |
| How often do you lubricate the trigger assembly? (Months or Number of rounds) | | | | |
| Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? > ☐ YES ☐ NO | | | | |
| When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?) $//a_s$ as | | | | |
| What were the services performed?) | | | | |
| Ship your INSURED firearm by either UPS or Parcel Post to: | | | | |
| Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357 | | | | |
| WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM. | | | | |
| :: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper | | | | |

http://www.remington.com/asp/factory_repair_form.asp

8/25/2011

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for

damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.

ARS LABEL REQUEST FORM

| DATE: | 11/28/2011 | Service Request # | SR00004917 |
|---------------|------------|---------------------|-------------------|
| QUANTITY: | 1 | WEIGHT PER PACKAGE: | 10 LBS |
| REQUESTED BY: | fulcherdm | email address; | I WILL MAIL LABEL |
| | | | |
| | | | |

Business:

Remington Service PO Box 700 Madison, NC 27025-0700 www.Remington.com

LABEL INFORMATION

MAIL LABEL TO:

DENNIS FRYMAN 2963 SE 17TH AVE ALBANY, OR 97322 US SR00004917


Email:

RETURN ITEM TO:

ILN

Arms Services





NOV 28, 2011 ALL CURR USD ACT UT 10.0 LBS 4XX596 SVC GNDCOM SVL GNUCOM TRACKING# 1Z4XX5969065029520 REF 1:SR00004917 REF 2: HANDLING CHARGE 0.00 SINGLE-PIECE PUB RATE CHRGS: SVC T/P USD RS 0.50 SD 0.00

1 OF 1

0.00 0.00 0.00 DV 0.00 DC 0.00 SP 0.00 DGD 12.74 AH 0.00 TOT PUB CHG 12.74 PUB+HANDLING



