

Remington Arms Co., Inc.  
Product Service  
Legal Case #:4980

## Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
		11/4/2010	11/7/2011	10/19/2010			

## Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Joseph G.	Genuardi	403 Stratford Ave.	Collegeville	PA	19426		H n/a

## Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4079 Other - Unexamined		Unknown	
S	Concern:1007 Fired on Safe Release			
C	FSR			

11/4/10: Received a letter from Consumer Service Dept. Customer wrote to Ilion about his early Model 700. Stated that he has had FSR while cleaing it. No damage - No injury. df

## Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/	20000	42529		
Date Purchased	Where Purchased	Accessories	Original Owner			
			Y			

Ammunition Information - None Defined

Other Products Information - None Defined

## Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
	Repair/Replacement Cost	Repair/Replacement Date				

11/4/10: Sending ARS, ltr, form. df 11/7/11 Not sent for inspection.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
------	----------	------	---------

4980

403 Stratford Ave.  
Collegeville, PA 19426

October 19, 2010

Customer Service  
Remington Arms Co.  
Ilion, NY 13357


To Whom it may Concern,

I purchased my Remington 700 in 1962 and am advising that on occasion it fires when moving the safety forward.

This has occurred as recently as today when cleaning the rifle. Serial number is 42529 and also has hand punched number 7RJ58.

Please advise how I may resolve this safety issue.

Yours truly,



Joseph G. Genuardi

NOV 04 2010

NOV 04 2010

Received Date: \_\_\_\_\_

CSR: \_\_\_\_\_

Response Date: \_\_\_\_\_

Response/Fee: \_\_\_\_\_

