Remington Arms Co., Inc. Product Service Legal Case #:6494

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete 238709 8/23/2011 8/24/2011 8/24/2011

Customer Information

Type Business First Name Last Name Street City State Zip Age Contact 2180 Jericho Turnpike T&T Tactical Garden City Park Reporter T&T Tactical 11040 W 516-739-2607 36 Cunningham Ave Incident Raymond Neufeld Floral Park 11001 H 516-250-2650

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PΙ

PD Cause:4015 Improper Maintenance
S Fires on bolt closing Concern:1008 Fired on Bolt Closing

Unknown

С

9/6/11 Per not with rifle, the gun accidentally is triggered upon closure of the bolt. It occurs about every 3re or fourth closing.cm

Firearm Information

Mfg. Model/Ga. SKU Serial Bbl. DOM Type Remington CF/BA 700/300 WIM MA n/a B6501283 ED 10/1/1983 Where Purchased **Date Purchased** Accessories **Original Owner** U

CONCERN: FBC

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Settlement Release Date Reimbursement Reimbursement Reimbursement Release Date Reimbursement Reimbursement Release Date Release Date Reimbursement Release Date Re

Per Ilion, can offer to replace TPA, clean and test fire at 1/2 normal cost

Repair/Replacement Cost Repair/Replacement Date

9/6/11 Per Ilion, trigger assm has a dried and sticky lube residue causing parts to bind andwork sluggish. Can offer to replace TPA, clean and test fire at 1/2 normal cost.cm 9/7/11 Spoke with rep at T&T, gave details of inspect and quote. She will contact the owner for approval.cm 9/7 Dealer called to approve and requested COD.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		8/24/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4015	Improper Maintenance	
Barrel	Description		24" 300 WIN MAG
	Date Code		ED
	Bore Plugged	False	
	Bulged	False	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=6494&Type=Case

9/7/2011

	Fired	False	1	
	Fired while Obstructed			
	Muzzle/Crown Condition	Slightly Worn; Functioning		
Bolt	Firing Pin	Slightly Worn; Functioning		
	Shroud	Slightly Worn; Functioning		
	Face	Slightly Worn; Functioning		
	Handle	Slightly Worn; Functioning		
	Stop	Slightly Worn; Functioning		
Extractor	Condition	Slightly Worn; Functioning		
	Cut Condition	Slightly Worn; Functioning		
	Ext/Eject Test	False		
Locking	Block Condition	Select		
	Lug Condition	Slightly Worn; Functioning		
	Notch Condition	Select		
Overall	Exterior Condition	Slightly Worn; Not Functioning		
	Stock Condition	Slightly Worn; Functioning		
	Fore End Condition	Select		
Receiver	Condition	Slightly Wom; Functioning		
	Bulged	False		
	Description		M/700 SAFETY	
Safety	Function	Like new; Functioning		
	Sub-Assembly	Non-ISS		
Sear	Lift	Select	N/A	
	Notch	Slightly Worn; Functioning		
		Test Fired	False	
Feeding Test	Tests	False		
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY,STICKY LUBE RESIDUE PARTS BIND,WORK SLUGGISH WILL FOLLOW DOWN	
	Pull	Select	10+#	
	Altered	False		
	Sub-Assembly	M/700 Non-Bolt Lock		

T&T Tactical 2180 Jericho Turnpike Garden City Park, NY 11040 516.739-2607 p 516-739-0852 f

241/83 E 10/83

August 18, 2011

Remington Arms Services ATTN: Repair Department 14 Hoefler Avenue Ilion, New York 13357

Dear Remington:

費B6501283 Model: 700

PE00238709

1

Enclosed please find Repair #10025 in our repair book.

The gun information is as follows:

Make: Remington

Model: 700

Serial #: 86501283 Caliber: 300 Win Mag

Repair Problem: The gun accidentally is triggered upon closure of the bolt. It occurs about every third or fourth closing and needs your prompt attention to this, as it could be deadly to the operator.

Owner: Raymond J Neufeld 516.250.2650

36 Cunningham Avenue Floral Park, NY 11001

Please repair and return to the store. It is clearly a manufacturer's defect, and possibly a problem with the trigger mechanism.

Thank you for your cooperation. Please contact our store directly should you have any questions and not the owner at 516-739-2607 Monday through Saturday 11 AM-5 PM, our email address is tntactical@vahoo.com.

Sincerely,

T.A. has a dried + sticky lube Risi dive coursing pants to bind + work shuggish.

Cena Tretola
TECTIVE

CAN often to replace 7770, e lear +

AUG 2 6 2011

BY:

BY:

T & T Tectical 2180 Jesicho Tumpike Garden City Park, NY 11040



Phone Commat 5/6/502/2/656 Centred Letter //

Sound Book Reference Number	Manufacturer/Importer	Model	Serial Number	Туре	Caliber/ Gange						
10025	Reminston	700p.	86501283	BoH	300 WIN 1	maj					
The above listed firearm(s) was left for gunsmith work on \(\frac{16}{20} \). The firearm(s) was returned to its owner on											
date is unknown, please enter the best approximate date, and indicate that it is approximate.) The owner of the firearm(s) is Roumond J Newfold, fives upon print name) Out Closure											
who resides at 30 Cunningham the or at welf (number and street)											
		TI Ora	exte and zip code),								
	(signatur	e)	(date)	· .							





