Remington Arms Co., Inc. Product Service Legal Case #:6346

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete

237697 8/11/2011 7/12/2011 8/12/2011

Customer Information

Business Last Name Street City Type First Name State Zip Age Contact 1089 Albert Dr. Incident JD Pennington Russellville 72802 H 479-968-4119 AR

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PD Shot hole in floorboard of

Cause: 4006 Altered Adjustments or Components

Concern: 1007 Fired on Safe Release

Unknown

S

C FSR

truck

7/12/11: Customer called in. He was using his rifle sometime ago on his farm & had a FSR. Shot a hole in the floorboard of his truck. No injury. He wants us to examine rifle & he is willing to pay for repair if he has to. He loves the rifle. df

Firearm Information

Mfg. Remington

Type CF/BA Model/Ga.

SKU 25783

Bbl. DOM Serial

Date Purchased

Where Purchased

700/22-250 REM

Original Owner

B6680359 2/1/1985 LF

NATIONWIDE SPTS DISTRIB18966

Accessories

Y

CONCERN: FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement

Release of Claims

Release Date

Reimbursement

Cash Settlement Reim. Date Cash Date APV APV

Per Ilion - Quote to

repair

Repair/Replacement Cost Repair/Replacement Date

7/12/11: Mailing ARS, letter, form. df 8/18/11: Per Ilion - TA dirty, rusty & set screws altered. Replace TA, clean & test fire @ 1/2 normal cost - quote. I spoke to customer & he mailed payment to us on 8/17. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		8/12/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	
Barrel	Description		24" 22-250 REM
	Date Code		LF
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
			\neg

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=6346&Type=Case

8/18/2011

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	BINDS
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Worn; Functioning	
	Notch Condition	Select	
Overall	Exterior Condition	Worn; Functioning	SCRATCHES/MARS/DENTS/RUST
	Stock Condition	Worn; Functioning	SCRATCHES/MARS/DENTS
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning]
Receiver	Bulged	False	
	Description		M/700 SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS]
	Lift	Select	.014
Sear	Notch	Slightly Worn; Functioning	DIRTY
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY,RUSTY.TRIG NOT RETURNING WILL FOLLOW DOWN
	Pull	Select	2.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Non-Bolt Lock]

24" LFZ/Q 2.5" .014

6346

July 12, 2011

JD Pennington 1089 Albert Dr. Russellville, AR 72082 Phone: 479-968-4119

Ref: #6346, Model 700, Serial #B6680359

Dear Mr. Pennington,

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination and a form.

Please include a copy of this letter and form to put inside the shipping container. The letter and form inside are important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results.

I hope that this action will keep you a loyal Remington customer.

Sincerely, Dell Fulcher

Consumer Affairs Administrator

Remington Arms Co., LLC

Phone: 1-800-243-9700 press 0 and ask for ext 8686

Fax: 336-548-7872

. 1

T.A. Lirty Justy & set screws Altered. Replace TPA, clean + leat Rine At 1/2 Normal

BY:----

COST.

Quote

B6680359

Model: 700

RE00237697

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

Print :	[Reset]					
Model Number: 7∞	Serial Number: B6680359					
Are you the original owner?: VES NO						
Name: 30 Pennington	Date of Purchase:					
Address (no PO Boxes):						
City: Russellville	State: AR	Zip: 72402				
Phone (Daytime): 식7역 - 역6% - 시11역	Fax:					
E-mail Address:(if e-mail address is provid be sent)	ed, notification of recei	pt and shipment will				
E-mail A I would like to receive future e		emington.				
Please describe your proble	m and date of occurr	ence:				
Sometimes fires when you take the satety off and hesitates to fire when you pull the trigger.						
500 cha	racters left					
Ammunition Information:						
Manufacturer: Dinchoster Type: High Velocity						
Other (i.e. bullet weight/type, shot size, powder): 15 gain SHP						
Handload Information:						
Powder Used:	Powder Weight:					
Case/Hull Used:	Primer Used:					
Bullet Type/Shot Size:	Reloader Used:					
Firearms Care (Cleaning and Lubrication):						

Brand of cleaning solution used:				
How often do you clean the bore? (Months or Number of rounds) <u>Λιε ιο νιο</u> πολη				
How often do you clean the action? (Months or Number of rounds)				
How often do you clean the trigger assembly? (Months or Number of rounds)				
Brand of lubricant used: Rem oil				
How often do you lubricate the bore? (Months or Number of rounds) οριστοία του ορι				
How often do you lubricate the action? (Months or Number of rounds) Ο η ι ο μοητή				
How often do you lubricate the trigger assembly? (Months or Number of rounds)				
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? >☑ YES ☐ NO				
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?)				
What were the services performed?)				
Ship your INSURED firearm by either UPS or Parcel Post to:				
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357				
WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.				
:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a				

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for

damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

- :: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)
- :: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:		7/12/2011	REQUESTED BY:	Dell
QUANTITY:	1		WEIGHT PER PKG:	10 lbs
PLEASE CHECK ONE MEDIA COORDINATOR TO MAIL			I WILL MAIL	XXXXX September 1
DESCRIPTION:	Ref# 6346 rifle			

LABEL INFORMATION

MAIL LABEL TO: JD Pennington

1089 Albert Dr.

Russellville, AR 72082 Phone: 479-968-4119

RETURN ITEM TC Remington Arms

Attn: Product Service

Ilion, NY

PLEASE COMPLETE ALL PARTS OF THIS FORM. AND SEND TO THE MEDIA COORDINATION

4XX596 JUL 12, 2011 ALL CURR USD 1 OF 1 SVC GNDCOM ACT NT 10.0 LBS

TRACKING# 1Z4XX5969066Z89971
REF 1:J D PENNINGTON/CD/DMF

REF 2:REF#6346/RIFLE

HANDLING CHARGE 0.00

SINGLE-PIECE PUB RATE CHRGS: SVC T/P USD COD RS 0.50 DV 0.00 0.00 SD 0.00 0.00 DC 0.00 DGD SP 0.00 AH 0.00 PR 0.00 PUB+HANDLING 10.36 TOT PUB CHG 10.36









