

Remington Arms Co., Inc.
Product Service
Legal Case #:6982

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
249003	12/2/2011	12/5/2011	12/5/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Classic Arms		Classic Arms	14796 Zane Rd	Lore City	OH	43755		W 740-432-3055
Incident		Mike	Smith	100 Country Club Ct	Terra Alta	WV	26764		W 304-789-2431

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4006	Altered Adjustments or Components		
S	Fires without touching trigger	Concern:1025	Unexplained Discharge - No Mention of Safety Position	Unknown
C				
12/15/11 Per note with rifle, gun goes off without touching trigger.cm				

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/270 WIN	n/a	A6207195	DZ	10/1/1975
Date Purchased	Where Purchased	Accessories	Original Owner			
	HORNICKS HDWE JOHNSTOWN PA	TWO PIECE BASE,RINGS,SCOPE	U			
CONCERN:GOES OFF NOT TOUCHING TRIGGER						

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, test fire at BLSM program price						
	Repair/Replacement Cost	Repair/Replacement Date				
	18.40	12/15/2011				
12/15/11 Per Ilion, trigger assm dirty, set screws altered. Replace TPA, clean, test fire at BLSM program price.cm						

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		12/5/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	
Barrel	Description		22" 270 WIN
	Date Code		DZ
	Bore Plugged	False	
	Bulged	False	

	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulgcd	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	N/A
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY.TRIG NOT RETURNING WILL FOLLOW DOWN
	Pull	---Select---	2.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE,RINGS,SCOPE

Purchase Order

227

123083

TO	Remington Arms	DATE	11-30-11
ADDRESS	Ilion N.Y.	DATE REQUIRED	
CITY, STATE, ZIP	13357	TERMS	6082
SHIP TO	CLASSIC ARMS	HOW SHIPPED	
ADDRESS	14796 Zane Road Lore City, OH 43755	REQ. NO. OR DEPT.	
CITY, STATE, ZIP	(740) 432-3055	FOR	

2211
D29/7
2.54

QUANTITY	DESCRIPTION	PRICE	UNIT
1			
2	Rem 700 BDL 270cal		
3	SeNo. AG207195		
4	w/ Scope		
5	Comp: Gun goes off with out		
6	Touching tgr.		
7			
8	Please Replace Trigger		
9	with up date.		
10			
11			
12			
13			
14			
15			

THANKS

IMPORTANT Purchase Order Number must appear on all invoices - packaging, etc. Please notify us immediately if you are unable to complete the order by date specified.	Please send _____ copies of your INVOICE with ORIGINAL BILL OF LADING. PURCHASING AGENT <i>Jim Cain</i>
--	---

RECEIVED
DEC 06 2011

BY:

Order Number: A6207195
Model: 700



RE00249003


T.A. Dinty, set screws altered.
Replace TPA, clean & test fire
under BLP for \$20.00 + ship

Quote

Jay M. Smith
100 Country Club Ct.
Terra Alta, WV 26764

November 23, 2011

Gary Chapman
14796 Zane Rd.
Lore City, OH 43755



Dear Gary,

Re: Remington 700 BDL, 270 caliber would sell for \$450.00. This gun has fired on three separate occasions without touching the trigger and is in need of repair. Please call Jay M. (Mike) Smith with any questions at 304-692-5996.

Sincerely,
Mike Smith (Jay M.)

AG 207195





