,

		F	Remington Arms C Product Servio	-				
			Legal Case #:8	177				
Case Information								
)ate Opened 12/11/2012	Date Opened(PS) 11/19/2012	Date Clo 12/27/2		l ent Date 17/2012	Pre Lit	Lit Ob	solete
Customer Informa		11/19/2012	12/2/12	012 11/	1772012			
Type Bus	iness First Na	me Last Name	Street	City	State Zi	ip Age	Conta	
Incident	Seth	Ray	3592 State Rt 9	Hickory	KY 420)51	C 270-705	-5524
ncident-Informat								· ·
	ims	C	Codes	Repair I	est. Medical	Treatment	t Medical	Status
PI Shot through	rt tricep ndow, wife's car							
PD & house	ndow, whe's car		Not Duplicate Co	meern		Y	Went to I	
S Fired with Sa C	fe on	Concern:1028 Fired	With Safe ON				surge	лу
-		d been using the rifle o						
will be yet. He sa	id that he wants to	rom the inside out per I gun checked out to see						
Firearm Informati		Tura	Model/Ga.	SKU	Serial	Bbl.	DOM	
Mfg. Remington		Туре CF/BA	700/308 WIN	85435	G7169354		19/2012 8:36:	32 AM
Date Purchased		Purchased		Original Owner	0/109334	CU 4/J	17/2012 8.30.	52 AIVI
		ORTING GOODS		Y				
CONCERN:DISC	CHARGED WITH	SAFETY ON						
Ammunition Info	rmation - None De	fined		- ··· ·				
	formation - None							
Settlement								
			Remington/700/C	CF/BA				
Settlemer	nt Rele	ease of Claims	Release Date	Reimburs	ement	Cash tlement	Reim. Date APV	Cash Date APV
To restore confi replace TA, clea								
		Replacement Cost	Repair/Replacem Date	ent				
	-	\$50	Date					
	7/12: Left VM for	ox order# 1406611. df : customer w/report info						
Examination[Ren	nington/CF/BA]	· · · · · · · · · · · · · · · · · · ·	,,					
			·····	······································		···	······································	
Part		Sub-Part		Code			Comment	
	Examiner					B.TRA	VIS	

Part	Sub-Part	Code	Comment
	Examiner]	B.TRAVIS
	Exam Date]	12/12/2012
Examination	Product Type]	RF
	Action Type]	Α
	Assigned To]	J.BALIO
Cause	4038	Could Not Duplicate Concern	· ·
	Description]	26" 308 WIN HB
	Date Code		CG

12/27/2012

ŧ

	Bore Plugged	False	
	Bulged	False	
Barrel	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Like new; Functioning	
	Firing Pin	Like new; Functioning	
	Shroud	Like new; Functioning	
Bolt	Face	Like new; Functioning	
	Handle	Like new; Functioning	
	Stop	Like new; Not Functioning	BINDS
	Condition	Like new; Functioning	
Extractor	Cut Condition	Like new; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Like new; Functioning	
	Notch Condition	Select	
	Exterior Condition	Like new; Functioning	
Overall	Stock Condition	Like new; Functioning	
	Fore End Condition	Select	
n :	Condition	Like new; Functioning	
Receiver	Bulged	False	
Safety	Description		XMP SAFETY
Jaiety	Function	Like new; Functioning	
	Lift	Select	.011
Sear	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
	Condition	Like new; Functioning	
Trigger	Pull	Select	3.5#
	Altered	False	
	Sub-Assembly	X-Mark Pro	



November 19, 2012

Seth Ray

3592 State Rt 945 Hickory, KY 42051 Phone: 270-705-5524

Ref: # 8177, Model 700, Serial # G7169354

Dear Mr. Ray,

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination. A box will arrive separately.

Please include a copy of this letter and service request to put inside the shipping container. The letter and service request inside are important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results.

I hope that this action will keep you a loyal Remington customer.

Sincerely, Dell Fulcher Consumer Affairs Administrator Remington Arms Co, LLC Phone: 336-548-8686 Fax: 336-548-7883



DI	EC	E1	تا 100 20ء2		
M	DEC	13	2012	IJ	
ВҮ:					

Remington Arms Company, LLC • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

Service Request

Remington Service PO Box 700



ATTN: Product Service

Madison, NC 27025-0700

www.Remington.com

Parts and Repairs: P:800-243-9700/F:336-548-7801 This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. PLEASE RETAIN THIS COPY FOR YOUR RECORDS.

Service Request Number	Serial Number / Description		Date of Request:	11/19/2012
SR00035484	G7169354 Model 700 RIFLE Caliber: 308		Date Printed:	11/19/2012
Customer: SETH RAY	Model 700 KIFLE Caliber: 308	Destination: Arms Services		
-3592 STATE-RT-945		14 Hoefler Ave		
HICKORY, KY 4205	1 US	Ilion, NY 1335	7 US	
Email:		Email:		
Your request for service on th returned. If not, you will be c	e item(s) will be evaluated by our repairman to determi ontacted with an estimate before work is performed.	ne if it is covered under our warranty p	oolicy. If it is your firearm	will be repaired and
Reason For Return M123 - FORWARD TO	PRODUCT SERVICE FOR INSPECTION			•
Service Request Section Product Service # 8177				
Product Service # 8177				
	:			
Parts And Service Details	· · · · · · · · · · · · · · · · · · ·			
Material Type	Description	Qty Warranty Needed	Price	Disc Amount
THIS IS NOT AN INVOICE. This is not based on the conver	This is a pre-estimate to repair, recondition, or replace station with our representative.	the item(s)	Sub Total: Est Sales Tax:	.00
			Grand Total:	\$.00

Factory Repair Form

Print	Reset				
Model Number: 700	Serial Number: G7169354				
Are you the original owner?: 🗹 YES 🗆 NO					
Name: Seth NRAY	Date of Purchase: 10-01-2012				
Address (no					
3592 STRT 945					
City: Hickory	State: Ky Zip: 4205/				
Phone (Daytime): (270) 705-5524	Fax:				
E-mail Address: (if e-mail address is provided, notification of receipt and shipment will be sent) mopar Kay 21470, Yahoo.com					
E-mail A I would like to receive future e					
Please describe your proble					
FireArm discharge w	ith sattyon				
BE And I was shot is	7 pulled nothe Arm on 11-17-2012				
500 cha	racters left				
Ammunition	nformation:				
Manufacturer: LAPUA /and REMINGTON	Type Scenar / CoreLock				
Other (i.e. bullet weig powder): 55					
Handload In	formation:				
Powder Used: Powder Weight:					
Case/Hull Used:	Primer Used:				
Bullet Type/Shot Size:	Reloader Used:				
Firearms Care (Cleanir	ng and Lubrication):				

http://www.remington.com/asp/factory_repair_form.asp

8/25/2011

Factory Repair Form

Have Not cleaned Bore

Page 2 of 3

144

After insury	
Brand of cleaning solution used: Ram oil	
How often do you clean the bore? (Months or Number of Only 95 rounds) DAECA month of the state F	rounds ired y Ford
How often do you clean the action? (Wonth's or Number of rounds) Time down The bolt when clean	n:~6
How often do you clean the trigger assembly? (Months or Number of rounds) have NOT Taken gun down the Brand of lubricant used: Renaoi'	TE fary of
Brand of lubricant used: Remoil	lubu; Rima
How often do you lubricate the bore? (Months or Number of rounds) when cleaned	
How often do you lubricate the action? (Months or Number of rounds) when cleanged	
How often do you lubricate the trigger assembly? (Months or Number of rounds) when cleaneing	
Have you reviewed the cleaning and maintenance recommendations on our web si in our owners manual? > P YES INO	ite or
When was the last time that your firearm was serviced by a Remington authorize repairman/gunsmith?) $h_{45}m_{64}$ yer	ed
What were the services performed?)	
Ship your INSURED firearm by either UPS or Parcel Post to:	
WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OF THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAN YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.	N. IF
:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and hand Preferably, ship in a firearm box. (Note: Original boxes may not be returned.)	ling.
:: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments witho proper	out a
://www.remington.com/asp/factory repair form.asp	8/25/2011

Factory Repair Form

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for

damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D.-Charges, please include your credit-card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.

http://www.remington.com/asp/factory_repair_form.asp

ARS LABEL REQUEST FORM

DATE:	11/19/2012		Service Request #	SR00035484
QUANTITY:	1		WEIGHT PER PACKAGE:	10 LBS
REQUESTED BY:	fulcherdm		email address:	I WILL MAIL LABEL
Business:		Remington Servic PO Box 700 Madison, NC 270 www.Remington	025-0700	
······		LABEL IN	FORMATION	
MAIL LABEI	_ TO:	SETH RAY 3592 STATE RT HICKORY, KY SR00035484		
		Email:		
RETURN IT	EM TO:	ILN	nga φ, α, = 192	
		Arms Services		
L		4XX596 NOV 19, 2012 SVC GNDCOM BL TRACKING# 124XX59690670 REF 1:SR00035484 REF 2:	ACT WT 10.0 LBS #PK WT 10.0 LBS 079053 All Currency US	
		DC 0.00 C		

ATTN: Product Service









