٠

1

Remington Arms Co., Inc. Product Service Legal Case #:7739

		Llegal Case h. h.	<i>.</i>				
Case Information							
RE# Date Oper				Incident Date		Lit Lit	Obsolete
272204 6/18/201	6/19/201	6/19/2012	2 6/0	5/2012			
Customer Information							
Type Business Fi	irst Name Last Nam		City		Zip A	lge Co	ntact
Incident	Des Veitch	2462 Northumbria	Dr. Sanfor	rd FL	32771	H 407-	323-2114
Incident Information							
Claims	Codes	R	epair Est.	Medical	Treatme	nt Media	al Status
PI							
PD Cause	-	olicate Concern		Un	known		
	m:1007 Fired on Safe I	Release					
C	(. 		. • • • •	0 /1 0 . 77		1 500	
Customer sent rifle in w/ gun range. He asked for			Suntain on $3/2$	23/12. He	said he ha	ad a FSR on	6/6/12 at a
							100
Firearm Information							
Mfg.	Туре	Model/Ga.	SKU	Serial	Bbl.	DOM	1
Remington	CF/BA	700/308 WIN		G711870	2 RF 11	/17/2011 11	23:32 AM
	here Purchased		inal Owner				
HENR CONCERN: FSR	Y S TACKLE LLC T	WO PIECE BASE	Y				
CONCERN. FSR							
Ammunition Information	n - None Defined						
Other Products Informat							
Settlement							
		Remington/700/CF/	ΈA				
					Cash	Reim.	Cash
Settlement	Release of Claims	Release Date	Reimburs	ement s	Cash Settlemen	t Date APV	Date APV
Per Ilion - Replace TA @ n/c - goodwill gesture							
		Repair/Replacemen	ıt				
	Cost \$51	Date					
	221			fidanca i			

6/22/12: Per Ilion - Could not duplicate concern. As a goodwill gesture to restore confidence in rifle, will replace TA, check over & test fire at n/c. df

Examination[Remington/CF/BA]

C

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
Examination	Exam Date		6/19/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE

_


,

;

Cause	4038	Could Not Duplicate Concern		
	Description		26" 308 WIN	
	Date Code		RF	
	Bore Plugged	False		
Barrel	Bulged	False		
	Fired	False		
	Fired while Obstructed			
	Muzzle/Crown Condition	Slightly Worn; Functioning		
	Firing Pin	Slightly Worn; Functioning		
	Shroud	Slightly Worn; Functioning		
Bolt	Face	Slightly Worn; Functioning		
	Handle	Slightly Worn; Functioning	_	
	Stop	Slightly Worn; Functioning		
	Condition	Slightly Worn; Functioning		
Extractor	Cut Condition	Slightly Worn; Functioning		
	Ext/Eject Test	False		
	Block Condition	Select		
Locking	Lug Condition	Slightly Worn; Functioning		
	Notch Condition	Select		
	Exterior Condition	Slightly Worn; Functioning		
Overall	Stock Condition	Stock Condition Slightly Worn; Functioning		
	Fore End Condition	Select		
	Condition	Slightly Worn; Functioning		
Receiver	Bulged	False		
	Description		XMP SAFETY	
Safety	Function	Like new; Functioning		
	Sub-Assembly	Non-ISS		
	Lift	Select	.011	
Sear	Notch	Notch Slightly Worn; Functioning		
		Test Fired	False	
Feeding Test	Tests	False		
	Condition	Slightly Worn; Functioning		
T . •	Pull	Select	4#	
Trigger	Altered	False		
	Sub-Assembly	X-Mark Pro		
Non-Remington Components	Description		TWO PIECE BASE	

.

Arms Services 14 Hoefler Ave Ilion. NY 13357 Des Veitch 2462 Northumbria Dr Sanford. FL 32771



June 10 2012 Serial numbe : G7116702

To whom it concerns,


I purchased this firearm on 3/23/12 from GanderMountain in Lake Mary, FL. I have fired approximately 200 rounds through the gun. On June 6th I was at my range and the gun discharged when I moved the trigger from SAFE to FIRE without touching the trigger. This is very disconcerning and a huge inconvenience as I am in the middle of a long range shooting course. I have invested in a BELL and Carlson stock and spent a lot of time and effort braking in the barrel and working up a hand load for my rifle. I put the original stock back on as was suggested by you.

I have used the case that came with the firearm to send it to you. PLEASE do not forget to send it back to me when you return my firearm.

I would appreciate it very much if you would expedite the inspection and return of my rifle with a detailed report of what you found.

Thank you. Veitel Des Veitch





Could not duplicate concerna AS A Good-W. A Gesture to ALS tone confidence in Rifle WM fit A New TPA, checkoven + Test at Re/C

	DERMTN	FI	REARMS SALI	E Date: 4473#: Assoc		
GM#350 - Lake Mary 3750 Flagg Lane Lake Mary, FL 32746 (407) 804-0514			Sold To: DESMOND NMN VEITCH 2462 NORTHUMBRIA DRIVE			
			SANFORD, FL 32771 (407) 323-2114			
Inventory Number	Manufacturer/Importer	Model	Туре	Caliber/Gauge	Serial Number	
047700855691	Remington Arms Co. Inc.	700	Rifle	308 Win	G7116702	
Florida Sta	tute 790.175 :					•

""IT IS UNLAWFUL, AND PUNISHABLE BY IMPRISONMENT AND FINE, FOR ANY ADULT TO STORE OR LEAVE A FIREARM IN ANY PLACE WITHIN REACH OR EASY ACCESS OF A MINOR UNDER 18 YEARS OF AGE OR TO KNOWINGLY SELL OR OTHERWISE TRANSFER OWNERSHIP OR POSSESSION OF A FIREARM TO A MINOR OR A PERSON OF UNSOUND MIND"

All new firearms purchased at Gander Mountain follow the manufacturer's warranty for a new firearm purchase. See your owner's manual for this information and remember that Gander Mountain is a warranty repair station for most firearm manufacturers. All used firearms purchased from Gander Mountain are guaranteed against defects in materials and workmanship for a period of 30 days from the date of purchase. Please save this receipt as your proof of purchase should warranty work become necessary. Accidental damage, abuse, and barrel ruptures are not covered by this guarantee.

Consistent with industry standards, ALL FIREARM SALES ARE FINAL. No refunds or exchanges can be honored. Each firearm manufacturer requires that you read their owner's manual before using.

I understand the safe method of operations, handling and care of the above firearm(s) and acknowledge receipt of above in satisfactory condition.

Signed:

Date:



