2

Washington and washing to the

and the state of the second second

F

				Remington A Product Legal Ca	Service						
Case Inform	nation										
RE# 290386	Date O 11/26/	-	Date Opened(PS 11/28/2012		ate Closes 2/13/2012		ent Date	Р	re Lit	Lit	Obsolete X
Customer Ir	formation										
Туре	Business	First Name	Last Name	Str	eet	City	State	Zip	Age	C	ontact
Incident		Ronald	Markley	1620 Ros	ecrans Di	Billings	MT	59105	-	H 40	6-256-3997
Incident Inf	ormation		-								
Cla	aims		C	odes			Repair Est.	-	Medical reatment		Medical Status
PI											
PD		Cause:4054	As received Follo								
S Acciden dischar		Concern: 1025	Unexplained Dise Position	charge - No N	Aention of	f Safety		Ŭ	inknown		
С											
12/11/12 Pe	er note on SR	, accidental dis	charge.cm								
Firearm Info	ormation										
Mfg.	,	T	pe	Model	/Ga.	SKU	Ser	ial Bb	.	D	ОМ
Reming	ton	CF	/BA	710/270	WIN	27408	71040)584 XI	J 12/3/2	001 1	1:42:26 AM
Date Purc			urchased	Access		Original Owner	r				
) CORPORATION	N SCOPE	BASE	U					
CONCERN	ACCIDEN	TAL DISCHAR	.GE								
Ammunitio	n Informatio	n - None Define	d								
Other Produ	icts Informat	tion - None Def	ined								
Settlement											
				Remington/	'710/CF/F	3A					
Settlement Release of Cla		ns Rel	ease Date	se Date Reimbu		Cas Settlen		Reim. Date APV		Cash Date APV	
Replacing 770	with						•				
	Repa	hir/Replacemen 132.00	nt Cost Repair/Re 12	eplacement I /13/2012	late						
12/13/12 Le 770 as repla		Markley to call	me. Need to see if	he is ok with	770 repla	acement.cm 12/3	13/12 Sp	oke with	Markley,	he's d	ok with the
			·····		.						

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment				
Examination	Examiner		B.TRAVIS				
	Exam Date		11/28/2012				
	Product Type		RF				
	Action Type		A				
	Assigned To		J.BALIO				
Cause	4054 As received Follows Down		DOES NOT PASS SAFETY NULL TEST. TRIG ASSM NO LONGER AVAIL. FOR REPAIR				
	Description		22" 270 WIN				
	Date Code		XU				
	Bore Plugged	False					
	Bulged	False					
	Fired	False					
	Fired while						

12/13/2012

PrintDisplay

۹ مط

	Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
Bolt	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning]
	Notch Condition	Select	
· · · · · · · · · · · · · · · · · · ·	Condition	Select]
Magazine	Box Condition	Missing	1
	Exterior Condition	Slightly Worn; Not Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
-	Bulged	False	
	Description		STANDARD SAFETY
Safety	Function	Like new; Functioning]
	Sub-Assembly	ISS	
	Lift	Select	N/A
Sear	Notch	Slightly Worn; Functioning	
L		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	WILL FOLLOW DOWN FROM NULL TEST
	Pull	Select	4.5#
	Altered	False]
	Sub-Assembly	Other Remington	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID = 8215&Type = Case

12/13/2012

Service Request

Remington Service PO Box 700

Madison, NC 27025-0700

z2 Parts and Repairs: P:800-243-9700/F:336-548-7801 www.remington.com This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information XU12, will carry as a multiplication for our Service. This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This mean and will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT 4 c WITH YOUR RETURN. Date of Request: 11/08/2012 Service Request Number Serial Number / Description 826 SR00034355 71040584 Date Printed: 11/08/2012 LE-Caliber: 270 Destination: Customer: RONALD MARKLE Arms Services 14 Hoefler Ave 1620 ROSECRANS DRIVE Ilion, NY 13357 US BILLIGS, MT 59105 US Email: Email: Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed. **Reason For Return** M240 - BOLT LOCK SAFETY MODIFICATION Service Request Section Accidental discharge. 11/8 drs Parts And Service Details Material Type Description Qty Warranty Price Disc Amount Needed BY:----Dend this in a hardcase as I have no other way to ship, Please return if passible Thinks m Markel 歸71040584 Model: the item(s) Sub Total: .00 .00 Est Sales Tax: いノイハ \$.00 Grand Total: