Remington Arms Co., Inc.
Product Service
Legal Case #:8086

Case Informa	ation			2562 5434							
RE# Date Opened 286984 10/25/2012		Date Opened(PS) 10/26/2012		Date Closed 11/16/2012		Incident Date		Pre Li	t Lit	Obsolete	
Customer Int	formation										
Type 1	Business	First Name	Last Name	Street	City	State	Zip	Age		Cont	act
Incident		Weldon	Reedy	3660 Birch St	Baker City	OR	97814			H 541-51 541-519-3	9-9897 704, Kathy
Incident Info	mation				-		-				
Clair	ms		C	odes :		Repair	r Est.	Medica	l Treat	ment M	ledical Status
<u>PL</u>				rified or Undeterm						 ·	
PD Final wi	al cofot.	Cause:4040	Unknown								
s on	on Concern: 1005									Firearms Unexplained Discharge Safe ON	
C	•			n 2009 it immedia							., ,
he chambered bolt forward	d the 1st ro to chambe	und and fired	then the 2nd and I and the rifle dis	to sight in it malfu fired, adjusted the charged 10 ft in fr	scope and ejec	ted the e	mpty ca	sing ou	it of the	rifle and	firmly slid th
Firearm Info	rmation										
Mfg.		Type		Model/Ga.		SKU	5	Serial	Bbl.	1	OOM
Remingto	mington CF/BA 770/243 WIN		70/243 WIN	85637 7147					8/13/200	8 9:07:10 AM	
Date Purch		ere Purchase		Accessories	_	nal Ow	ner				
CONCERN:		-MART #711 HILE CLOSIN	SCOPE,RIN G BOLT WITH	GS,BASE,EXTRA SAFETY ON	MAG	U					
								Terri i stima i consti		the contract to the second	de se :
		on - None Defi									
	ets informa	tion - None D	erined								
Settlement				Remington/7	70/CF/BA						
Settlemen	t F	Release of Clai	ms	Release Date	Reimbur	sement		Cash tlemen		Reim. Dat APV	te Cash Date APV
Refunding for rifle					379.00				1	1/16/201	2
IIIC	Repa	ir/Replaceme	nt Cost Repair	-/Replacement Da	ıte						
call regarding where she pu	offer to reg the receip rchased an	place with a 70 of of price paid of they had the	00 SPS or refund. I left a voice m purchase date lis	cm 11/14/12 Spok sge for Kathy with sted as Sept 25, 20 etail for 2008 and	te with Mr. Ree my fax, email 08 however not	and photon	ne numi e. The o	ber.cm dealer to	11/16/1 old her	2 Kathy o	alled Bi-Mar
Examination	(Remingto	n/CF/BA]						/\/	16 5	Sent.	rigned
								= /	7	, (- Lo
Part		-Part	Code		AVIC		Con	≖ 6	408	10	T.Kin
	Examine				LAVIS			_			
Examination	Exam Da				5/2012			= .			
				RF				=			
	Action T			A T NA	AGLE			=			
			her - Unspecified			DENICI	PICIT	EOL	OWEL	DOWN	WITH
Cause	4040		ner - Unspecifie ndetermined - Fir		DURING INSP. AT BENCH RIFLE FOLLOWED DOWN WITH SAFETY ON AND WOULD FAIL THE SAFETY NULL TEST.						
	Description		20" 243 WIN								
	Date Cod			wc							
1	n 2 2 3 3	- [10							

PrintDisplay Page 2 of 2

1	Done Diversed	False	1
Barrel	Bore Plugged		4
	Bulged	False	<u></u>
	Fired	False	<u> </u>
	Fired while Obstructed		_
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt.	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	<u>]</u>
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	7
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	7
Locking	Block Condition	Select	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	Ī
	Condition	Select	7
Magazine	Box Condition	Slightly Worn; Functioning	2 - MAGS
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	7
	Fore End Condition	Select	7
	Condition	Slightly Worn; Functioning	7
Receiver	Bulged	False	
	Description		STANDARD SAFETY
Safety	Function	Like new; Not Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	Select	N/A
	Notch	Slightly Wom; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	WILL FOLLOW DOWN WITH SAFETY ON
	Pull	Select	4.5#
	Altered	False	
	Sub-Assembly	Other Remington	7

70" 4.5" wc86

October 14, 2012

8086

ATTN: Remington Arm Service Department

After we purchased this rifle it immediately malfunctioned, the first time it was fired. On 8/5/2009, we being lifetime Remington firearm owners knew that we could send it back to the manufacturer and it would be replaced or repaired we could count on it. We sent it back to on August 5, 2009 we have not used this rifle it has been in a gun safe, until 10/1/2012 when a family member wanted to use it for hunting season. When we all went out to sight in our rifles for the 2012 deer season, it malfunctioned again almost killing a family member who was standing off to the side not down range, When I loaded a magazine with newly purchased Remington .243 Win/powerlokt ammo. With the rifle pointing down range safely, I chambered the first round and fired then the second round and fired, adjusted my scope and ejected the empty casing out of the rifle and firmly slide the bolt forward to chamber the 3rd round the rifle discharged 10 ft in front of me, my finger was not on the trigger and the safety was on. I hadn't even locked the bolt down, it scared us so bad especially the family member that had the round hit 2 ft in front of him.

I am a retired law enforcement officer of 24 years and a range master who is currently selling 17 Remington brand firearms you need to make this right. I do NOT want your Remington Firearm back for the 3rd time. You need to send me a check back or a gift card for the value of this rifle combination Bushnell 3X9 scope-black.

You should know all of this was video taped by myself with a video recorder on a tripod with 5 witnesses. Who are also selling there remingtons.

We are all lucky that I follow the range rules and have had extensive law enforcement firearms training. Or this may not have ended with just this letter and the replacement of this firearm.

Weldon & Kathy Reedy 3660 Birch St Baker City OR 97814 541-519-3704

Phone 541-519-9897

DECEIVE) L (CT 3 1 20,2

BY: -----

71472180 /Model: 770 RE00286984









