

Remington Arms Co., Inc.
Product Service
Legal Case #:6936

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
255898	1/25/2012	11/29/2011	2/3/2012	11/26/2011			

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Nickey	Chaisson	837 Ave G	Westwego	LA	70094		C 504-416-4088 F 504-826-1176 E snapper.head@cox.net

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD Shot a hole in truck door	Cause:4038 Could Not Duplicate Concern			Unknown
S	Concern:1007 Fired on Safe Release			
C FSR				

11/29/11: Cusotmer called in. He stated that he was using rifle on 11/26/11 & it had a FSR & shot a hole in his truck door. He did not ask refund on truck damage. He bought gun used from a friend & has never had a problem for years. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPRG	n/a	6448782	PU	6/1/1971
Date Purchased	Where Purchased	Accessories	Original Owner			
	M W DIST CHARLESTON W VA		N			

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replace TA, clean & test fire @ n/c - goodwill gesture						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$66					

11/29/11: Mailing ARS & forms. Box order# 1276400. df 2/3/12: Spoke to customer. We agreed to replace TA, clean & test fire @ n/c - goodwill gesture. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/26/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 3006 SPRG
	Date Code		PU
	Bore Plugged	False	
	Bulged	False	
	Fired	False	

	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.010
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	---Select---	5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	

6936

2211
pub
5.5
011
COPY

November 29, 2011

Mickey Chaisson
837 Ave G
Westwego, LA 70094
Phone: 504-416-4088

Ref: # 6936, Model 700, Serial # 6448782

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination and service request. A box will arrive separately.

Please include a copy of this letter and service request to put inside the shipping container. The letter and service request inside are important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results. I will contact you once I get the report.

I hope this action will keep you a loyal Remington customer.

Sincerely,
Dell Fulcher
Consumer Affairs Administrator
Remington Arms Co., LLC
Phone: 1-800-243-9700 press 0 and ask for ext 8686
Fax: 336-548-7872

enclosure

Serial Number:

6448782

Model: 700



RE00255898

RECEIVED
JAN 30 2012
BY: _____

Remington Arms Company, LLC • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025
Phone 800-243-9700 • www.remington.com

PS 27185

Service Request

Remington Service
PO Box 700

Madison, NC 27025-0700



ATTN: Product Service

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. **ENCLOSE THIS DOCUMENT WITH YOUR RETURN.**

Service Request Number SR00005129	Serial Number / Description 6448782 Model 700 Center Fire Caliber: 3006	Date of Request: 11/29/2011 Date Printed: 11/29/2011
Customer: MICKEY CHAISSON 837 AVE G WESTWEGO, LA 70094 US Email:	Destination: Arms Services 14 Hoeffer Ave Ilion, NY 13357 US Email:	

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return
M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION

Service Request Section
Product Service # 6936 - FSR

Parts And Service Details							
Material	Type	Description	Qty Needed	Warranty	Price	Disc	Amount

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.

Sub Total: .00
Est Sales Tax: .00

Print

Reset

Model Number: <u>700</u>		Serial Number: <u>6448782</u>	
Are you the original owner?: <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO			
Name: <u>Nickey Chaisson</u>		Date of Purchase: <u>8/2001 (Approx.)</u>	
Address (no PO Boxes): <u>837 AVE G</u>			
City: <u>Westwego</u>		State: <u>LA</u>	Zip: <u>70094</u>
Phone (Daytime): <u>504-416-4088</u>		Fax: <u>504-826-1176</u>	
E-mail Address: (if e-mail address is provided, notification of receipt and shipment will be sent) <u>SNAPPER.HEAD@COX.NET</u>			
E-mail Address: <input checked="" type="checkbox"/> I would like to receive future e-mail updates from Remington.			
Please describe your problem and date of occurrence: <u>11-26-11</u> <u>RIFLE FIRED when SAfty</u> <u>WAS disengaged To unload</u> <u>RIFLE</u>			
500 characters left			
Ammunition Information:			
Manufacturer: <u>Remington</u>		Type: <u>PSP core LOKT</u>	
Other (i.e. bullet weight/type, shot size, powder): <u>150 GRAIN</u>			
Handload Information:			
Powder Used:		Powder Weight:	
Case/Hull Used:		Primer Used:	
Bullet Type/Shot Size:		Reloader Used:	
Firearms Care (Cleaning and Lubrication):			

Brand of cleaning solution used:
How often do you clean the bore? (Months or Number of rounds) <u>3 to 6 months</u>
How often do you clean the action? (Months or Number of rounds) <u>3 to 6 months</u>
How often do you clean the trigger assembly? (Months or Number of rounds) <u>3 to 6 months</u>
Brand of lubricant used: <u>Hoppe's</u>
How often do you lubricate the bore? (Months or Number of rounds) <u>3 to 6 months</u>
How often do you lubricate the action? (Months or Number of rounds) <u>3 to 6 months</u>
How often do you lubricate the trigger assembly? (Months or Number of rounds) <u>6 months</u>
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? > <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith? <u>N/A</u>
What were the services performed? <u>N/A</u>
Ship your INSURED firearm by either UPS or Parcel Post to:
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357
<input type="checkbox"/> WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM. :: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.

ARS LABEL REQUEST FORM

DATE: 11/29/2011	Service Request # SR00005129
QUANTITY: 1	WEIGHT PER PACKAGE: 10 LBS
REQUESTED BY: fulcherdm	email address: I WILL MAIL LABEL

Business:	Remington Service PO Box 700 Madison, NC 27025-0700 www.Remington.com
------------------	---

LABEL INFORMATION

MAIL LABEL TO:	MICKEY CHAISSON 837 AVE G WESTWEGO, LA 70094 US SR00005129 Email:
RETURN ITEM TO:	ILN Arms Services



4XX596 NOV 29, 2011 ALL CURR USD 1 OF 1
 SVC GNDCOM ACT WT 10.0 LBS
 TRACKING# 1Z4XX5969065609760
 REF 1:SR00005129
 REF 2:

HANDLING CHARGE 0.00		SVC T/P USD
SINGLE-PIECE PUB RATE CHRG:		RS 0.50
DY 0.00	COD 0.00	SD 0.00
DC 0.00	DGD 0.00	SP 0.00
AH 0.00	PR 0.00	
TOT PUB CHG 10.27	PUB+HANDLING	10.27

ATTN: Product Service







