

Remington Arms Co., Inc.
Product Service
Legal Case #:7876

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
279447	8/20/2012	8/22/2012	8/22/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Crown Enterprises		Crown Enterpris	145 Hutton Ranch Rd	Kalispell	MT	59901		W 406-758-7417
Incident		Ronald Keith	Rash	108 Valley View Ct	Kalispell	MT	59901		H 406-755-4364

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4015 Improper Maintenance			
S	Has misfired twice	Concern:1025 Unexplained Discharge - No Mention of Safety Position	Unknown	
C				
9/6/12 Per note sent with rifle, repair faulty safety under recall. Has misfired twice.cm				

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPRG	n/a	6550014	CW	4/1/1972
Date Purchased	Where Purchased	Accessories	Original Owner			
	MONTANA HDW GT FALLS MONT	SCOPE,RINGS,TWO PIECE BASE	U			

CONCERN:MISFIRED TWICE

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replace TPA, clean, test at BLSM price						
	Repair/Replacement Cost	Repair/Replacement Date				
	30.40	9/6/2012				

9/6/12 Per Ilion, trigger assm very dirty and rusty causing parts to work sluggish. Replace TPA, clean, test at BLSM price.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		8/22/2012

Examination	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4015	Improper Maintenance	
	Description		22" 3006 SPRG
	Date Code		CW
	Bore Plugged	False	
	Bulged	False	
Barrel	Fired	False	
	Fired while Obstructed		
Bolt	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Worn; Functioning	METAL DIRTY,RUSTY.
	Stock Condition	Worn; Functioning	STK HAS BEEN BEDDED WITH AN EXCESSIVE AMOUNT OF BEDING MATERIAL
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	N/A
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	Tests	False	
	Condition	Worn; Not	VERY DIRTY,RUSTY.PARTS WORK SLUGGISH

Trigger		Functioning	WILL FOLLOW DOWN
	Pull	--Select--	5#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		SCOPE,RINGS,TWO PIECE BASE

Return to Remington for safety recall

22"
CW4/12
5#

34700



7876

FIREARM ACTIVITY FORM

☐ TRADE

SERIAL 6550014

☐ TEMP STORAGE

MAKE Remington

☐ EXCHANGE

MODEL 700

☒ CUSTOMER WAITINGS

CALIBER 30-06 BARREL 22

☐ CUSTOMER WAITINGS PICK UP

☐ STORE STOCK RTV

REASON return to Remington to repair

☐ RETURN (DEFECTIVE)

ACCESSORIES Faulty safety under recall
Has misfired twice

☐ RETURN

☐ CONSIGNMENT

TRADE ALLOWANCE

☐ CONSIGNMENT RECOVERY

with Bushnell Sportview 4X32 Scope

VENDOR (CUSTOMER) INFORMATION:

LAST NAME:

Rash

FIRST NAME:

Ronald

MIDDLE NAME:

Keith

PHYSICAL ADDRESS:

108 Valley View Ct

CITY:

Kalispell

STATE MT ZIP

59901

CONTACT PHONE NUMBER

(406) 755-4364

PHOTO ID #:

MT DL (REDACTED) 74110

EXPIRES:

06/10/2016

VENDOR/CUSTOMER SIGNATURE:

Ronald Rash

DATE:

8-11-12

SALES ASSOCIATE SIGNATURE:

Joe Rudolph

DATE:

08/11/2012

RECEIVED
AUG 27 2012

STOCK#

RETAIL:

ACTIVITY FORM COMPLETELY!!!

T.A. very dirty + rusty causing parts
to work sluggish. Replace TPA, clean +
Test under BCP Run 820. +

Q

6550014

Model: 700

BY: _____



RE00279447







