

Remington Arms Co., Inc.
Product Service
Legal Case #:7565

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
265527	4/24/2012	4/10/2012	4/25/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Matthew	Farmerie	14158 Lambert Rd	Whittier	CA	90605		H 949-290-9902

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4015 Improper Maintenance			
S	Fired on it's own Concern:1025 Unexplained Discharge - No Mention of Safety Position		Unknown	
C				

4/10/12 Per call from Farmerie, he has a 700 that he bought 2nd hand and he had opened it to make sure it was unloaded and then set it against the counter and he heard the hammer drop.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPRG	n/a	6816546	LZ	2/1/1975
Date Purchased	Where Purchased	Accessories	Original Owner			
	MUNSON SPG GDS COSTA MESA CAL		N			

CONCERN:HAMMER DROPPED WHILE NOT HELD

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, test at BLSM price						
	Repair/Replacement Cost	Repair/Replacement Date				
	30.40	5/4/2012				

4/10/12 Mailing ARS.cm 5/4/12 Per Ilion, trigger assm dirty and sticky, parts bind and work sluggish. Replace TPA, clean, test at BLSM price.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		4/25/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4015	Improper Maintenance	
Barrel	Description		22" 3006 SPRG
	Date Code		LZ
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while		

	Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Not Functioning	BINDS
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	SLOPPY AFT MKT RECOIL PAD FIT
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.007
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	VERY DIRTY AND STICKY PARTS BIND AND WORK SLUGGISH WILL FOLLOW DOWN
	Pull	---Select---	10+#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	

frmREInquiry - Repair Inquiry

Repair Number: RE00265527

Serial: 6816546 Model 700 Center Fire Caliber: 30-06 SPRG

Repayment:

Verify Repair

Status: New 4/10/2012 2:41:23 PM

ADDRESS INFORMATION

Customer

Received from

Return To

Received from

Name: MATTHEW FARMERIE

MATTHEW FARMERIE

Address 1: 14158 LAMBERT RD

14158 LAMBERT RD

Address 2: PO Box:

PO Box:

City: WHITTIER

WHITTIER

State: CA Zip Code: 90605 Country: US

CA Zip Code: 90605 Country: US

FFL:

01011900

Contact / Condition Problems Estimate History / Status Shipping / Billing

Problems Reported

Code	Desc
M123	FORWARD TO PRODUCT SE...

Repair Notes

Repairman's Comments

T.A. dirty & sticky parts bind & work sluggish. No trace JDA, clean & test under BCP Ron & 20. +
Awoke

Problems Found

Code	Desc
------	------

CSR Comments


Hammer dropped when not being held cm

Refresh

Close

6816546

Model: 700



RE00265527

BY:

APR 26 2012

Wednesday, Apr 25 2012 12:45:11 PM

5:13:47

Wednesday, Apr 25 2012

3:13 AM

22"
L22/75
104#
1007

ARS LABEL REQUEST FORM

DATE:	04/10/2012	Service Request #	SR00017146
QUANTITY:	1	WEIGHT PER PACKAGE:	10 LBS
REQUESTED BY:	mitchelcs	email address:	Christy.Mitchell@remington.com

Business:

Remington Service
PO Box 700
Madison, NC 27025-0700
www.Remington.com

LABEL INFORMATION

MAIL LABEL TO:

MATTHEW FARMERIE
14158 LAMBERT RD
WHITTIER, CA 90605 US
SR00017146

Email: Christy

RETURN ITEM TO:

ILN

Arms Services



ATTN: Product Serv # 7565





