

Remington Arms Co., Inc.  
Product Service  
Legal Case #:7644

## Case Information

| RE#    | Date Opened | Date Opened(PS) | Date Closed | Incident Date | Pre Lit | Lit | Obsolete |
|--------|-------------|-----------------|-------------|---------------|---------|-----|----------|
| 266685 | 5/7/2012    | 5/8/2012        | 5/8/2012    |               |         |     |          |

## Customer Information

| Type     | Business                      | First Name | Last Name       | Street         | City         | State | Zip   | Age | Contact        |
|----------|-------------------------------|------------|-----------------|----------------|--------------|-------|-------|-----|----------------|
| Reporter | Frank's Gun & Tackle Shop Inc |            | Frank's Gun & T | 3549 St Hwy 30 | Gloversville | NY    | 12078 |     | W 518-883-5053 |

## Incident Information

| Claims | Codes                   | Repair Est.                 | Medical Treatment     | Medical Status |
|--------|-------------------------|-----------------------------|-----------------------|----------------|
| PI     |                         |                             |                       |                |
| PD     | Cause:4038              | Could Not Duplicate Concern |                       | Unknown        |
| S      | Fired when closing bolt | Concern:1008                | Fired on Bolt Closing |                |
| C      |                         |                             |                       |                |

5/18/12 Per letter with rifle, the customer said he closed the bolt on an unloaded gun and the gun fired off.cm

## Firearm Information

| Mfg.           | Type               | Model/Ga.      | SKU            | Serial   | Bbl. | DOM                  |
|----------------|--------------------|----------------|----------------|----------|------|----------------------|
| Remington      | CF/BA              | 700/7MM RUM    | 26283          | E6719443 | LV   | 2/1/2001 11:13:05 AM |
| Date Purchased | Where Purchased    | Accessories    | Original Owner |          |      |                      |
|                | PRICES CREEK STORE | TWO PIECE BASE | U              |          |      |                      |

CONCERN:FBC

Ammunition Information - None Defined

Other Products Information - None Defined

## Settlement

Remington/700/CF/BA

| Settlement                                               | Release of Claims | Release Date | Reimbursement | Cash Settlement | Reim. Date APV | Cash Date APV |
|----------------------------------------------------------|-------------------|--------------|---------------|-----------------|----------------|---------------|
| Can offer to replace TPA, clean, test at 1/2 normal cost |                   |              |               |                 |                |               |

| Repair/Replacement Cost | Repair/Replacement Date |
|-------------------------|-------------------------|
| 49.81                   | 5/18/2012               |

5/18/12 Per Ilion, set screws altered. Could not duplicate concern. Can offer to replace TPA, clean, test at 1/2 normal cost.cm

## Examination[Remington/CF/BA]

| Part        | Sub-Part     | Code | Comment  |
|-------------|--------------|------|----------|
| Examination | Examiner     |      | B.TRAVIS |
|             | Exam Date    |      | 5/8/2012 |
|             | Product Type |      | RF       |
|             | Action Type  |      | A        |
|             | Assigned To  |      | T.NAGLE  |

|                          |                        |                             |                    |
|--------------------------|------------------------|-----------------------------|--------------------|
| Cause                    | 4038                   | Could Not Duplicate Concern |                    |
| Barrel                   | Description            |                             | 26" 7MM RUM MB     |
|                          | Date Code              |                             | LV                 |
|                          | Bore Plugged           | False                       |                    |
|                          | Bulged                 | False                       |                    |
|                          | Fired                  | False                       |                    |
|                          | Fired while Obstructed |                             |                    |
|                          | Muzzle/Crown Condition | Slightly Worn; Functioning  |                    |
| Bolt                     | Firing Pin             | Slightly Worn; Functioning  |                    |
|                          | Shroud                 | Slightly Worn; Functioning  |                    |
|                          | Face                   | Slightly Worn; Functioning  |                    |
|                          | Handle                 | Slightly Worn; Functioning  |                    |
|                          | Stop                   | Slightly Worn; Functioning  |                    |
| Extractor                | Condition              | Slightly Worn; Functioning  |                    |
|                          | Cut Condition          | Slightly Worn; Functioning  |                    |
|                          | Ext/Eject Test         | False                       |                    |
| Locking                  | Block Condition        | ---Select---                |                    |
|                          | Lug Condition          | Slightly Worn; Functioning  |                    |
|                          | Notch Condition        | ---Select---                |                    |
| Overall                  | Exterior Condition     | Slightly Worn; Functioning  |                    |
|                          | Stock Condition        | Slightly Worn; Functioning  |                    |
|                          | Fore End Condition     | ---Select---                |                    |
| Receiver                 | Condition              | Slightly Worn; Functioning  |                    |
|                          | Bulged                 | False                       |                    |
| Safety                   | Description            |                             | M/700 SAFETY -     |
|                          | Function               | Like new; Functioning       |                    |
|                          | Sub-Assembly           | ISS                         |                    |
| Sear                     | Lift                   | ---Select---                | .015               |
|                          | Notch                  | Slightly Worn; Functioning  |                    |
|                          | Tests                  | Test Fired                  | False              |
| Feeding Test             |                        | False                       |                    |
| Trigger                  | Condition              | Slightly Worn; Functioning  |                    |
|                          | Pull                   | ---Select---                | 3.5#               |
|                          | Altered                | True                        | SET SCREWS ALTERED |
|                          | Sub-Assembly           | M/700 Non-Bolt Lock         |                    |
| Non-Remington Components | Description            |                             | TWO PIECE BASE     |



"Areas Foremost Outfitter"  
3549 St. Hwy. 30, Gloversville, NY 12078  
518-883-5053  
franksgunshop@frontiernet.net

26"  
LV 2/01  
3.5#  
015

ENCLOSED you will find a Remington  
700 LH SER# E6719443.

AS PER CUSTOMER, SAID he CLOSED the  
bolt on a UNLOADED gun AND the gun  
FIRED OFF. CAN you check this out,  
EASE the customer's mind.

Thank you  
FRANK.

Serial  
Number:

E6719443

Model: 700



RE00266685

RECEIVED  
MAY 15 2012

BY:.....

set screws altered  
could not duplicate concern  
can offer to replace TPA, clean  
+ TEST AT 1/2 normal cost.

Quote





