

Remington Arms Co., Inc.
Product Service
Legal Case #:8348

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
292660	12/12/2012	12/13/2012	1/6/2013				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Gander Mtn.	--	Gander Mtn.	3602 S. Hwy 41	Terre Haute	IN	47802		W 812-237-0940

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD Shot in house	Cause:4038 Could Not Duplicate Concern		Unknown	
S FBO	Concern:1020 Fired on Bolt Opening			
C				

Gander Mtn sent gun in for consumer. Consumer stated gun is firing when the bolt is being opened, shot in house, consumer not happy, very concerned, consumer mentioned a possible recall on this firearm. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPRG	n/a	A6625462	PQ	6/22/1978
Date Purchased	Where Purchased	Accessories	Original Owner			
	TG/Y STORES CO OKLA CITY OK	SCOPE,SEE THRU RINGS.TWO PIECE BASE,SLING	U			

CONCERN: FBO.SHOT IN HOUSE

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replace TA, clean & test fire @ n/c - goodwill gesture						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$50					

1/6/13: As a gesture of goodwill - replace TA, clean & test fire at n/c. No recall on firearm. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		12/13/2012
	Product Type		RF
	Action Type		A
	Assigned To		J.BALIO
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 3006 SPRG
	Date Code		PQ
	Bore Plugged	False	
	Bulged	False	
	Fired	False	

	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	TOP SCOPE CAP MISSING WHEN REC'D
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	N/A
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY
	Pull	---Select---	6#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		SCOPE,SEE THRU RINGS.TWO PIECE BASE,SLING



Service Request

Service Order # 4074

22"
PQ 6/78
L#

8.3.48

SHIPPED TO VENDOR/STORE:

Remington Repair FFL# 6-16-00726
14 Hoefler Ave

Ilion, NY 13357

Attn:

Date Shipped: 12/06/2012

Phone: (888) 888-8888

RETURN SHIP TO:

Gander Mountain, FFL# 4-35-167-01-4B-01794
Attn: Gun Parts Dept.
3602 S. Hwy 41
Terre Haute, IN 47802

FIREARM INFORMATION:

Manufacturer: Remington

Model: 700

Type: Rifle

Cal/Ga.: .30-06cal

Serial Number: A6625462

Cased?: ☐

DESCRIPTION OF ITEM RETURNED:

scoped remington 700 with sling

REASON FOR RETURN:

Gun is firing when bolt is being opened. Shot in house, customer not happy. Very concerned. Customer mention a possible recall on this firearm

ATTENTION VENDOR

Please contact me with any questions or concerns.

(812) 237-0940

BILLING INFORMATION:

Please include the service order number on all invoices and correspondence:

SHIP TO ABOVE ADDRESS

Forward all invoices to: **Gander Mountain**
Attn: Roy Christensen
6801 120th Ave
Kenosha, WI 53140

RECEIVED
DEC 19 2012

BY: _____

Serial
Number:

A6625462

Model: 700



RE00292660

Gunsmith SO# 4074

GM#270 - Gander Mountain
3602 S. Hwy 41
Terre Haute, IN 47802
(812) 237-0940
Gunsmith:



* Transferred Status *

CUSTOMER INFORMATION:	
Home #:	(812) 448-2699 Day #:
Name:	brannan, robert
Address:	11668 N county road 300 w
	brazil, IN 47834

DATES:	
Acquired:	11/29/2012
Apx Comp:	
Completed:	
Cust. Called:	
Disposed:	

FIREARM INFORMATION:			
Manufacturer:	Remington	Type:	Rifle
Model:	700	Cal/Ga.:	.30-06cal
		Serial Number:	A6625462
		Firearm Value:	\$0.00
		Cased?:	<input type="checkbox"/>

Description: scoped remington 700

Condition: good

Service Description: Gun is firing when bolt is being opened. Shot in house, customer not happy. Very concerned

Customer mentioned a possible recall on this firearm.

LABOR		
UPC	Description	Amount
Labor Sub Total:		\$0.00

Labor Notes:

PARTS		
UPC	Description	Amount
Parts Sub Total:		\$0.00

Parts Notes:

* Notice* ID is required when picking up a firearm.	TOTALS	
	Labor Sub Total:	\$0.00
	+ Parts Sub Total:	\$0.00
	Total:	\$0.00
	- Deposit Amount:	\$0.00
Amount Due:		\$0.00

* Does not include Sales Tax *

The Child Safety Lock Act of 2005 states "it is unlawful for a dealer to sell, deliver, or transfer any handgun to any person, other than another licensee, unless the transferee (buyer) is provided with a secure gun storage or safety device for that handgun." Gander Mtn. will be providing trigger locks to all transferee's (buyer's) for a nominal fee. Transferee's may also supply their own secure gun storage or safety device.

SIGNATURE: _____

DATE: _____







