Remington Arms Co., Inc. Product Service Legal Case #:8851

Legal Case #:8851 Case Information Obsolete RE# **Date Opened** Date Opened(PS) **Date Closed** Incident Date Pre Lit Lit 4/26/2013 4/26/2013 309019 4/25/2013 Customer Information Business First Name Last Name Street Contact Type City State Zip Age 3500 Market Place Circle, Ste B W 231-929-5590 Reporter Gander Mt Gander Mt Traverse City MI 49684 Incident Information Claims Codes Repair Est. Medical Treatment Medical Status ΡI PD Cause:4038 Could Not Duplicate Concern Unknown S Fired when safety was moved Concern: 1007 Fired on Safe Release 5/1/13 Per note with rifle, gun went off when safety was moved.cm Firearm Information Model/Ga. Type SKU Serial Bbl. DOM Mfg. Remington CF/BA 700/7MM REM MA n/a 6869465 PZ 6/4/1975 **Date Purchased** Where Purchased Accessories Original Owner WALLS GEN STORE BLAIRSTOWN MO U CONCERN: FSR Ammunition Information - None Defined Other Products Information - None Defined Settlement Remington/700/CF/BA Cash Reim. Cash Settlement Release of Claims Release Date Reimbursement Date APV Date APV Settlement Per Ilion, replace TPA, clean and test at BLSM program price Repair/Replacement Repair/Replacement Cost Date 29.04 5/1/2013 5/1/13 Per Ilion, could not duplicate concern. Trigger assm dirty and sticky causing parts to work sluggish. Replace TPA, clean and test at BLSM program price.cm Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		4/26/2013
	Product Type		RF
	Action Type		Α
	Assigned To		S.NICHOLS
Cause	4015	Improper Maintenance	
Barrel	Description		24" 7MM REM MAG
	Date Code		PZ
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=8851&Type=Case

5/1/2013

	Firing Pin	Slightly Worn; Functioning	1
Bolt Extractor	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Not Functioning	BINDS
	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overali	Stock Condition	Slightly Worn; Functioning	HAS BEEN REFINISHED
Receiver	Fore End Condition	Select	
	Condition	Slightly Worn; Functioning	
	Bulged	False	
	Description		BOLT LOCK SAFETY
Safety Scar	Function	Like new; Functioning	
	Lift	Select	.009
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	1 6212	False	
	Condition	Slightly Worn; Functioning	DIRTY,STICKY LUBE RESIDUE
Trigger	Pull	Select	2.5#
	Altered	False	SEALANT PRESANT
	Sub-Assembly	M/700 Bolt Lock	



Service Request

24"

Service Order #8201

SHIPPED TO VENDOR/STORE:

Remington Repair FFL# 6-16-00726 14 Hoefler Ave

Ilion, NY 13357

Attn:

Date Shipped: 04/20/2013

Phone: (800) 243-9700

RETURN SHIP TO:

Gander Mountain, FFL# 4-38-055-01-7B-02234

Attn: Gun Parts Dept.

3500 Market Place Circle Ste B

Traverse City, MI 49684

FIREARM INFORMATION:

Manufacturer: Remington Arms Co Inc.

Type:

Serial Number: 6869465

Cal/Ga.: 7MM MAG

Cased?: □

Model: 700

DESCRIPTION OF ITEM RETURNED:

COMPLETE FIREARM

REASON FOR RETURN:

GUN WENT OFF WHEN SAFETY WAS MOVED DO SAFETY RECALL

ATTENTION VENDOR

Please contact me with any questions or concerns.

MICHAEL ROBINSON (231) 929-5590

BILLING INFORMATION:

Please include the service order number on all invoices and correspondence:

SHIP TO ABOVE ADDRESS

Forward all invoices to:

Gander Mountain (262-857-3757)

Attn:HOLLY FRENCH **6801 120TH STREET**

KENOSHA , WISCONSIN 53140

BY:----

6869465 Model:

could not dup CONCERN T.A. dipty esticky incusing parts to world sluggish. Rep. TPA clean + tost und BLP Con 20+







