٨

Remington Arms Co., Inc. Product Service Legal Case #:9604

.it Obsolete Contact 8-982-1464 8-383-4632 E n@gmail.com
'ontact 8-982-1464 8-383-4632 E
8-982-1464 3-383-4632 E
8-982-1464 3-383-4632 E
8-982-1464 3-383-4632 E
8-383-4632 E
Е
Iedical Status
icuicai Oditus
hanksgiving
ired.
DOM
12 2:21:16 PM
Reim. Cash Date Date APV APV
AEV AEV
ing ARS,
ing ARS, ce in rifle will

http://cps03sp01.remington.com:99/Remington_PSA/PrintDisplay.aspx?ID=9604&Type=C... 2/4/2014

:

- -----

.

÷

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
Examination	Exam Date		1/29/2014
	Product Type		RF
	Action Type		A
	Assigned To		S.NICHOLS
Cause	4038	Could Not Duplicate Concern	
	Description	7	26" 308 WIN HB
	Date Code		XG
	Bore Plugged	False	
Barrel	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Like new; Functioning	·
······································	Firing Pin	Like new; Functioning	
	Shroud	Like new; Functioning	
Bolt	Face	Like new; Functioning	—
	Handle	Like new; Functioning	
	Stop	Like new; Functioning	
······················	Condition	Like new; Functioning	
Extractor	Cut Condition	Like new; Functioning	
2	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Like new; Functioning	
LUOKINS	Notch Condition	Select	
	Exterior Condition	Like new; Functioning	
Overall	Stock Condition	Like new; Functioning	<u> </u>
Overall	Fore End Condition	Select	
	Condition	Like new; Functioning	
Receive r	Bulged	False	
	Description		STANDARD SAFETY
Safety		Like new; Functioning	STANDARD SAFETY
-	Function Lift	Select	.009
5			009
Sear	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
	Condition	Like new; Functioning	
Trigger	Pull	Select	3.5#
	Altered	False	SEALANT PRESANT
	Sub-Assembly	M/700 Non-Bolt Lock	

http://cps03sp01.remington.com:99/Remington_PSA/PrintDisplay.aspx?ID=9604&Type=C... 2/4/2014

Quota	ation	Remington Se PO Box 70	ervice 0		Estin	nating	
		Madison, NC	27025-0700		Ke	eport	
Parts and R	epairs: P:(80	00) 243-9700/F:(336) 548-7801 www.remi	ngton.com		Page	: 1	
		E IN EXCHANGE FOR REPLACED PARIS.		•			
PLEASE APPRO	ove by Signin Receive Your	S IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE IG BELOW AND RETURNING TO THE ABOVE ADDRESS. REF R APPROVAL IN 21 DAYS, WE WILL RETURN THE ITEM(S) AS	PAIR TO TAKE API RECEIVED, POST	PROXIMATELY (6) WE AGE DUE.	EEKS AFTER RECEIPT	OF APPROVAL	
Remington d regulations.	lisclaims all Consumers	warranties concerning legality of a firearm's confi are advised to check their local laws to determine	guration under whether certai	applicable state, n firearm feature	county & locai lav s are lawful.	ws or	
-							
c	ustomer:			I tem 1	Return To:		
		IILLHOAN			USS MILLHOAN	A.1/C	
		URNIVALL AVE IN COUNTRY, CA 91351 US			7018 FURNIVALL ANYON COUNTR		1 US
	0/11/10						. 00
[
Please Circle	•						
VISA I	MC DISCO	OVER Card No PO Number:		Exp.Dat	e		-
Approval Sig	nature:	Time to C		Da	ate:		
Daytime P	hone: () Time to C	Call:				
If you d	lesire any cha	ange, please use the reverse side for your comments ar	nd mark this box				
Repair Num		Serial Number / Description				01/28/2014	
RE00335752		RR23002B Model: 700 308 WTN Caliber BOLT Action RIFL	F MfaBu			01/29/2014 2/4/2014	
		Remington-USA	L MIEDY.		vate i finited.	2/4/2014	
		Proble					
Reported R014 - FOI	RWARD TO	-	'ound (007 - COULD	NOT DUPLICAT	E CUSTOMERS C	CONCERN	
to restore con	fidence in rif	Technician C Te will replace trigger assembly, check over and test fi					
			ie at no enalee				
				NOT 1 1 1 1			
Material	Туре	ESTIMATE (note: C.O.D./Shipping and Handli Description	Qty		this Quote.) Qty Price	Disc Am	ount
F27591	Part	40-X POL TRIG ASSB RH	Needed 1	Fro Warranty	m Inv 100	0	.00
4000114	Service	GR-SHIPPING & HANDLING (GUN REPAIR)	1	Warranty	1 .00	0	.00
4000119	Service	GR-TEST	1	Warranty	1 .00	0	.00
					Sub Total: Est Sales Tax:		.00 .00
1					Grand Total:	Ş	5.00

.

.



December 6, 2013

Russ Millhoan 27018 Furnivall Ave. Canyon Country, CA 91351 Phone: 818-383-4632

COP

26"

4612/ 3.5 .00

Ref # 9604, Model 700, Serial # RR23002B

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination. A box will arrive separately.

Please include a copy of this letter and service request to put inside the shipping container. The letter and service request inside are important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm.

I hope that this action will keep you a loyal Remington customer.

Sincerely, J.B. Irving Consumer Affairs Administrator Remington Arms Co, LLC / H&R Phone: 336-548-8684 Fax: 336-548-7872

DECEIVE JAN 3 0 2014

BY:....



could Not dup. concern. To restore confidence in Rifle will typ. T.A. check OWER & TOST AT IN/C WARNARY

Remington Arms Company, LLC • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

Service Request

Remington Service PO Box 700

ATTN: Product Service

Madison, NC 27025-0700

www.Remington.com

Parts and Repairs: P:800-243-9700/F:336-548-7801 This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Service Request Number SR00070211 Customer: RUSS MILLHOAN 27018 FURNIVALL A CANYON COUNTRY Email:	RR23002B Model 700 RIFLE Caliber: 308 VE	14]]	Da	ate of Request: ate Printed:	12/06/2013 12/06/2013	
returned. If not, you will be constructed in the returned of the return	e item(s) will be evaluated by our repairman to deter ontacted with an estimate before work is performed.	mine if it is covered und	er our warranty policy.	If it is your fircarn	will be repaired and	j
Service Request Section Product Service #9604. jbi Parts And Service Details Material Type	i	Qty	Warranty	Price	Disc Amount	
		Needed				
THIS IS NOT AN INVOICE. 1 being sent based on the conver	This is a pre-estimate to repair, recondition, or replace sation with our representative.	se the item(s)		Sub Total: Est Sales Tax	. 00	

Irving, Jesse B.

From: Sent: To: Subject: Russ Milhoan [rgmilhoan@gmail.com] Friday, December 06, 2013 1:48 PM Irving, Jesse B. RE: Remington 700

Thank you.

On Dec 6, 2013 5:33 AM, "Irving, Jesse B." < Jesse.Irving@remington.com > wrote:

Russ,

Paperwork and a UPS shipping label will be coming in the mail and a box for shipping will be coming by UPS.

From: Russ Millhoan [mailto:rgmilhoan@gmail.com] Sent: Thursday, December 05, 2013 6:51 PM To: Irving, Jesse B. Subject: RE: Remington 700

Irving,

I am sorry the 91605 is my work zip code, my correct home zip code is 91351 otherwise the address I gave is correct. Phone number is: cell (818) 383-4632 and work is (818) 982.1464. If you call at work just ask for Russ. I assume you got my serial number in the E-Mail last night...if memory serves it was RR23002B. Memory does not always serve me well so I hope you got the note last night.

Russ

From: Irving, Jesse B. [mailto:Jesse.Irving@remington.com] Sent: Thursday, December 05, 2013 8:26 AM To: Russ Milhoan Subject: RE: Remington 700

Russ,

Please confirm your address. Zip code 91605 is coming up as North Hollywood, CA. Also, we need your phone number in case we need to call you. We always recommend removing any accessory items such as scopes or slings and etc. I would be happy to send you a box for shipping.

1

From: Russ Milhoan [mailto:rgmilhoan@gmail.com] Sent: Thursday, December 05, 2013 1:45 AM To: Irving, Jesse B. Subject: RE: Remington 700

Serial number is RR23002B

On Dec 4, 2013 2:00 PM, "Russ Millhoan" <<u>rgmilhoan@gmail.com</u>> wrote:

OK, give me till tonight to get the serial number to you and I will send it in. Do I take off the scope and bipod? (I would prefer to keep the scope on since I have dialed it in very precisely). I have a pelican style gun case that would be very secure do you think I should send it in my case? I does pack well in my gun case with the scope. Let me know what you prefer.

Russ

From: Irving, Jesse B. [mailto:<u>Jesse.Irving@remington.com</u>] Sent: Wednesday, December 04, 2013 1:11 PM To: Russ Millhoan Subject: RE: Remington 700

Russ,

If you are having an issue, we would like to get it in for examination. I cannot comment on having work done outside of Remington.

From: Russ Millhoan [mailto:rgmilhoan@gmail.com] Sent: Wednesday, December 04, 2013 3:25 PM To: Irving, Jesse B. Subject: RE: Remington 700

Thank you very much Jesse, but I would like to consider another option if you think it would be OK. I am told by someone I trust very much that this trigger is likely an adjustable trigger since the gun is less than a year old. Although I have never tried to adjust the trigger (and would never attempt to), I wondered if the gun shop did adjust it before I picked it up. Would it be OK to have it looked at by a gunsmith to check the adjustment? What do you think? I will have to look up the serial number when I get home but the caliber is .308 and mailing address and phone number are below. Do let me know about checking the adjustment with a gunsmith before sending the prepaid box...I would like to take care of this in the simplest way and I don't know if I could bear parting with my baby.

Russ Milhoan

27018 Furnivall Ave

Canyon Country, Ca

91605

From: Irving, Jesse B. [mailto:Jesse.Irving@remington.com] Sent: Wednesday, December 04, 2013 12:07 PM To: rgmilhoan@gmail.com Subject: Remington 700

Russ,

We would like to have the firearm come into our Product Services Department at our factory for examination. Please reply back to me with the serial number of the firearm, caliber, your mailing address and phone number. We would like to send you a pre-paid shipping label for UPS to have the firearm come in. I will also include a form that you can fill out to let the examiner know exactly what happened and when this occurred.

Sincerely,

J.B.

J.B. Irving | Consumer Affairs Administrator

Remington Arms Company, LLC

870 Remington Dr., PO Box 700, Madison, NC 27025-0700 Phone: <u>1.800.243.9700</u> | Phone: <u>336.548.8684</u> | Fax: <u>336.548.7872</u> or <u>336.548.7723</u> Email: <u>jesse.irving@remington.com</u>

Freedom Group Family of Companies: Remington | Marlin | Bushmaster Firearms | DPMS / Panther Arms | H&R | Barnes Bullets | Advanced Armament Corp | Mountain Khakis | Dakota Arms | Parker Gun | Para USA

Confidentiality/Proprietary Note: This e-mail and any files transmitted with it are intended solely for the use of the individual or entity to which they are addressed. If you are not the intended recipient or the person responsible for delivering the e-mail to the intended recipient, be advised that you have received this e-mail in error and that any use, dissemination, forwarding, printing or copying of this e-mail is strictly prohibited. If you have received this e-mail in error and delete this e-mail from your system.

From: Russ Millhoan [mailto:rgmilhoan@gmail.com] Sent: Wednesday, December 04, 2013 2:42 PM To: shopinfo Subject: RE: Remington 700

Thank you for your response. I have another question for you about an accidental fire. Two days after sending my last question was Thanksgiving day and we went to the range as I have done many times and when I clicked the safety off....the gun fired. Thankfully it was pointed down range and in a direction I intended to shoot. It is less than a year old and had less than 1000 rounds through it so it has no excessive wear. It is also not a maintenance issue since I always clean my gun between every use. Can you give me some help with this? Perhaps there is a part of the gun that needs special cleaning I may have missed or a particular method of use of the safety I need to know; just grasping at straws here any information would be much appreciated.

Russ Milhoan

From: shopinfo [mailto:info@shopremingtoncountry.com] Sent: Wednesday, December 04, 2013 10:43 AM To: Russ Millhoan Subject: RE: Remington 700

Mr. Milhoan,

As far as converting your Model 700 you will need to purchase the aftermarket conversion kit that is offered through Brownell's. What you have listed below is not what it takes for the conversion.

In regards to your question about the ammo, we will need to suggest that you contact Federal since it seems the problem lies with the ammo not the firearm.

Thanks for contacting us and we look forward to the opportunity to serve you again in the future!

From: Russ Millhoan [mailto:rgmilhoan@gmail.com] Sent: Tuesday, November 26, 2013 8:26 PM To: shopinfo Subject: Remington 700

Dear Sirs,

I have a question about the magazine clip you sell for the Remington model 700. I have found the parts below that I think are needed to convert my model 700 .308 to a magazine... is that all that is needed and can I acquire a larger than 4 round clip?

Model 700 308/6mm Magazine Box S/A ADL Blued (F15283)

Remington Model 700 BDL Short Action Magazine Box - Blued (19645)

One more question...my model 700 is a few months old and seems to fire my reloads just fine but when I switch to Federal American Eagle each shot has the brass lodge in the chamber and I have to put a dowel down the barrel and tap it in order to be able to eject the spent round. Can you tell me why this happens? Is it because it is new and needs to be broken in or adjusted or anything else?

Thank you,

,

Russ Milhoan

ARS LABEL REQUEST FORM

DATE:	12/06/2013	Service Request #	SR00070211
QUANTITY:	1	WEIGHT PER PACK	AGE: 10 LBS
REQUESTED BY:	irvingjb	email address:	I will mail
Business:		Remington Service PO Box 700 Madison, NC 27025-0700 www.Remington.com	
		LABEL INFORMATION	1
MAIL LABE	L TO:	RUSS MILLHOAN 27018 FURNIVALL AVE CANYON COUNTRY, CA 91351 US SR00070211	
		Email:	
RETURN IT	EM TO:	ILN Arms Services	
		4XX596 DEC 6, 2013 SVC GNDCOM ACT \ TRACKING# 1Z4XX596906521515 REF 1:SR00070211 REF 2:	ALL CURR USD 1 OF 1 WT 10.0 LBS 59
		HANDLING CHARGE 0.00 SINGLE – PIECE PUB RATE CHRG DV 0.00 COD DC 0.00 DGD AH 0.00 PR 	S: SVC T/P USD 0.00 RS 0.60 0.00 SD 0.00 0.00 SP 0.00 PUB+HANDLING 14.28
ATTN: Proc	luct Service		







