Remington Arms Co., Inc. Product Service Legal Case #:9325

Case Information

Date Opened Date Opened(PS) Pre Lit Lit Obsolete **Date Closed Incident Date**

10/22/2013

Webber

Customer Information

Business First Name Last Name Street Contact City State Zip Age

Incident Ray

P.O. Box 991 1020 Airport Rd

Taylor AZ 85939

H 928-536-4811

Incident Information

Claims Codes Repair Est. **Medical Treatment Medical Status**

PΙ

PD

Cause:4079 Other - Unexamined Concern:1008 Fired on Bolt Closing

Unknown

S FBC \mathbf{C}

10/22/13: I received call from Ray Webber, he stated that his gun fired while closing the bolt. jbi

Firearm Information

Mfg.

Type

Model/Ga.

SKU

Serial Bbl. DOM

Remington

CF/BA

700/243 WIN

N/A

6397537

Date Purchased

Where Purchased

Accessories Original Owner

WHITE STORES WICHITA F., TEXAS

N

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement

Release of Claims

Release Date

Reimbursement

Cash Settlement Date APV

Reim.

Cash Date APV

Repair/Replacement Repair/Replacement

Cost

Date

10/22/13: Sending ARS, letter, and SR paperwork. Box sent on SAP order 1554080. jbi

Examination[Remington/CF/BA]

Part Sub-Part Code Comment

ARS LABEL REQUEST FORM

DATE:	10/22/2013	Service Request #	SR00065120	
QUANTITY:	1	WEIGHT PER PACKAGE:	10 LBS	
REQUESTED BY:	irvingjb	email address:	I will mail	

Business: Remington Service PO Box 700 Madison, NC 27025-0700 www.Remington.com

LABEL INFORMATION

MAIL LABEL TO:

RAY WEBBER P.O. BOX 991 1020 AIRPORT RD SR00065120 TAYLOR, AZ 85939 US Email:

RETURN ITEM TO:

ĪLN

Arms Services



OCT 22, 2013 ALL CURR USD ACT WT 10.0 LBS 4XX596 OCT 22, 2013 SVC GNDCOM ACT WT TRACKING# 1Z4XX5969067272263 REF 1:SR00095120 REF 2:

1 01 1

HANDLING CHARGE 0.00

SINGLE - PIECE PUB RATE CHRGS:

DV 0.00 COD B.00

DC 0.00 DGD 0.00

AH 0.00 PR 0.00

TOT PUB CHG 14.29 PUB-1 S: SVC T/P USD 8.00 RS 0.50 0.00 SD 0.00 0.00 SP 0.00 PUB+HANDLING 14.29

ATTN: Product Service