

RD-7018

Remington Arms Company, Inc. INCORPORATED

RECEIPTED EXPENSE BILL MUST

S.V. No.	
Remington	

ACCOMPANY ALL CHA TRANSPORTAT					er No.		
SHIPPED VIA			SELLER'S INVOICE NO.		DATE _	10/28/99	
SHIPPING WEIGHT			BOUGHT OF	Rich Montgomery			
F.O.B.			STREET AND NO.	2400 Eastridge CT			
PER CENT	DAYS	DAYS NET	CITY AND STATE	Fort Collins, CO 80524			
QUANTITY			AMOUNT				
	To reimburse customer						
	Reference R99-21071		\$300.00				
	1		<u> </u>	 			
	-						
CHARGE	MATERIAL OR SERVICES REC'D BY FLS		PAID	AMOUNT OF BILL	\$300.00		
8850050-230145	PURCHASED, A		ATE	DISCOUNT			
	APPROVED BY	CH	HECK D.	NET	\$300.00		
RECEIVED OF							
REMINGTON ARMS CO.	\$300.00						
DATE	SIGNATURE OF PAYEE						

INITIAL CUSTOMER C	ND ESTIMATING I	neruki		F SUPRY		E BRAKE		R 99-	ORDER -21071
PS GOSTONIET				MAYR RECO					
DATE RECEIVED DA	TE OPENED DATE CO	OE	SERIAL NUMBER	NEW SE	FRIAL NUMBER	MODEL AND GRA			
10/26/99 1			B6576	583		700	30-06	BL	DL/LH
ACCESSORIES	Zants	LYSIGH	11.2				C.E.	4-84 2N	ID TIME
EDOM:	<u></u>					0100.70	UE	- 04 AF	I TUE
FROM:	•				٦	SHIP TO:			
•	MOTGOMERY				'	MOTGOM	ERY, RI		
	2400 EAST	RIDGE CT				2400 E	ASTRIDG		
	FORT COLL	ZNI	Cf	0 80524		FORT C	OLLINS		CO
								86	9524
			ni.e.	ሮ ሐው - ጣፈ 44	200 0 00	n			
ACCOUNT NUMBER	ACCOUNT NUM	MBER N/C		T NO:2148	سلامت قيمالا.	PROM. DATE	ESTIMATE	D VIA	
SSOW, NOMBER	2301	145	WRITE [7		. FIGIVI. DATE	LOTIMATE		UPS
GUN CONDITION								REPAIR CHAP	
NEW								<u> </u>	
LIGHTLY WORN								EXCISE	
	†							TAX	
☐ WORN								INSURANCE	
VERY WORN								UPS	
UNREPAIRABLE								PARCEL POS	~~ ~~
MARRED	L							TOTAL	الم
CUSTOMER CONCE	ERN AMMO	FUNCT	ION	FINISH	ACCURACY	FIT	IN	ISPECT	
CYCLE	A AVIIVO	B1							
TRIGGER GROUP		. B1 : B1				<u> </u>	15.		
BOLT ASSY.		: 60 - B3				; E2	F2		
BARREL ASSY.		- B3 		<u> </u>	1	13 13	F3		
REC. ASSY.				. 0		£17	1F3 +F4		
		B5	1						
WOOD			. C*	<u> </u>		E5			
METAL			+ C2						
MAIN FAULT		Ruste			Rigger	Shoe			
		Rubb	ing '	uned					
			<i>-</i>		_				
		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,							
PARTS				COMMENTS	SURA	P. Gus	n De.	r Cosi	tomer
PARTS					SCRAY	a gui	z pe	r Cost	toner
PARTS					Scrapest -	o gui	z pe	r cosi	toner
PARTS		7,000			Suray rest -	o gui	z pe Kš	r cosi E,	tomer 3/44
PARTS		7,000			Scrapest -	o gui	pe Ris Fis	r cosi E,	tomer 3/99
PARTS		7,200			Scray est -	o gur	pe R\$ FCS	r cosi E, 10/28	tomur 3/99
PARTS		7,200			Scrap vest -	a gue	pe R \$ FCS	r cost E, 10/28	tomer 3/99
PARTS					Scray rest -	o gur	pe R\$ FCS	r cosi E,	toner 3/99
PARTS					Scrages to	o gur	, pe R s FCS	r cosi E, 10/28	10 mir
PARTS					Scrapest -	o gur	pe R s FCS	r cost E, 10/28	15 mer 3/99
PARTS					Scrapest -	o gur Close	pe A s Fas	r cosi E, 10/2E	15 mer 3/99
PARTS				COMMENTS	Scrapest -	o gun	R\$ FCS	10/28	3/99
PARTS					SURAY DEST -	P. GUM Close	P Pe A \$ FCS	r cost E, 10/28	James 3/99
PARTS				COMMENTS	SCRAY SCST -	O GUI	R\$ FCS	10/28	3/99
ARTS				COMMENTS		Close CLEAN DATE	R\$ FCS	10/28	3/99
ARTS				COMMENTS			P-CS	10/28	3/99 PATTER

October 14, 1999

Mr. Fred Supray Remington Firearms Corporation 14 Hoefler Ave. Ilion, NY 13357

Dear Mr. Supray,

Enclosed is my Model 700 30-06 for your review. I must admit, I was going to send a lengthy letter explaining how disappointed I am with Remington and my Model 700. However, having cooled down I will just give you the facts.

Approximately 1 ½ years ago I sent my gun to your facility for repair. The gun on a random basis would discharge by releasing the safety. This occurred on one occasion and now having the gun repaired by Remington it again (twice) has discharged while releasing the safety. After receiving the gun back from Remington with repairs made I had to again send the gun back to Remington as the bolt would not completely close. Does Remington have a quality control individual? If so, he or she certainly did not evaluate my gun prior to it leaving your facility. Safety is everything when it comes to hunting or shooting and I must tell you, receiving my gun back with a problem that it did not have when first sent to your facility certainly gives me concern for Remington's attitude towards safety. Not only did my gun come back with the original problem still yet resolved but it came back with a problem that it did not have when sent in for repairs. Releasing the safety and having a gun discharge, in my opinion, is the worst safety issue that can occur when handling a gun.

I have enclosed my gun for your review only. I do not want the gun back as I have absolute no confidence with this gun. Please destroy and remove this firearm from the public domain. I do require or am I asking for any monetary retribution. I simple want this gun destroyed. I can not and will not sell this gun to another individual, and I will no longer carry this gun in the field.

In conclusion, my experience with Remington over the past 30 years has been excellent. We own several Remington guns (1100, 870's, Model 7) and overall have had wonderful experiences using your products. I understand this is a one time bad experience however, a one time bad experience with this type product can or could be a deadly experience.

I appreciate your time in reviewing this letter. No reply is necessary. Just destroy this gun.

Sincerely,

Rich Montgomery 970-482-9315