REMINGTON ARMS COMPANY, INC.

INTER-DEPARTMENTAL CORRESPONDENCE

Remington **CUPOND**

D*ETERS* QUPOND

CC: H. R. Dorr G. R. McCormick W. B. Parsons E. A. Walsh W. A. Walters H. D. Herbert E. Sapp

"CONFINE YOUR LETTER TO ONE SUBJECT ONLY"_

February 13, 1946 Ilion, New York

TO:

R. A. A. HENTSCHEL

FROM:

C. W. BORDEN

SUBJECT: PURCHASED PARTS - M/721-722

In a meeting held in W. B. Parsons' office, 2-8-46, attended by Messrs. Walters, Parsons, Walsh, Sapp, Herbert and the writer, the following questions were discussed relative to model drawings on purchased parts for the M/721-722 rifle. These questions were brought up by Mr. Walters, Buyer, working with the Purchasing Department, who has attempted to place orders for these components.

1. Barrel Bracket - A 17002

A new material procurement sheet will be required showing definitely where the shear marks should be removed on this component.

2. Open Sight Assembly - B 17030Y

Several of the vendors question the feasibility of brazing the sight base to the open sight leaf and heat treating this assembly after brazing. It is suggested that this assembly be reviewed and corrections made accordingly. It is also recommended that this drawing be dimensioned and show the sight base in the top view.

a. Sight Base - A 17031

The word "Production Weld" should be read "Projection Weld".

Open Sight Leaf - B 17032

It is felt that the 40° max. radius dimension should be expressed more clearly and read from 0° to 40° max. Centrality figure designated #1 should be removed or corresponding centrality figures should be placed on the drawing for other surfaces.