

LIMITED DISTRIBUTION

-2-

FOOTNOTES

1. It was felt by some that the W770 stock was too massive around the grip near the front of the comb. There was insufficient clearance for the heel of the hand.
2. The Model 670 is not available in .308 Winchester. Winchester introduced this cartridge.
3. The R660 bolt release cannot be operated without the aid of an external object. A slender object must be inserted into the receiver to depress the bolt stop while the bolt is then withdrawn over it.