

APPENDIX LIMITED DISTRIBUTION

Assembly Methods

	<u>Remington</u>	<u>Winchester</u>
copper braze:	bolt handle to bolt body 700, 660 bolt head to bolt body 700, 660	bolt handle to bolt body 770, 670
spot welded:		folded magazine box assembly
threaded permanent:	barrel to receiver, 700, 660	barrel to receiver, 770, 670 firing pin sleeve to firing pin (also drive-loc pinned)
threaded removable:	front and rear sights to barrel bolt plug to bolt body receiver assembly to stock	front and rear sights to barrel bolt sleeve to bolt body receiver assembly to stock
pinned:	firing pin tip to firing pin	