

John W. Block

Progress Report

9/27/78

370 Insulation trap

The latest 370's, Fosters and
recently newings will be furnished to Proc.
Examine the mother

Target grade hugg was in the
this test lab. Time flying tests have started.

Shotgun	T. nigger Pull at start	Rounds	Present Trigger Pull
870	2.08 #	1000	1.9 #
1100	2.92 #	210	2.87
1120	4.08 #	-	-

on the first two guns a fail to connect
and a double click safety.
was encountered. It was found that the trigger was
not returning to the hammer and was caused by

11.7.1 - 500 Fire Control

Fire controls that have adjustment for range
within in safe limits are known as remote location.

From the stock, light trigger is removed and placed
There are hand are in the test area.

2 different designs of a test area that
a. in the design is involved with the design
will be ready in action for testing and
market evaluation.

11.7.8.3, 530's, 541's, and 542's

a. in the design is involved with the design

b. in the design is involved with the design

c. in the design is involved with the design

11788-22 Hunt

work is progressing on the design
and layout for this model and similar.

Estimated time

The marketing department has requested information on the
market, estimated sales, and this model along with
other recent questions. Evaluation will begin as
results are received.

Production has gone out for quotes on
the hand-coiled model for preliminary introduction.

DON'T SAY IT — WRITE IT

To _____
From _____

Date _____

CENTER FIRE RIVETLESS EXTRACTORS

PURCHASING EXPECTS A PROPOSAL FROM OUR
CURRENT VENDOR BEFORE THE END OF SEPTEMBER,
ABOUT A MONTH OVERDUE.

ASEA MANIPULATOR

THREE QUOTES ON POLISHING EQUIPMENT HAVE BEEN
RECEIVED 30M, 45M & APPROX. 50M. NONE ARE
FULLY SATISFACTORY AS YET, & WILL HAVE TO BE
REFINED. DELIVERIES ~~AND~~ OF 5 MONTHS WERE
QUOTED. ASEA HAS ~~NOT~~^{HAD} PRINTS OF SUGGESTED
GRIPPER DESIGNS SINCE SEPT 1, BUT HAS NOT
RESPONDED

BARREL DRILL LINE

THE VENDOR WAS VISITED SEPT 5 & 6, DESIGNS
ARE NEARLY COMPLETE & FINALIZE PRINTS
SHOULD BE IN LION BY OCT. 1 FOR APPROVAL

DON'T BE SORRY — BE SAFE

BENCH REST BULLETS

APPROXIMATELY 57,000 6MM BENCH REST BULLETS
HAVE BEEN SHIPPED TO THE WAREHOUSE

PRICE & MATERIAL STANDARDS ARE CURRENTLY
BEING RE-EVALUATED TO UP DATE INCREASE
COST OF MATERIALS AND DIRECT LABOR. NEW STANDARDS
WILL PROVIDE A MORE ACCURATE COST FOR THE
JOB.