

This went to participating Jew smith.

TELEGRAM

Thank you for agreeing to assist us in the installation of a new trigger assembly in Remington 600, Model 660 and Mohawk 600, and XP-100 pistols, covered by our recall.

Our toll free Message Center is advising customers in your area of your availability to make this installation.

We are sending you under separate cover special repair and information forms, plus an initial supply of replacement trigger assemblies.

For your information, Remington will assume full and complete responsibility for any and all claims that may arise out of the design or manufacture of the trigger assembly provided to you by Remington for this modification.

The ^{only} guns included in the recall are all Remington Model 600 and 660 rifles, and all Mohawk Model 600 rifles, except those with a serial number starting with an "A". Also included in the recall are any XP-100 pistols with a serial number between 0001 and 7,507,983.

If you have any questions, please call Ed Sienkiewicz collect at (315) 894-9961.

REMINGTON ARMS COMPANY, INC.

10/27/73