REV. 8-58

REMINGTON ARMS COMPANY, INC.

INTER-DEPARTMENTAL CORRESPONDENCE

Remington

September 21, 1979

TO:

E. C. Larson

FROM:

R. G. Sherman

SUBJECT:

RECALL REPAIR STATUS

TOTAL REPAIRS MADE BY ILION THROUGH 7/14/79

| MODEL XP-100 NODEL 600-660 | 1,506 879 2,385 |
|--|-------------------------|
| TOTAL REPAIRS MADE BY CANADA | . 479. |
| TOTAL REPAIRS BY FIELD SERVICE STATIONS THROUGH 9/18/79 | 17,512 |
| REPAIRS MADE BY NYCPD (Not-included in Accounting's APV's) | 313 |
| REPAIRS MADE AT THE BRIDGEPORT CUN SHOP | 12 |
| NUMBER OF REPAIRS PERAINS MADE ON T NUMBER OF ENTERNAL NOT PAID AS OF 9/18/79 TOTAL DOCUMENTED REPAIRS TO DATE | 20,701 193 20,894 |
| (Not included in Accounting's APV's) | # |
| TOTAL TRIGGERS PRODUCED BY ILION TO DATE | 23,752 |
| TOTAL TRIGGERS SHIPPED BY ILION | 23,722 |
| TOTAL TRIGGERS ON HAND IN ILION | 30 |

ILION TRIGGER INVENTORY 9/20/79

30 units

UNPAID INVOICES OUTSTANDING

193

The amount of additional recall repairs that will be generated as a result of our latest 140,000 unit ATF mailing would be only sheer speculation at this point. However, I believe that we would be safe in saying that between now and the end of 1979 the repairs performed in the field would fall between 1,500 and 2,000 units.

Although there would be a certain amount of time and additional expense involved, we might consider contacting each one of our service stations requesting:

1. The number of fire control units on hand.

We are doing this.

- ,2. The number of Model 600-660 rifles to be repaired.
- The best estimate of what they would expect to repair in possibly the next 3 months.

This could be accomplished with a letter containing a return self-addressed envelope or actually making the phone calls from our department down here. If Ilion is seriously concerned about the possibility of a fire control overrun that may not be utilized, possibly this would give them the most accurate numbers to base our future trigger assembly production on.

Dest legalus,

' R. G. Sherman

RGS/ac