

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Capital \$	Ops. \$	Depart. Number	Depart. Labor \$	Total % Overhead
	Blank Material - Screw Machine			\$ 210.00			
	Gaging (vendor and Remington)			\$ 500.00	Vendor		
10	Black Oxide Color		\$ -	\$ -	8551	\$ 18.39	240.20%
	Totals		\$ -	\$ 710.00			

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Capital \$	Ops. \$	Depart. Number	Depart. Labor \$	Total % Overhead
	Blank Material - Screw Machine			\$ 210.00	Vendor		
	Gaging (vendor and Remington)			\$ 500.00			
10	Black Oxide Color		\$ -	\$ -	8551	\$ 18.39	240.20%
	Totals		\$ -	\$ 710.00			

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Capital \$	Ops. \$	Depart. Number	Depart. Labor \$	Total % Overhead
	Blank Material - Screw Machine			\$ 210.00			
	Gaging (vendor and Remington)			\$ 500.00	Vendor		
10	Black Oxide Color		\$ -	\$ -	8551	\$ 18.39	240.20%
	Totals		\$ -	\$ 710.00			

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Capital \$	Ops. \$	Depart. Number	Depart. Labor \$	Total % Overhead
	Blank Material - Screw Machine			\$ 210.00			
	Gaging (vendor and Remington)			\$ 500.00	Vendor		
10	Black Oxide Color		\$ -	\$ -	8551	\$ 18.39	240.20%
	Totals		\$ -	\$ 710.00			

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Capital \$	Ops. \$	Depart. Number	Depart. Labor \$	Total % Overhead
	Blank Material - Screw Machine			\$ 210.00			
	Gaging (vendor and Remington)			\$ 500.00	Vendor		
10	Black Oxide Color		\$ -	\$ -	8551	\$ 18.39	240.20%
	Totals		\$ -	\$ 710.00			