

DON'T SAY IT-WRITE IT

To Clark Workman

Date 4/25/81

From Tami C.

cc: M/700 Fire Control

I discussed this with Tim Martin some time ago and neglected to return to you with comments. Tim indicates that with the new fire control Fred Martin is working on, if the sear connector engagement or weight of pull are adjusted out at acceptable limits, the safety will become hard to operate and therefore discourage the user from adjusting to set a "hair trigger".

"SAFETY RULES ARE PERFECT TOOLS"