

P.I. NO GUN EXAMINATION REPORT NUMBER: 467 MODEL: 700 ADL
 GENERAL CONDITION: POOR - DIRTY R #: 16802
 OUTSIDE WORK: RECOIL PAD & STOPS ADDED DATE: 6-12-81
SCOPE SCREWS REMOVED FROM: LOUISIANA WILDERNESS
SCOPE SCREWS REMOVED FROM: SUPPLY INC
 FIRED AMMO TYPE: NOT KNOWN P.O. BOX 1961, 4024 RODEO
 ST. MARIAN CITY LA.
 & CONDITION: GUN #: 6355141
 PROOF: A INSP.: 9 TEST: 87 CODE: OT= 7-70
 HEADING: OK GA./CAL.: 3006
 BREACH OPENING: OK CHECKED BY: M-HARDY
 RECOIL SHOULDERS: OK APPROVED: GH 6/22/81
 CHAMBER: OK APPROVED: GH 6/22/81
 TEST: APPROVED: J.H. 6/22/81
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: GH 6/22/81

- BRIGH METAL + RUST ON BBL
BOLT RUSTY POOR FIT OF RECOIL PAD

COMPLAINT: SAFETY WON'T WORK + TRIGGER GOES OFF
WITH OUT PULLING WHEN WORKING BOLT

INCIDENT: _____

COMMENTS: Fire control jammed up. Sean safety cam sticks
in down position. Excessive grunt in fire control.
Replace fire control - charge customer.

- Trigger pull 3#

- Gun passes tick test.