

Rev. 2-15-61

P.I. YES GUN EXAMINATION REPORT NUMBER: 37 MODEL: 700 BDL L.H.
GENERAL CONDITION: SLIGHTLY WORN R #: 28088
OUTSIDE WORK: SCOPE MOUNTED DATE: 11-22-82
FIRE AMMO TYPE: UNKNOWN FROM: CENTURY LAND CO.
945 Town & Country Blvd.
Suite 350
Houston, TX 77024
& CONDITION: _____ GUN #: 6859417
PROOF: REP 2 INSP.: 123 TEST: 63 CODE: 5-76
HEADING: O.K. GA./CAL.: .270 WIN.
BREECH OPENING: O.K. CHECKED BY: SAW
RECOIL SHOULDERS: O.K. APPROVED: RPH 12/8/82
CHAMBER: O.K. APPROVED: WJ 12/8/82
TEST: _____ APPROVED: DN. 12/20/82
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: RUB 12-22-82

COMPLAINT: "... RIFLE FIRED WHEN I WAS TRYING TO UNLOAD IT..."

INCIDENT: MOVED THE SAFETY TO THE OFF POSITION
TO OPEN THE BOLT.

COMMENTS: Replace fire control as requested by
customer.