

## SAFE "OFF - ON" FORCES

### PROCEDURE FOR MEASURING SAFE "OFF - ON" FORCES

#### 1. General

To measure Safe "Off - On" forces on firearms not manufactured by Remington Arms, Consult Lab Supervision.

#### 1 A. Equipment Needed (Fig. 4 - 9)

- Push - pull gauge.
- Test Procedure Sheet.
- Work Bench with a Gun Saddle.

Figure 4 - 9

