

# Model Shop Work

- Receivers
- assemble barrel, chamber, crown
- machine bolt assembly (bolt lock sets required)
- machine S extractors (mild. & 222's also)
- machine bolt plug - drawing required - at check
- machine bolt lock - detail required - at check
- turn bolt lock spring - drawing required
- machine stock, file
- alter/purchase scope mount cap screws [ $\#5-40 \times \frac{1}{4}$ ]
- machine safety - [wire]
- assemble button
- machine/alter sear - drawing required need plt
- machine/alter trigger - drawing required need plt
- machine/alter side plate - drawing required - at check
- rivet housing, color
- turn adjustment screw - drawing required
- machine plunger - drawing required
- alter adjustment screw - drawing required - need plt
- machine bolt stop release
- turn bolt stop spring
- machine magazine catch
- REAR SPACER

Focus Panel fittings

1  $\frac{1}{8}$  2  $\frac{1}{8}$  3  $\frac{1}{8}$  4  $\frac{1}{8}$  5  $\frac{1}{8}$

$\frac{1}{8}$

Stocks (3 laminating)

Two pt levers to be finished  
One synthetic to be installed

Bore Assemblies

Bore patches  
Assemble barrel, Chamber & Case  
Polish + Color (Boreblast)

Misc - powder coat  
guard,股票, followers

Assemble

Under Browning A-Bolt