

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 660
GENERAL CONDITION: NEW R #: 006930
OUTSIDE WORK: SCOPE MOUNTED, SWIVELS ADDED. DATE: 3-13-72
CEMENT REMOVED - REAR ADJUSTING SCREW. FROM: ACKERMAN'S FIRST
AID SUPPLIES
FIRED AMMO TYPE: - GROVE CITY, PA.
& CONDITION: _____ GUN #: 111373
PROOF: R.E.P. ^{ASSEMBLER 65} INSP.: 73 TEST: 79 CODE: KR = 5/68
HEADING: - GA./CAL.: 243 WIN.
BREACH OPENING: - CHECKED BY: PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

SEAR AND TOP INSIDE OF HOUSING COATED WITH DRIED
LUBRICANT OR OTHER MATERIAL.

COMPLAINT: "GOES OFF WITHOUT WARNING."

INCIDENT: FOLLOW DOWN

COMMENTS: THE LUBRICANT OR WHATEVER, CAUSED SLUGGISH
RESPONSE OF TRIGGER ASSEMBLY - TRIGGER FAILURE TO
RETRACT, SEAR FAILURE TO RETURN TO COCKED POSITION.