
From: Supry, Fred L.
Sent: Monday, November 19, 2007 8:27 AM
To: Watson, Laura M.
Subject: RE: RE00136658/ Green

11/19/2007

It was logged in here Friday just before noon; I just got it off the PS truck and did the examination. I could find no fault with the rifle for the accidental discharge. The follower was stuck as received, if that was binding it could account for his feeding problems. We will service the rifle and install an X-Mark Pro trigger assembly.

Fred Supry, Manager
Product Service and Law Enforcement Training
Remington Arms Company
14 Hoefler Avenue
Ilion, NY 13357

Phone: 315-895-3606
Fax: 315-895-3661
e-mail: fred.supry@remington.com

From: Watson, Laura M.
Sent: Friday, November 16, 2007 10:43 AM
To: Supry, Fred L.
Subject: RE00136658/ Green

Fred, Looks like this one came in earlier this week is it just on hold b/c of inventory?
He's called me twice this week to check on it. You know how they get! ☺

Laura Watson
Consumer Affairs Administrator
Remington Arms Company
Phone 800-243-9700 ext 8789
Fax 336-548-7890
Email laura.watson@remington.com