
From: Norton, Vince
Sent: Thursday, October 11, 2007 9:18 AM
To: McCollum, James M.
Subject: FW: REQUISITION
Attachments: image001.gif

Did the PO for these parts get sent out to U of L?

From: Norton, Vince
Sent: Wednesday, October 03, 2007 4:29 PM
To: Diaz, Danny
Cc: McCollum, James M.
Subject: REQUISITION

1003010852 – 30 receiver inserts from U of L for the Model 710 fire control.

During assembly of the DAT fire controls there was an issue with the trigger pull adjustment. The fix requires a change to the insert. I will discuss the problem with you when you get back in the office.
Vince