

CONCEPT TO CUSTOMER – SIX STEPS

1. DEFINE PRODUCT / CUSTOMER NEEDS

2. DEFINE PRODUCT CONFIGURATION

3. DEFINE PRODUCT DOCUMENTATION

(Drawing, BOM, Routings, Process Records)

4. DEFINE PRODUCT EQUIPMENT, TOOLING, PERSONNEL, LOCATION & FLOW

5. PRODUCTION T&P

6. PRODUCTION

<autofile>
Stephen Perniciaro

Page 1

<autodate>