

VS vs. 700P

The primary difference between the 700 VS and the 700P is the reinforcement in the fore end which designed for use with a bi-pod. The 700P does go through more quality checks, since they are used as duty weapons. The 700P is the only rifle we carry with a guaranteed minute of angle, however, the 700 VS is also the most accurate out of the box production firearm available today. We hope this information is helpful and we appreciate your loyal support of Remington products.

ACCURACY

We do not make accuracy guarantees of any kind, since accuracy varies greatly from shooter to shooter. The Model 700 VSSF is one of the most accurate out-of-the box rifles offered today.

BREAK IN PROCEDURE –FIRE LAPPING

Clean bore with a bronze bore brush after each shot for 20 shots. Then clean every 5 shots for 20 rounds. We hope this information is helpful and we appreciate your loyal support of Remington products.

TRIGGER ADJUSTMENT

For liability reasons we do not recommend adjusting your trigger assembly. You can, however, contact one of our Authorized repair centers that could give you further information. You can locate your nearest repair center by visiting the Repair Information Center in our Support Section and selecting your model and state.

<http://www.remington.com/Support/repairsvc/ModelSelection.asp>

We hope this information is helpful and we appreciate your loyal support of Remington products.

AMMO

Our guns, not unlike many other manufacturer's guns, may prefer one type ammo to another. We would recommend staying with the ammunition that works best in your gun. We hope this information is helpful and we appreciate your loyal support of Remington products.

ADL VS BDL

BDL simply means that the gun comes equipped with a floorplate. ADL means it's a top load only. We hope this information is helpful and we appreciate your loyal support of Remington products.

BDL TO DETACHABLE

Unfortunately we do not recommend alterations of this kind since it requires the removal of too much metal from the receiver. We hope this information is helpful and we appreciate your loyal support of Remington products.

ADL TO BDL

It is possible to convert your ADL Model 700 to a BDL Model 700, however; we don't recommend this type of conversion. You would have to change the magazine box, spring and follower, the trigger assembly and guard screws. These parts are approximately \$140. This price doesn't include the price of the stock. We hope this information is helpful and we appreciate your loyal support of Remington products.

METALLIC MAKE-UP

It is very unfortunate that someone would provide you with such negative information on Remington products. Our manufacturing plant is in the same place it has been for almost 200 years. The process is more modern, of course, but our Mode 700's still have the three rings of steel that we've always been famous for. The metal is not soft, and the bolt and trigger are some of the most sought after in the shooting world today.

TORQUE SPECS

Torque specifications for synthetic & wood stocks is hand tight which is 30 to no more than 35 inch pounds. We hope this information is helpful and we appreciate your loyal support of Remington products.

Torque specifications for Sendero & Police stocks is 45 inch pounds. We hope this information is helpful and we appreciate your loyal support of Remington products.

Torque specifications for M-24 is 65 inch pounds. We hope this information is helpful and we appreciate your loyal support of Remington products.

Torque specifications for Model 40-XS stocks is 65-70 inch pounds. We hope this information is helpful and we appreciate your loyal support of Remington products.

700 XCR'S

Due to production constraints the Model 700 XCR's in the Ultra Mag calibers have been pushed back on the production schedule. We appreciate your patience while waiting for this product. We appreciate your loyal support of Remington products and your visit to Remington Country

SHORT/LONG ACTION

The following is a list of short and long action calibers. We hope this information is helpful and we appreciate your loyal support of Remington products.

SHORT ACTION	LONG ACTION
.17 Rem	.270 Win
.222 Rem	.280 Win
.223 Rem	.30-06 Sprg
.22-250 Rem	7 x 64 Bren
7mm-08 Rem	7mm Mauser
6mm Rem	35 Whelen
.243 Win	6.5 x 55 Swedish
.308 Win	25-06
250 Savage	8mm Mauser
260 Rem	
.257 Roberts	

AMMONIA ETCHING BORE

Extended exposure to ammonia based products with more than 2% concentration can cause etching to the bore. Using a 50/50 mixture of alcohol and water can neutralize the ammonia. Our solvents such as Bore Bright do not contain ammonia. Thank you for your inquiry.

MOUNTAIN CONTOUR BBL

The lighter mountain rifles do have a lighter contour barrel, but they still have the same three rings of steel in the chamber area, where the combustion is contained. The weight is reduced toward the muzzle end of the barrel, therefore the thickness of the barrel is not compromised.

5-R RIFLING

The big advantage to 5-R rifling is that after the barrel is broken in, there is considerably less fouling of the bore and the life expectancy from an accuracy standpoint is greater. You may notice, however, that during the normal break in process there may be more metallic fouling than normal.

The rate of twist is 1:11.24" which is optimized for M118 Ball ammo as specified by the U.S.

We hope this information is helpful and we appreciate your loyal support of Remington products.

BARREL REPLACEMENT

Unfortunately we don't sell barrels or actions. You will need to send your gun to our Ilion facility if you are having a problem with your barrel and we will install a barreled action for you. You can, however, check with the following retailers to see if they have any of our actions available. We hope this information is helpful and we appreciate your loyal support of Remington products.

Midway Arms 800-243-3220
Christensen Arms 435-528-7999

SENDERO

The Model 700 SENDERO is equipped with a 26" heavy barrel that facilitates increased velocity and increased accuracy at longer ranges. The Remington model 700 is touted, in the shooting realm, as the most accurate out of the box rifle on the market today.

A CARTRIDGE BELOW: LAPUA CARTRIDGE

The model 700 magnum action has sufficient strength to withstand any of the pressures created by the Lapua cartridges, we do not recommend re-chambering a factory model 700 to the Lapua cartridge because it decreases the strength of the chamber in our barrels. You can safely re-barrel a 700 Magnum action with a barrel that is chambered for a Lapua cartridge. We hope this information is helpful and we appreciate your loyal support of Remington products.

BOLT REPLACEMENT

Unfortunately bolts for the Model 700's are restricted to the factory due to the fact that they have to be individually head-spaced. The charge for this service can range anywhere from \$150 to \$300 depending on how much work is involved with the individual gun.

Please send your firearm to our firearms plant listed below. To ensure proper shipping, we suggest the following:

- If warranty repair is being claimed, include proof of purchase
- Properly package your unloaded firearm. If you need a box, please call 1-800-243-9700, option Repairs.
- Do not send ammunition with your firearm.
- Include your full address and telephone number
- Include a letter that explains the problem
- Mail to: Remington Arms Company Inc.
Arms Services Division- Repairs
14 Hoefler Avenue
Ilion, New York 13357
Telephone: 1-800-243-9700, option: Repairs

After shipping, please allow 2 weeks before calling into the Repair Department.