

**BARBER - Kinzer PPS GAL RE0000337**

 SPORTING FIREARMS, AMMUNITION, TARGETS AND TRAPS  
 ILION, NEW YORK 13357

 PARTS (315) 895-7493  
 REPAIR (315) 895-7791  
 FAX (315) 895-7214 (315) 895-3059  
 CUSTOMER NUMBER: 257

DATE: 12/07/92

SOLD TO REPAIR UNDER NO.: 92-24398

SHIPPED TO

REPAIR ORDER NO. 92-49110

 FRONTIER GUN SHOP  
 14115 E LAMBERT ST  
 WHITTIER CA 90609

 FRONTIER GUN SHOP  
 14115 E LAMBERT ST  
 WHITTIER CA 90609

THIS IS AN ESTIMATE TO REPAIR, RECONDITION OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW. RETURN THE FIRST COPY TO REMINGTON ARMS CO., INC. ILION, NY 13357. KEEP THE SECOND COPY AS YOUR RECEIPT.

REPAIR TO TAKE ABOUT 3 WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN THIRTY DAYS, WE SHALL RETURN THE ITEM(S) AS RECEIVED.

 700 30-06 DDL/LH SERIAL NUMBER: 6720579  
 W/STUOS SCOPE BASE L/SIGHTS

 CUSTOMER REQUEST:  
 BROKEN CORN.

MAIN FAULT FOUND:

 AS ABOVE  
 REPLACE TRIGGER AT 1/2 PRICE AS PER PRODUCT SERVICE  
 NO OTHER FAULTS FOUND  
 DATE OF MFG: 04-73

 1 0020345 TRIGGER ASSEMBLY  
 9900005 TEST  
 WE ARE OFFERING TRIGGER ASSEMBLY AT 1/2 NORMAL COST,  
 AS GESTURE OF GOOD-WILL -  
 PW/HAK

 24.0  
 5.0

ALL PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS

 TOTAL REPAIR CHARGE  
 TAXES

29.0

☐ PLEASE RETURN REMITTANCE  
 WITH THIS COPY OR SHIPMENT  
 WILL BE MADE C.O.D.

 NOTE: IF YOU DESIRE ANY CHANGE USE THE  
 REVERSE SIDE FOR YOUR COMMENTS  
 AND MARK THIS BLOCK.

 INSURANCE  
 PARCEL POST

2.0

 PLEASE CIRCLE ONE  
 CARD  
 VISA/MC NO.

 EXP.  
 DATE

 DAYTIME  
 PHONE NO.

 TOTAL  
 CHARGES

34.0

THIS IS AN ESTIMATE TO REPAIR OR RECONDITION THE ITEMS LISTED  
 ABOVE. IF SATISFACTORY, PLEASE SIGN AND RETURN THIS COPY  
 TO:  
 REMINGTON ARMS COMPANY, INC.  
 ILION, NEW YORK 13357

QUOTATION COPY

CUSTOMER'S SIGNATURE

**BARBER - Kinzer PPS GAL RE0000337**

PDS 00220